Word Code

```
START PROGRAM
SET feed time TO "08:00"
SET bowl empty limit TO 10 grams
SET max retries TO 3
REPEAT FOREVER:
  current time = CHECK CLOCK
  IF current_time == feed_time:
    hopper level = MEASURE HOPPER
    IF hopper_level is EMPTY:
      SOUND BUZZER
      SEND ALERT "Hopper Empty"
      CONTINUE TO NEXT LOOP
    END IF
    SET try number TO 1
    WHILE try_number ≤ max_retries:
      SPIN MOTOR for 2 seconds
      WAIT 5 seconds
      bowl_weight = MEASURE BOWL
      IF bowl weight ≥ bowl empty limit:
        SEND ALERT "Feeding Successful"
        BREAK LOOP
      ELSE:
        INCREASE try number BY 1
      END IF
    END WHILE
    IF try_number > max_retries:
      SOUND BUZZER
      SEND ALERT "Dispense Jam"
```