
Mean axial/equatorial TM–O ratio
Ti
Mn
Fe
Co
Ni
1.0
1.1
1.2
0
0.25
0.5
0.75
1
x in $Na_xTM1_{0.5}TM2_{0.5}O_2$
Ti–O
Mn–O
Fe–O
Co–O
Ni–O
ratio = 1 (ideal octahedron)
O3 stable
P3 stable
O1 stable