

fujimak

FPC011

Maintenance Report

Operation Date: Sat 27/04/2024

Client	Yakiniku	Start Time	3:20 PM
PIC	Eduard Li Araquel	Finish Time	4:40 PM
Location	MOA	FOR: ☐ Warranty ☒ Billing	If For Billing:
Equipment	Meat Sink Faucet		
Brand	Franklin		
Model/Serial	N/A		

Concern: Loose trade faucet



Action Taken:
Replace Faucet Assembly at Meat Sink.
Testing and Observe. Turnover to MOD. Unit Operational

Recommendation:

#	Comments				
1	Power suply, voltage	NA	6	Wiring,Piping	NA
2	Amps	NA	7	Fire condition	NA
3	Filter, Condenser	NA	8	Gas Leak	NA
4	Compressor	NA	9	Sound	NA
5	Refrigeration leak	NA	10	Screw, Bolt	NA

Ranking	Rank
A: Unit Operational	A
B: For Replacement part(s)	Conditions
C: For Observation	O:Perfect Condition
D: For pull out-shop evaluation and repair	Δ:Not Good Condition (Need replace parts maintenance)
E. For Unit Replacement	*:DANGEROUS STOP TO USING

	Edward Li Araquel Technician
	Helbert Dedal Supervisor



Status(F) 1:Completed


Client Ariel Ellorda




Remarks1




Remarks6




Remarks2




Remarks7




Remarks3




Remarks8




Remarks4



Remarks9



Remarks5



Remark10

