e: XBee Disconnect

a: Status LED off

CONNECTED

IDLE

e: IR Rcv

a: XBee Ack

e: XBee Connect

a: Status LED on

e: XBee Reset

PENDING

e: XBee Verify

a: Blink Faster

e: XBee Verify Others

a: Blink Slower

VERIFY