## External Interface Board Test Results for EIB S/N: 0078

**Overall Test Status: Passed!** 

Technician: David Toner, Life #: 26565

Test performed: 04/13/25, 09:15 AM

## PSC I/O and MPS 5069 PLC I/O Test Results

## **Visual LED Status Test: Passed!**

| I/O Port     | Voltage  | Pass/Fail |
|--------------|----------|-----------|
| OUT1-PSC OFF | 5.084 V  | Pass      |
| OUT1-PSC ON  | 0.033 V  | Pass      |
| OUT2-PSC OFF | 5.079 V  | Pass      |
| OUT2-PSC ON  | 0.032 V  | Pass      |
| OUT3-PSC OFF | 5.067 V  | Pass      |
| OUT3-PSC ON  | 0.033 V  | Pass      |
| OUT4-PSC OFF | 5.032 V  | Pass      |
| OUT4-PSC ON  | 0.032 V  | Pass      |
| IN1-PSC OFF  | 0.0 V    | Pass      |
| IN1-PSC ON   | 19.805 V | Pass      |
| IN2-PSC OFF  | 0.0 V    | Pass      |
| IN2-PSC ON   | 19.9 V   | Pass      |
| IN3-PSC OFF  | -0.0 V   | Pass      |
| IN3-PSC ON   | 19.708 V | Pass      |
| IN4-PSC OFF  | -0.0 V   | Pass      |
| IN4-PSC ON   | 19.679 V | Pass      |
| 24V_PS       | 24.235 V | Pass      |