Notes:

1. [CRITICAL PRIORITY] Add black as a color option in input section
2. [CRITICAL PRIORITY] AWG needs to be visible for all conductors. For simplicity, remove A/B designators; only signal names should be shown on the harness left, and corresponding AWG values shown on the right.

3. [CRITICAL UPDATE] As conductor count grows, the harness routing view table also needs to expand, and it needs to format
correctly.