Hilda & Luna Beadworks

Quality Control Manual

Inspection criteria and sampling procedures for beads, charms, and findings

[Sample data]: *Fictional sample content generated for RAG (retrieval-augmented generation) testing purposes.*

---

1. Purpose

This manual defines the inspection criteria, sampling rates, and rejection thresholds used by the Quality Lead and production staff before any beads or charms are approved for packing and shipment.

2. Inspection Stages

Stage	When performed	Inspector
In-process check	Every 50 pieces during production	Line operator
Batch review	End of each production run	Quality Lead
Pre-pack audit	Before packing into retail/wholesale units	Packing supervisor
Outbound spot check	Random, 1 in 20 outbound orders	Shipping Lead

3. Glass Bead Defect Categories

3.1 Critical defects (automatic rejection)

- Sharp or unfinished hole edges
- Visible cracks or internal fractures
- Hole diameter outside tolerance (bead will not accept 0.3mm wire)

3.2 Major defects (reject if more than 2 per 100-piece sample)

- Color variation beyond Delta-E 2.0 from the approved standard
- Asymmetric or lopsided bead shape
- Trapped air bubbles larger than 1mm

3.3 Minor defects (acceptable if under 5 per 100-piece sample)

- Slight surface texture variation
- Minor size variation within ±0.3mm

4. Charm & Finding Defect Categories

- Critical: incomplete casting, missing bail/loop, plating that flakes under light scratch test
- Major: visible mold seam lines, uneven plating color
- Minor: very light surface marks not visible at arm's length

5. Sampling Plan

Batch size	Sample size	Accept if defects ≤	Reject if defects ≥
Up to 500 pieces	32 pieces	1	2
501–1,200 pieces	50 pieces	2	3
1,201–3,200 pieces	80 pieces	3	4

6. Rejected Batch Handling

Rejected batches are tagged with a red Quality Hold card and moved to the Hold Shelf in the Production Workshop. The Quality Lead determines whether the batch is reworked, downgraded to the 'Seconds' bin, or scrapped, within 2 business days.

7. Documentation

Every batch review is logged in the Quality Register with: batch ID, production date, operator, sample size, defects found, and disposition decision. Records are retained for 24 months.