

s_rx_state

ST_RX_IDLE

rxf_n_i = '0'

ST_RX_PRE

ST_RX_PRE2

ST_RX_OE

ST_RX_OE2

ST_RD0

ST_RD1

adbus_i = c_CMD_SYNC

ST_RD2

ST_RD3

ST_RD4

s_is_i2c = '1'

ST_RD5

ST_RD6

not (s_is_i2c = '1')

not (adbus_i = c_CMD_SYNC)

s_abort = '1'

ST_RX_RELEASE

ST_RX_RELEASE2

not (s_abort = '1')

ST_RX_EXEC

