Residential Treatment Facility
Inspection Report

Department of Health
P.O. Box 47874, Olympia, WA 98504-7874
TEL: 360-236-4732

November 23, 2021

Agency Name and Address	Administrator
Alliance Evaluation and Treatment Facility, 982 E Columbia Ave Ste 201, Colville, WA. 99114-3316	David M Nielsen PhD

Inspection Type	Inspection Onsite Dates	Inspector
ONGOING - ROUTINE	11/16/2021	RXE03

Inspection Number	License Number	RTF Services Types
X2021-738	RTF.FS.60756070	Mental Health Services, ,

Please note that the deficiencies/violations/observations noted in this report are not all-inclusive, but rather were deficiencies/violations/observations that were observed or discovered during the on-site inspection.

Deficiency Number and Rule Reference	Observation Findings	Plan of Correction
2340 Water supply, sewage and waste disposal WAC 246-337-130(2) The licensee shall ensure:(2) Tempered water between one hundred and one hundred twenty degrees Fahrenheit in resident areas.	Based on observation and interview, the facility failed to provide tempered water between one hundred and one hundred twenty degrees Fahrenheit. Failure to provide proper water temperatures for handwashing may result in disease transmission for staff and residents. Findings included: 1. Observation on 11/16/2021 at 10:56 AM showed the following: a. Kitchen Handwashing sink #1-125 degrees F (Fahrenheit) b. Kitchen Handwashing sink #2-124 degrees F (Fahrenheit) c. Kitchen Handwashing sink #3-125 degrees F (Fahrenheit)	

	2. Interview on 11/16/2021 at 11:02 AM, Staff A, Facility Administrator, stated that they acknowledged the temperature was not within the range of one hundred and one hundred twenty degrees Fahrenheit.	
U2955 Design, Construct, Install Backflow Air Gap WAC 246-215-05215 An air gap between the water supply inlet and the flood level rim of the PLUMBING FIXTURE, EQUIPMENT, or nonFOOD EQUIPMENT must be at least twice the diameter of the water supply inlet and may not be less than one inch (25 mm).	Based on observation, the facility failed to provide the proper air gap between the water supply and the flood level rim of the plumbing fixture, equipment, or nonfood equipment. Failure to provide the proper air gap can lead to accidental backflow and can cause serious health risks and/or contamination. Findings included: 1. Observation on 11/16/2021 at 11:25 AM showed the washing sink waste/discharge pipe did not have the proper air gap of at least twice the diameter of the pipe, as the indirect waste/discharge pipe was also observed to be below the rim of the floor sink and/or floor drain. 2. Interview on 11/16/2021 at 11:26 AM, Staff A, Facility Administrator, stated that they acknowledged that the indirect waste pipe was observed to be below the rim of the floor sinks and floor drains in the kitchen.	
U3680 Handwashing Facilities Handwashing Signage WAC 246-215-06320 A sign or poster that notifies FOOD EMPLOYEES to wash their hands must be provided at all HANDWASHING SINKS used by FOOD EMPLOYEES and must be clearly visible to FOOD EMPLOYEES.	Based on observation and interview, the facility failed to provide signage that notified food employees to wash their hands and be visible to food employees. Failure to provide handwashing signage may result in cross-contamination and/or pathogenic/foodborne illness transmission. Findings included: 1. Observation on 11/16/2021 at 10:55 AM showed that the facility could not locate any sign or poster near the	

	handwashing sink in the foodservice dining areas notifying employees to wash their hands. 2. Interview on 11/16/2021 at 10:56 AM, Staff A, Facility Administrator, stated that acknowledged there was no handwashing signage near handwashing sinks in the kitchen.	

Northeast Washington Alliance Counseling Services
165 E. Hawthorne Avenue
Colville, WA 99114

Corrective Action Plan

December 3, 2021

Alliance Evaluation & treatment Facility, 982 E. Columbia Ave, Ste 201, Colville, WA 99114-3316 Agency Name and Address		David M. Nielsen, Ph.D. Administrator
ONGOING-ROUTINE Inspection Type	11/16/2021 Inspection Onsite Dates	RXE03 Inspector
X2021-738 Inspection Number	RTF.FS.60756070 License Number	Mental Health Services RTF Services Types

Regulation Number	How the Deficiency Will Be Corrected	Responsible Individual(s)	Estimated Date of Correction	Monitoring/ Action Level Indicating Need for Change of POC
WAC 246-337-130(2)	Water at hand wash sinks was high (above 120F) as a result of a programming issue on the building automation system. This allowed too wide a band for the loop. The target temperature was lowered, and the bandwidth narrowed to prevent loop temp spikes above 120F at the hand washing sinks.	Eric Rodgers, Manager Facilities Services	12/01/21	Facilities engineering will continue to monitor domestic hot water loop and adjust as necessary.
WAC 246-215-05215	Adjustments have been made to the air gap to ensure at least twice the diameter of the water supply inlets and not less than one inch for each drain.	Eric Rodgers, Manager Facilities Services	12/01/21	No further action should be needed; one time fix.
WAC 246-215-06320	Approved Hand washing signs have been placed in clearly visible location near the handwashing sinks in the food services dining areas.	Peggy Doyle, Manager FANS Tasha Anisimov, IP	11/17/21	IP will add visual and inspection of the signs in the food services dining areas to quarterly department rounding.

STATE OF WASHINGTON
DEPARTMENT OF HEALTH
PO Box 47874 • Olympia, Washington 98504-7874

December 13, 2021

David Neilsen
Administrator
Alliance Evaluation & Treatment Facility
982 E Columbia Ave, Ste., 201
Colville, WA 99114

Subject: Inspection Number x2021-738

Dear Mr. Nielsen:

The Washington State Department of Health conducted an inspection at Alliance Evaluation & Treatment Facility - 982 E Columbia Ave, Ste., 201- Colville, WA 99114

Your inspection was conducted on November 23, 2021. The Plan of Correction that was submitted on December 7, 2021 was approved on December 13, 2021. No further action is required.

I sincerely appreciate your cooperation and hard work during the inspection process and look forward to working with you again in the future.

Sincerely,

Rosa Elvia, SUDP
Behavioral Health Reviewer