REVISION BLOCK				APPROVED	
ECO NO.	REV	DESCRIPTION	DATE	HW ENG	NPIE
EA587783	A0	INITIAL RELEASE PER ECO NO.	03/15/21	T.N.	J.D.

NOTES: UNLESS OTHERWISE SPECIFIED

1. ASSEMBLY WORKMANSHIP TO MEET OR EXCEED LATEST REVISION OF IPC-A-610 CLASS 2.
2. AREA ARRAY PACKAGE SOLDER JOINT VOIDS TO MEET OR EXCEED LATEST REVISION OF IPC-7095, CLASS 2.
3. THIS ASSEMBLY DRAWING SHOWS ALL COMPONENT LOCATIONS FOR ALL BOARD STUFF OPTIONS. REFER TO SPECIFIC BILL OF MATERIALS FOR COMPONENTS USED AND SCHEMATIC.
4. REFER TO MANUFACTURING ASSEMBLY PROCEDURES (MAPs) LISTED ON THE BILL OF MATERIALS.
5. SQUARE PADS INDICATE PIN NUMBER 1 THRU HOLE COMPONENTS. POSITIVE TERMINALS OF POLORIZED CAPACITORS, CATHODES OF DIODES AND EMITTERS OF TRANSISTORS.
6. TRIM ALL THRU HOLE COMPONENT LEADS TO .085" MAXIMUM LENGTH FROM THE LEAD PROTRUSION SIDE OF THE PCB.
7. AFFIX SERIAL NUMBER LABEL IN DESIGNATED AREA AS SHOWN.
8. MARK BILL OF MATERIALS ASSEMBLY NUMBER AND REVISION IN AREA SHOWN. REFER TO CISCO PART NUMBER LABEL SPECIFICATION 95-9135-01. DO NOT USE THE PART NUMBER AND REVISION FROM THIS DRAWING.
9. DESIGNATED AREA FOR INSPECTION AND TEST STAMPS.
10. ALL SCREWS SHALL BE TIGHTENED PER SPECIFICATION: TORQUE STANDARD FOR MECHANICAL ASSEMBLY INCH AND METRIC SCREW THREAD FASTENERS 95-5874-01.



PRIMARY SIDE

UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES.
TOLERANCES:
.XX +/- 0.01
.XXX +/- 0.005
ANGLES: +/- 5°

MATERIAL: N/A

FINISH: N/A

THIRD ANGLE PROJECTION

APPROVALS	DATE
ECAD:LFERRARO	03/15/21
EENG:TKNGO	03/15/21
NPIE:JODASILV	03/15/21

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134
U.S.A.

TITLE PCADWG
NG MODULAR LC
LC4-DB

SIZE E | DWG NO. 60-103676-05 | REV A0

SCALE : NONE | SHEET 1 OF 2

SECONDARY SIDE



SIZE	DWG NO.	REV
E	60-103676-05	A0
SCALE : NONE		SHEET 2 OF 2