

## **IMPORTANT NOTICE**

Please make the following changes in your Technical Manual.

Page 110 — Left column, under "Resistors — Control."

ADD:

R1424

6-474-12 470 kΩ resistor


## **Schematics**

Part 4 of 4 — Cut out the new X-Ray view of the Motion Circuit Board below and tape it over the old one.

 Remove the attached Schematic of the Motion Circuit Board and tape it over the old Schematic.


Thank you,

**HEATH COMPANY** 



X-RAY VIEW OF THE MOTION CIRCUIT BOARD\*

Page 1 of 2 ETW-18 & EB-1801-30/595-2872-01 591-4238



SCHEMATIC OF THE MOTION CIRCUIT BOARD

Page 2 of 2 ETW-18 & EB-1801-30/595-2872-01 591-4238