BOM Maker's Friend MF05 3D-Printer, UniProKit UPKlib V2.06

| Partname | PartNo. | pcs. | Description | Pos | Supplier |
|-------------------|----------|------|---------------------------------------------------|-----|----------|
| | | | | | |
| UPKlib | | | | | |
| tslot4 | 17092201 | 1 | T-Slot Nut 6, 40x20x20mm, framepart for tensioner | 1 | ML |
| tslot6 | 17092202 | 3 | T-Slot Nut 6, 60x20x20mm, distance holder | 2 | |
| tslot48 | 17092209 | 5 | T-Slot Nut 6, 480x20x20mm, distancer | 3 | |
| tslot8con | 17092220 | 2 | T-Slot Con, 480x20x20mm | 4 | |
| tslot40con_16 | | 4 | Framepart y-direction | 5 | |
| tslot48con_double | | 3 | Framepart x-direction | 6 | |
| m6x8 | 17092303 | 128 | 8mm, M6 ISO 7380, display- and spool-holder | 7 | |
| m6x12 | 17092304 | 62 | 12mm, M6 ISO 7380, mount holder | 8 | |
| m6x16 | 17092305 | 9 | 16mm, M6 ISO 7380, mount foot to frame | 9 | |
| m6x20 | 17092306 | 10 | 20mm, M6 ISO 7380, mount tslot6 | 10 | |
| m6x25cyl | 17092307 | 16 | 25mm, M6 DIN 7984, connect z-frame with y-base | 11 | |
| m6nutplate | 17092309 | 205 | für TSlot, Slot6, M6 | 12 | |
| m6washer | 17092310 | 42 | 6.4x12x1.6, DIN 125, display- and spool-holder | 13 | |
| m6nut | 17092308 | 4 | 5.6x10mm, M6 DIN934, mount z-floating-bearing | 14 | |
| m2x10 | | 2 | screws for mout limitswitch to holder | 15 | |
| m2.5x12ws | | 4 | M2.5 x 12 woodscrew | 16 | |
| m3x6 | | 17 | mount stepper | 17 | |
| m3x6cone | | 2 | mount mainboard on holder | 18 | |
| m3x8cyl | 21032807 | 20 | mount adapter on mgn12 | 19 | |
| m3x10cyl | 19070615 | 12 | mount stepper to holder | 20 | |
| m3x20cyl | 19082011 | 2 | pole for belt | 21 | |
| hammermutter m3 | 21032803 | 16 | | 22 | |

| m4x6lockscrew | | 10 | for coupling-5-8 | 23 |
|--------------------------|----------|----|----------------------------------------------------------|----|
| m4x6 | | 3 | screws for electronics-holder | 24 |
| m4x8 | | 4 | screws for mount z-switchholder to tslot | 25 |
| m4x10cyl | 21090302 | 16 | mount Sc8uu-Adapter | 26 |
| M4x12cyl | 19082012 | 2 | for extruder mounting | 27 |
| n4x14cyl | | 4 | screw for sk8 | 28 |
| M4x30cyl | 19082013 | 2 | for extruder mounting | 29 |
| n4x30cone | | 4 | mount heatbed | 30 |
| M4nut | 19070613 | 4 | for extruder mounting | 31 |
| nammermutter-m4 | 21091602 | 7 | hammer-nut for m4x6 | 32 |
| m6x40cyl | 19082015 | 2 | mount belt on carriage | 33 |
| angle8 | 17092226 | 2 | mount z-top-holder | 34 |
| latplate6 | 17092236 | 2 | connect distancer to frame | 35 |
| latplate8 | 17092237 | 6 | connect tslots | 36 |
| latplate24 | 17092240 | 3 | carriage parts | 37 |
| con | 17092301 | 2 | stabilizes frame | 38 |
| a-connector | 17092313 | 10 | mount z-frame | 39 |
| endcap1e | 17092315 | 18 | endcap | 40 |
| cablehose | | 1 | hose for collecting/binding cables, 300 cm, for 48 75 90 | 41 |
| cablebinder10 | | 24 | cablebinder 10x10, 6x15, 6x20cm | 42 |
| adjustring8mm | 21031001 | 2 | blocks z-shaft top | 43 |
| nema17-40con | 19070622 | 5 | z-stepper-motors | 44 |
| Shaft8x490 | | 2 | z-shaft for lm8uu | 45 |
| shaft8x480 | 19082003 | 2 | slider axis | 46 |
| oupling-5-8 | 19082007 | 2 | couples stepper 5 with thread 8 | 47 |
| Frapezoidal_thread_480 | 19082006 | 2 | z-thread | 48 |
| t2-6-belt | 19070616 | 2 | y-belt, 90cm | 49 |
| Gt2-20-6-m5-pulley | 19070617 | 2 | pulley, 20 teeth, 5mm, gt2-6-belt | 50 |
| sk8 | 19082008 | 4 | holder for shaft | 51 |
| sc8uu | 19082002 | 4 | lm8uu block | 52 |
| | 19082206 | 8 | linear bearing | 53 |
| Sc8uu-adapter2g | 21090301 | 4 | SC8UU Adapter | 54 |
| Im8uu Sc8uu-adapter2g | 19082206 | 8 | linear bearing | 53 |

| trapezoidal_nut 1 | 9082005 | 2 | drive nut | 55 |
|---------------------------------------------|-------------|----|-----------------------------------------|----|
| mgn12h-rail-400 | | 1 | Rail, mgn12, 400 mmm | 56 |
| mgn12h-block 2 | 1032804 | 1 | Block, mgn12 | 57 |
| | | | | |
| Accessoriess | | | | |
| PLA-Sample | | 1 | Stück Filament zum testen | 58 |
| LCD-Display | | 1 | LCD-Display im Metall-Gehäuse | 59 |
| Cable_220v | | 1 | 230V-AC Netzkabel | 60 |
| spool-holder | | 1 | Filament Spooler | 61 |
| display-holder | | 1 | Holder for LCD-Display | 62 |
| LCD-Display and Spool Holder and plugin cab | le 220v for | ps | | |
| ultrabase310 | | 1 | Creality Ultrabase glasplate, 310x310mm | 63 |
| heatbed-clips-small | | 4 | Clips for mounting glasplate on heatbed | 64 |
| glasplate300 | | 1 | glasplate 300x300mm | 65 |
| electronics-box | | | | |
| electronics-cover | | 1 | housing for mainboard | 66 |
| Display-cables | | | | |
| display-10pol | | 2 | Pfostensteckerkabel f. LCD-Display | 67 |
| Z-cables | | | | |
| z-motor-4pol | | 2 | cable for Z1 and Z2 stepper motor | 68 |
| z-switch-2pol | | 1 | cable for Z-switch | 69 |
| X-cables | | | | |
| x-motor-4pol | | 1 | cable for X stepper motor | 70 |
| x-switch-2pol | | 1 | cable for X-switch | 71 |
| Y-cables | | | | |
| y-motor-4pol | | 1 | cable for X stepper motor | 72 |
| y-switch-2pol | | 1 | cable for X-switch | 73 |
| Extruder-cables | | | | |
| fan-cable | | 2 | cable for Fan1 and Fan2 | 74 |
| | • | | | · |

| e-motor-4pol | | 1 | cable for extruder stepper motor | 75 |
|---------------------|----------|---|--------------------------------------|----------|
| e-thermistor-2pol | | 1 | cable for nozzle temp-sensor | 76 |
| e-nozzle-2pol | | 1 | cable for nozzle heater cartridge | 77 |
| Heatbed-cables | | | | |
| h-6pol | | 1 | cable for h-power and h-tempsensor | 78 |
| Connect Powersupply | | | | |
| ps24V15A | 21091601 | 1 | PowerSupply 24V 15 A | 79 |
| ac-plugswitch | | 1 | Mainswitch and Main-AC-Power-Plug | 80 |
| ps-cables | | | | |
| ps-mainboard-2pol | | 1 | Powersupply to mainboard | 81 |
| Switches | | | | |
| limitswitch-2pol | | 3 | Simple limitswitches for x, y, z | 82 |
| z-switchholder | | 1 | Holder for z-limitswitch | 83 |
| y-switchholder | | 1 | Holder for y-limitswitch | 84 |
| Mainboard | | | | |
| anetboard1.7 | | 1 | mainboard, 24V | 85 |
| electronics-holder | | 1 | mountplate for mainboard | 86 |
| Powersupply-holder | | | | |
| powersuplly-holder | | 1 | holder for powersupply (modifiziert) | 87 |
| z-axis | | | | |
| z-floating-bearing | | 2 | z-top holder | 88 |
| x-axis | | | | |
| ganze_x_achse_quer | | 1 | muss noch ausgearbeitet werden | 89 |
| z-steppermotor | | | | |
| z-bottom-left | | 1 | left z-bottom-holder | 90 91 |
| z-bottom-right | | | right z-bottom-holder | |

| Heatbed | | | |
|--------------------|---|-----------------------------------------------|-----|
| heatbed300_276_209 | 1 | 300mm with hole-edge-distances 12 and 45.5 mm | 92 |
| bedlevel-knob | 4 | adjust heatbed | 93 |
| spring_8x25 | 4 | distance-spring for heatbed | 94 |
| bedmount1d_left | 2 | bedmount left | 95 |
| bedmount1d_right | 2 | bedmount right | 96 |
| y-belt | | | |
| belt-tensioner | 1 | belt-tensioner (assembly) | 97 |
| y-steppermotor | | | |
| nema17holder6mm | 1 | stepper holder, 6mm | 98 |
| machine-feet | | | |
| foot-35x24 | 4 | machine-foot, h 24 dia 35 depth 13 | 99 |
| foot-38x25 | 0 | machine-foot, h 25 dia 38 depth 12 | |
| Extruder | | | |
| extruder_adapter | 1 | extruder adapter to mount on mgn12 | 100 |
| Mount idler | | | |
| mf_idler | 1 | x-idler, z-carriage-right | 101 |
| belt-tensioner | 1 | belt-tensioner (complete) | 102 |
| Mount stepper | | | |
| mf_steppermount | 1 | x-stepper, z-carriage-left | 103 |

804