H12-211.exam.125q

Number: H12-211 Passing Score: 800 Time Limit: 120 min



H12-211

Huawei Certified Network Associate- Huawei Networking Technology and Device

Exam A

QUESTION 1

The network administrator wants to improve the performance of network transmission, what steps can the administrator take? (Choose two)



- A. Change the work mode to full duplex of each end station.
- B. Link the end stations together using a switch.
- C. Change the work mode to half duplex of each end station.
- D. Link the end stations together using a hub.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 2

On Huawei switch, which of the following commands can be used to set port duplex mode as "auto negotiation"? (Choose two)

- A. duplex negotiation auto
- B. duplex auto-negotiation
- C. duplex auto
- D. undo duplex

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 3

The network administrator wishes to transmit data between two end stations. The network interface cards of both devices operates at 100Mbps however one supports half duplex while the other uses full duplex mode.

What will occur as a result?

- A. The end stations cannot communicate.
- B. The end stations can communicate, but data may be lost during transmission of large amounts of traffic.
- C. The end stations will operate normally
- D. The end stations can communicate, but speed is different during transmission of large amounts of traffic.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 4

An Ethernet port can work one of three duplex modes, whereas an Optical Ethernet port only supports one single mode.

Which of the following represents this mode?

- A. Full-duplex
- B. Half-duplex
- C. Auto-negotiation
- D. Simplex

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 5

While inspecting packets in the network, a network administrator discovers a frame with the destination MAC address of 01-00-5E-A0-B1-C3.

What can the administrator determine from this?

- A. The MAC address is a unicast address.
- B. The MAC address is a broadcast address
- C. The MAC address is a multicast address.
- D. The MAC address is incorrect.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 6

According to OSI reference model, which layer is responsible for end to end error checking and flow control?

- A. Physical layer
- B. Data link layer
- C. Network layer
- D. Transport layer

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 7

Which of the following mechanisms are used for flow control? (Choose three)

- A. Acknowledgement
- B. Buffering
- C. Source quench messages
- D. Windowing

Correct Answer: BCD

Section: (none) Explanation

QUESTION 8

Source Destination Protocol Info 10.0.12.1 10.0.12.2 TCP 50190 > telnet [SYN] Seq=0 Win=8192 Len=0 MSS=1460 10.0.12.2 10.0.12.1 TCP telnet> 50190 [SYN, ACK] Seq=0 Ack=1 Win=8192 Len=0 MSS=1460 10.0.12.1 10.0.12.2 TCP 50190 > telnet [ACK] Seq=1 Ack=1 Win=8192 Len=0

Refer to the capture output. The administrator has captured three packets in the network. Which statement regarding the captured packets is incorrect?

- A. This packets represent a TCP three-way handshake process.
- B. 10.0.12.1 is the telnet server, while 10.0.12.2 is the telnet client.
- C. The three packets contain no application data.
- D. 10.0.12.1 uses port 50190 to buid the telnet connection.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 9

An Ethernet frame is captured by network protocol analyzer tool and the value of Type/Length field is 0x0800.

Which of the following statements about the frame are correct? (Choose two)

- A. The frame structure of the frame is $Ethernet_II$
- B. The frame structure of the frame is 802.3
- C. Its upper layer protocol is IP
- D. Its upper layer protocol is IPX

Correct Answer: AC Section: (none) Explanation

QUESTION 10

Which of the following descriptions regarding the TTL field of the IP packet is correct?

- A. The TTL defines how many packets the source can send.
- B. The TTL defines the duration during which the source can send packets.
- C. The TTL value will decrement by 1 each time the packet is routed.
- D. The TTL value will increment by 1 each time the packet is routed.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 11

Which of the following statements are correct about TTL field in IP packet? (Choose two)

<choice ident="A">
<choice ident="B">
<choice ident="C">
<choice ident="D">



https://www.gratisexam.com/

- A. The maximum value of TTL is 65535.
- B. Normally, it's impossible for a router to receive a packet whose TTL is zero.
- C. The main purpose of TTL is to prevent IP packets from circulating endlessly in a network which can consume a lot of bandwidth.
- D. TTL value will be decremented as a packet is passed through the network devices such as hub, LAN switch and router.

Correct Answer: BC
Section: (none)
Explanation

QUESTION 12

In the case of Huawei router, what is the "-i" parameter in a Ping command issued on a VRP operating system used to set?

- A. Interface for sending an Echo Request packet
- B. Source IP address for sending an Echo Request packet
- C. Interface for receiving an Echo Reply packet
- D. Destination IP address for receiving an Echo Reply packet

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 13

To provide the information about the IP addresses that a user packet traverses along the path to the destination, which of the following does Tracert record in each expired ICMP TTL packet?

- A. Destination port
- B. Source port
- C. Destination address
- D. Source address

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 14

A network administrator recently used tracert to trace the path to the destination IP address of an external website, however the trace path displayed only a timeout result.

Which of the following statements correctly explains the reason for this? (Choose two)

- A. The source router had shutdown the ICMP function.
- B. This destination IP address does not exist.
- C. The gateway cannot find a route to the destination.
- D. This is a normal phenomenon.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 15

Ping 10.0.0.2: 56 data bytes, press CTRL_C to break
Reply from 10.0.0.2: bytes=800 Sequence=1 ttl=255 time=2 ms
Reply from 10.0.0.2: bytes=800 Sequence=2 ttl=255 time=10 ms
--- 10.0.0.2 ping statistics --2 packet(s) transmitted
2 packet(s) received
0.00% packet loss
round-trip min/avg/max = 2/6/10 ms

A network administrator uses the ping command to test connectivity to the destination 10.0.0.2 on a Huawei AR series router.

Which statement regarding the output is correct?

- A. The network administrator used the command ping -c 2 -s 800 10.0.0.2
- B. The network administrator used the command ping -a 2 -v 800 10.0.0.2
- C. The path between the source and destination is not OK.
- D. The network administrator changed the default TTL value.

Correct Answer: A

Section: (none) Explanation

Explanation/Reference:

QUESTION 16

Which of the following statements explains the behavior of the ICMP redirect function? (Choose two)

- A. When a router receives data on the interface via which the same data needs to be forwarded, and the source is on the same segment as the next hop, an ICMP redirect message will be sent by the router to the source.
- B. When a router receives data on an interface, and the router's IP address matches the destination IP of the data, an ICMP redirect message will be sent by the router to the source.
- C. When a router receives data on the interface via which the same data needs to be forwarded, and the source is on the same segment as the next hop, an ICMP Redirect message will be sent by the source to the router.
- D. When a router receives data on the interface via which the same data needs to be forwarded, and the source is on a different segment from the next hop, an ICMP redirect message will be sent by the router to the source

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 17

Host A wishes to send data to host C, and generates an ARP request to obtain the destination MAC address.

Which statement is true?

- A. The destination IP address of the ARP request is Host C.
- B. The destination MAC address of this ARP request is Host C.
- C. The destination IP address for the ARP request is a broadcast IP address.
- D. The destination MAC address of this frame is the MAC address of G0/0/0 on RTA.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 18

An ARP request is sent by host A to obtain the destination MAC address of host D.

Which statement is true about regarding the ARP reply?

- A. The destination MAC address of this frame is the MAC address of Switch A.
- B. The destination IP address of this packet is the VLANIF1 IP address of Switch A.
- C. The destination MAC address of this frame is the MAC address of Host A.
- D. The destination IP address of this packet is a broadcast IP address.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 19

Which of the following statements about gratuitous ARP packets are true? (Choose two)

- A. A system can determine whether conflicting IP addresses are used by sending a gratuitous ARP packet
- B. A gratuitous ARP packet uses the same format as an ARP request packet.



- C. A gratuitous ARP packet can help to update an IP address.
- D. A gratuitous ARP packet uses the same format as an ARP reply packet.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 20

UDP is connectionless oriented, which of the following must be used in order to ensure reliability?

- A. Internet Protocol
- B. Application Layer Protocol
- C. Network Layer Protocol
- D. Transmission Control Protocol

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 21

The administrator has configured an IP address for Host A and Host B, but had forgotten to configure a default gateway.

What effect will this have on the hosts?

- A. Neither host will be affected, and therefore will be able to communicate with the peer.
- B. Host A will be unable to connect to the router's G0/0/0 interface.
- C. Hosts will be unable to communicate unless arp-proxy is enabled on the router.
- D. The host will be unable to reach neither the local nor remote network destinations.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 22

A host has established a telnet connection with the router attached to interface G0/0/0.

Which of the following statements are correct? (Choose two)

- A. The destination address of a frame sent by the host will be the MAC address of the router interface.
- B. The destination address of a frame will be the MAC address of the switch interface.
- C. The destination port number in a segment header will have a value of 80.
- D. The destination IP address of a packet will be the IP address of the network interface of the router.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 23

The administrator uses the ping command on the host to test connectivity to the website www.huawei.com.

The command line shows a request time out. The administrator displays the ARP entries for the host.

Which entry will be found in the ARP cache table of the host?

- A. The MAC address of the destination www.huawei.com will exist in the ARP cache.
- B. The MAC address of the switch will exist in the ARP cache.
- C. The IP address of the destination www.huawei.com will exist in the ARP cache.
- D. The MAC address of router interface G0/0/0, will exist in the ARP cache.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 24

When R2 forwards data to R3 from R1, which of the following items will change? (Choose two)

- A. The source MAC address
- B. The destination MAC address
- C. The source IP address
- D. The destination IP address

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 25

If Host B also configured the IP address as "192.168.1.1/24", an IP address config will occur. What will happen as a result?

- A. Host B will send an ICMP request to the destination with the configured IP address. If a reply is received, the host will notify of an address conflict.
- B. Host A will send a gratuitous ARP request to resolve the MAC address of the destination 192.168.1.1, for which Host B will reply.
- C. Host B will send a gratuitous ARP request to resolve the MAC address of the destination 192.168.1.1, for which Host A will reply.
- D. Host A will ignore any received ARP request intended for destination 192.168.1.1.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 26

<quidway>display mac-address</quidway>	
MAC Address VLAN/VSI Learned-From Type	
5489-98ec-f018 1/- GE0/0/13 dynamic	
Total items displayed = 1	

Refer to the graphic. A switch attempts to forward a frame to the MAC destination 5489-98ec-f01. What operation will occur on the switch?

- A. The switch will send a request to obtain the MAC address of 5489-98ec-f011.
- B. The switch will report that the destination is unreachable and report this to the source.

- C. The switch will flood the frame via all ports, with exception of the port on which the frame was received.
- D. The switch will drop the frame because it does not have an entry in its MAC address table.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 27

Host A has been connected to switch A and configured with an IP address.

When Host A initially forwards a frame, what action will be taken by Switch A?

- A. Switch A will drop this frame.
- B. Switch A will attempt to flood the frame to all ports except for the G0/0/1 interface.
- C. Switch A will forward the frame via ports G0/0/1, G0/0/2 and G0/0/3.
- D. Switch will receive this frame before returning the frame to G0/0/1.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 28

A server is linked to port interface G0/0/1 of a switch. The administrator wishes to allow only this server to be linked to this interface on the switch.

Which method can be used to achieve this?

- A. Configure a static ARP entry using the server's IP address and MAC address in the switch.
- B. Configure a static MAC address binding entry of the server's MAC address and the interface in the switch.
- C. Configure the default gateway of the switch to be the same as the server's IP address.
- D. It is not possible to enable a single device to be associated with an interface.

Correct Answer: B Section: (none)

Explanation

Explanation/Reference:

QUESTION 29

An administrator connects two switches together in a local enterprise network. The ports of one switch support Fast Ethernet, while the ports of the other switch support Gigabit Ethernet. Hosts connected to one switch are able to communicate, however communication between the two switches fails.

What is the possible reason for this?

A. The ports have disabled auto-negotiation.



- B. One port is supporting auto-negotiation, while auto-negotiation is disabled on the port of the other switch.
- C. The port of one switch is operating using half duplex mode, while the port of the other switch is using full duplex mode.
- D. A Fast Ethernet port cannot communicate directly with a Gigabit Ethernet port.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 30

A layer 2 LAN switch generates CAM table entries according to the () of the received frame.

- A. Source MAC address
- B. Destination MAC address
- C. Source IP address
- D. Destination IP address

Correct Answer: A

Section: (none) Explanation

Explanation/Reference:

QUESTION 31

Which of the following statements about collision domains and broadcast domains are correct? (Choose three)

- A. Devices connected to the same hub form a collision domain
- B. Devices connected to the same hub form a broadcast domain
- C. Devices connected to the same bridge form a collision domain
- D. Devices connected to the same bridge form a broadcast domain
- E. Devices connected to the same router form a broadcast domain

Correct Answer: ABD Section: (none)
Explanation

Explanation/Reference:

QUESTION 32

Which of the following statements regarding layer-2 switch is incorrect?

- A. The switch learns MAC addresses automatically.
- B. The layer-3 header is modified before the received packet is transmitted.
- C. The layer-2 header is modified before the received packet is transmitted.
- D. The layer-2 LAN switch operates at data link layer.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 33

[R1]display interface GigabitEthernet0/0/0

GigabitEthernet0/0/0 current state: Administratively DOWN

Line protocol current state: DOWN

Refer to the display output. What can be determined based on the output of the display command?

- A. Interface Gigabit Ethernet 0/0/0 is connected to a wrong cable
- B. Interface Gigabit Ethernet 0/0/0 is not associated with an IP address
- C. Interface Gigabit Ethernet 0/0/0 is not associated with a dynamically defined route.
- D. Interface Gigabit Ethernet 0/0/0 has been manually shut down by an administrator.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 34

Which of the following statements regarding static and dynamic routing is incorrect?

- A. The static route can be easily configured and managed on the enterprise network.
- B. The use of dynamic routing is more convenient for the administrator to manage the network following network convergence.
- C. The static route can automatically recover when a link failure is encountered.
- D. Dynamic routing will use more resources than static routes.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 35

Which of the following are routed protocols? (Choose two)

- A. IP
- B. OSPF

- C. BGP
- D. IPX

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 36

Which of the following statements regarding the routing table are correct? (Choose two)

- A. The next hop in the routing table is redundant because the outgoing interface can be used for packet forwarding.
- B. The routes from generated by different protocols have different preferences.
- C. The metrics of different routing protocols are comparable.
- D. The metrics of different routing protocols are not comparable

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 37

Which of the following commands can be used to display the routing table on a Quidway router?

- A. display ip path
- B. display ip routing-table
- C. display interface
- D. display current-configuration

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 38

Which of the following entries is not included in the routing table?

- A. source address
- B. next hop
- C. destination address
- D. cost

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 39

Which of the following problems are caused by routing loops? (Choose three)

- A. Slow convergence
- B. Packets circulate between routers
- C. Router restarting
- D. Inconsistency of routing information

Correct Answer: ABD

Section: (none) Explanation

Explanation/Reference:

QUESTION 40

An administrator wishes to manage the router in the remote branch office, which method can be used?

- A. Telnet
- B. FTP
- C. Console Connection
- D. DHCP

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 41

The administrator cannot use telnet to manage the AR2200. The administrator is able to verify connectivity to the router and has been informed that other administrators have no difficulties using telnet.

Which statements describe the possible reasons for this problem? (Choose two)

- A. The user's status has been blocked
- B. The user's privilege level has been changed to 0.
- C. The user has been deleted.
- D. The telnet service in the AR2200 router has been disabled.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 42

A user logged into a VRP supported device through telnet, but when attempting to configure the device, found that he is unable to use the system-view command to enter the system-view.

What are the possible reasons for this? (Choose two)

- A. The device's VTY interface only provides permission for some telnet users to run the system-view command.
- B. The user's telnet software restricts use of this command.
- C. The user's privilege level is lower than the level associated with the system-view command.
- D. The system-view command privilege level is lower than the level associated with the user.

Correct Answer: AC Section: (none) Explanation

QUESTION 43

The users who log on the router through Telnet are not permitted to configure IP address.

What is the possible reason?

- A. Communication failures occur between the user and the router.
- B. The authentication mode of Telnet is set incorrectly.
- C. Privilege level of Telnet is set incorrectly.
- D. SNMP parameters are set incorrectly.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 44

Which of the following statements are correct? (Choose two)

- A. A single collision domain exists between RTA and SWC.
- B. A single broadcast domain exists between SWA and SWB.
- C. A single collision domain exists between SWA and SWC.
- D. A single broadcast domain exists between SWA and SWC.

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 45

On the interface serial 1/0/1 of RTA, the command "ip address unnumbered interface loopback 0" has been configured.

Which following statements are correct? (Choose two).

- A. The IP address of interface serial 1/0/1 is 10.1.1.1/24
- B. The IP address of interface serial 1/0/1 is 10.1.1.1/32
- C. The route entry 10.1.1.0/24 exists in RTA's routing-table
- D. The route entry 10.1.1.0/24 does not exist in RTA's routing-table

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 46

Refer to the graphic. The host has a problem establishing a telnet connection with the router attached to interface G0/0/0. Which of the following steps can be used to help the administrator identify the problem? (Choose two)

<choice ident="A">
<choice ident="B">
<choice ident="C">
<choice ident="D">

- A. Check whether the host has configured the gateway IP address.
- B. Check whether the switch has configured the gateway IP address.
- C. Use the ping tool to check connectivity between host and router.
- D. Check the telnet server configuration is right on the router.

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 47

Which of the following methods are supported by VRP platform to configure the router? (Choose three)

A. Through the Console port

- B. Through Telnet
- C. Through the AUX port
- D. Through FTP

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 48

The administrator wishes to update the configuration file of an AR2200 router using a USB cable.

How can this be achieved? (Choose two)

- A. The administrator should connect the USB cable between the terminal and the mini USB port of the AR2200 router.
- B. The administrator should connect the USB cable between the terminal and the USB port of the AR2200 router.
- C. The AR2200 router cannot support configuration updates through a USB cable.
- D. The administrator should install the mini USB drivers on the terminal after connecting the USB.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 49

The administrator wishes to manage a network through telnet from a user's terminal to a router.

How can this be achieved?

- A. A connection should be established between the ethernet port of the terminal and the console port of the router.
- B. A connection should be established between the ethernet port of the terminal and the ethernet port of the router.
- C. A connection should be established between the console port of the terminal and the ethernet port of the router.use console cable connect pc's ethernet port and router's console port.
- D. A connection should be established between the COM port of the terminal and the console port of the router.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 50

Whilst configuring a device, an administrator experiences trouble remembering certain commands.

Which of the following will help support the administrator? (Choose two)

A. TAB



B. question mark

C. ctrl+b

D. ctrl+c

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 51

<Huawei> system-view

[Huawei] user-interface console 0

[Huawei-ui-console0] user privilege level 15

[Huawei-ui-console0] authentication-mode password

[Huawei-ui-console0] set authentication password cipher huawei2012

[Huawei-ui-console0] quit

Refer to the configuration output. The administrator configured the device using the commands in the configuration output. Regarding these commands, which statement is false?

- A. The administrator wishes to enable management through the console interface.
- B. Following configuration, the administrator cannot manage the device remotely.
- C. A user that logs-in through the console interface is assigned the highest privilege level.
- D. The password of a user logged in through console is 'cipher huawei2012'.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 52

Which of the following is abbreviation of VRP?

- A. Versatile Routine Platform
- B. Virtual Routing Platform
- C. Virtual Routing Plane
- D. Versatile Routing Platform

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 53

<Huawei> system-view [Huawei]command-privilege level 3 view user save

Refer to the command output. What is the result of the shown command?

- A. The command adjusts the save command of a user to privilege level 3.
- B. The command adjusts the save command in the user view to privilege level 3.

- C. The command adjusts the user view command privilege level to 3, and saves the configuration.
- D. The command adjusts the privilege level of a user to 3, and saves the configuration.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 54

<Huawei>system-view [Huawei]history-command max-size 20

Refer to the command output. Which statements regarding the shown command are true? (Choose two)

- A. The command is used to adjust the size of the history command buffer.
- B. The default value of the history command buffer is 5.
- C. The command should be configured in the user-interface view.
- D. Once configured, commands totaling up to 20 bytes can be saved in the buffer.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 55

An AR2200 router is required to be reconfigured from scratch. Which steps are needed to achieve this? (Choose two)

- A. Reset the saved configuration.
- B. Clear the current configuration.
- C. Reboot the AR2200.
- D. Assign the configuration file to be used at next startup.

Correct Answer: AC Section: (none) Explanation

QUESTION 56

An administrator has been requested to replace the configuration file of a router in the network. The administrator has been instructed that after logging into the router, he must first permanently erase the current configuration file config.zip from the system.

Which command should he use to achieve this?

- A. delete /force config.zip
- B. delete /unreserved config.zip
- C. reset config.zip
- D. clear config.zip

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 57

Which of the following commands can switch a view from the system view to the user view?

- A. System-view
- B. Router
- C. Quit
- D. User-view

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 58

Which of the following storage devices are supported by Huawei router? (Select four)

- A. SDRAM
- B. NVRAM
- C. Flash
- D. Hard Disk
- E. CF Card

Correct Answer: ABCE

Section: (none) **Explanation**

Explanation/Reference:

QUESTION 59

Which of the following storage devices is used to store the startup configuration files in a router?

- <choice ident="A">
- <choice ident="B">
- <choice ident="C">
- <choice ident="D">
- A. SDRAM
- B. NVRAM
- C. Flash
- D. BootROM

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 60

<Huawei>reset saved-configuration
Warning: The action will delete the saved configuration in the device. The configuration will be erased to reconfigure. Continue? [Y/N]:

Refer to the configuration output. Which of the following statements are true? (Select two answers)

- A. A user should enter 'Y' when wishing to clear the saved configuration file.
- B. The saved-configuration file that the device starts with can be erased.
- C. The saved-configuration will be deleted after typing N
- D. The saved-configuration file will be replaced with the current-configuration.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 61

When a router is powered on, the router reads the configuration file saved in the default save directory to get itself initialized. If the configuration file does not exist in the default save directory, what does the router use to initialize itself?

- A. New configuration file
- B. Initial configuration file
- C. Default parameters
- D. Current configuration file

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 62

<Huawei>display startup

MainBoard:

Startup system software: sd1:/ar2220-v200r003c00spc200.cc Next startup system software: sd1:/ar2220-v200r003c00spc200.cc

Backup system software for next startup: null

Startup saved-configuration file: null Next startup saved-configuration file: null

Startup license file: null Next startup license file: null Startup patch package: null Next startup patch package: null

Startup voice-files: null Next startup voice-files: null

Refer to the display output. Which statement is false?

A. The current configuration file has not been saved.

- B. The current startup system software is ar2220-v200r003c00spc200.cc
- C. The next startup system software cannot be changed.
- D. The next startup system software can be changed by using the "startup system software <startup-softwarename>.cc" command.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 63

An AR2200 router in the company network cannot boot. In order to resolve this, the administrator wishes to update the VRP software.

What should he/she do?

- A. The administrator should use a console cable to connect the router and host, and directly upgrade the device.
- B. The administrator should use FTP to transfer the VRP software, by configuring the AR2200 router as an FTP client.
- C. The administrator should use DHCP to boot the AR2200, and then use the AR2200 router as a TFTP client to download the VRP software from the server.

D. The administrator should use the telnet command on the client to remote access the device, and upgrade the VRP software.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 64

<Huawei>

Warning: Auto-Config is working. Before configuring the device, stop Auto-Config. If you perform configurations when Auto-Config is running, the DHCP, routing, DNS, and VTY configurations will be lost. Do you want to stop Auto-Config? [y/n]:

Refer to the output. When the administrator first starts the router, a system notice is displayed, however after rebooting this router, the notice disappeared. What is the reason for this? (Choose two)

- A. This notice only appears during the very first device startup.
- B. The administrator has configured the device and saved the configuration, causing the notice to disappear.
- C. The administrator selected 'n' and did not save the configuration.
- D. The administrator selected 'y' and saved the configuration.

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 65

Which of the following commands can be used to display mapping relationship between network address and DLCI?

- A. display fr interface
- B. display fr
- C. display fr map-info
- D. display fr brief

Correct Answer: C

Section: (none) Explanation

Explanation/Reference:

QUESTION 66

Which of following may be the reasons that cause Frame Relay PVC to work abnormally? (Choose three)

- A. Same DLCI number is configured on the same router
- B. LMI type mismatch
- C. Frame Relay encapsulation type mismatch
- D. Incorrect configuration of the DLCI number

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:

QUESTION 67

An administrator wishes to update the VRP software of company's AR2200 router. How can this be achieved? (Choose three)

- A. The administrator can use FTP to transfer the VRP software, with the AR2200 router as the FTP client.
- B. The administrator can use FTP to transfer the VRP software, with the AR2200 router as the FTP server.
- C. The administrator can use TFTP to transfer the VRP software, with the AR2200 router as the TFTP server.
- D. The administrator can use TFTP to transfer the VRP software, with the AR2200 router as the TFTP client.

Correct Answer: ABD Section: (none)
Explanation

Explanation/Reference:

QUESTION 68

An administrator wishes to implement new features in the network, but the VRP version of one AR2200 router is out of date. The administrator needs to upgrade the VRP software.

Which of the following options regarding file transfer is false?

- A. The AR2200 router can function as a TFTP client to support the upgrade.
- B. The AR2200 router can function as the TFTP server to support the upgrade.
- C. The AR2200 router can function as the FTP server to support the upgrade.
- D. The AR2200 router can function as an FTP client to support the upgrade.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 69

FTP and TFTP can be used to update the system file on Huawei routers. Which of the following statements are correct? (Choose three)

<choice ident="A"> <choice ident="B"> <choice ident="C"> <choice ident="D">

- A. Huawei router can be configured as FTP Client
- B. Huawei router can be configured as FTP Server
- C. Huawei router can be configured as TFTP Client
- D. Huawei router can be configured as TFTP Server

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 70

An administrator discovered he/she was unable to use TFTP to transfer files to the router.

Which of the following describes the likely reason for this?

- A. The TFTP service had been disabled on the router.
- B. TCP port 69 of the server had been blocked.
- C. UDP port 69 of the server had been blocked.
- D. The username and password had been modified.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 71

FTP may be used to upgrade a router's VRP image.

Which of the following transmission modes should be used to achieve this?



- A. binary mode
- B. ASCII mode
- C. byte mode
- D. letter mode

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 72

A client failed to transfer a file to the FTP server, but found the IP connectivity was without problem. The client assumed that the problem was with the port

configuration.
The blocking of which ports would likely cause this problem? (Choose two)
A. 21
B. 80
C. 20 D. 50649
D. 50649
Correct Answer: AC Section: (none)
Explanation
Explanation/Reference:
QUESTION 73 When using VRP, which of the following commands is used to configure the data link layer encapsulation type of a serial interface as HDLC?
A. encapsulation hdlc
B. link-protocol hdlc
C. hdlc enable
D. link-protocol ppp
Correct Answer: B
Section: (none)
Explanation
Explanation/Reference:
QUESTION 74
If AH and ESP are both required to protect data streams between IPsec peers, how many Security Associations (SA) are required in total?
Λ 1
A. 1 B. 2
C. 3
0. 0

D. 4

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 75

Two routers establish an IPsec tunnel, which of the following does not need to be the same on both peering devices?

- A. Encapsulation mode
- B. Transform mode
- C. Proposal name
- D. authentication algorithm

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 76

Which of the following formats represent an accurate condensing of the IPv6 address 2031:0000:720C:0000:0000:09E0:839A:130B? (Choose two).

A. 2031:0:720C:0:0:9E0:839A:130B

B. 2031:0:720C:0:0:9E:839A:130B

C. 2031::720C::9E0:839A:130B

D. 2031:0:720C::9E0:839A:130B

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 77

Which of the following IPv6 addresses can be configured on a router's interface? (Choose two).

A. fe80:13dc::1/64 B. ff00:8a3c::9b/64

C. ::1/128

D. 2001:12e3:1b02::21/64

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 78

The IPv6 address achitecture does not include which of the following address types?

A. unicast

B. multicast

C. broadcast

D. anycast

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 79

Which of the following descriptions regarding IPv6 addresses are correct? (Choose two)

A. IPv6 addresses are 64 bits in length.

B. IPv6 addresses are 128 bits in length.

C. IPv6 extension headers are processed in order.

D. IPv6 extension headers are processed randomly.

Correct Answer: BC Section: (none)

Explanation

Explanation/Reference:

QUESTION 80

Interface G0/0/1 on RTA contains a MAC address of 00e0-fc03-aa73 and is configured with the IPv6 address 2001::2E0:FCFF:FE03:AA73. Which method is most likely to have been used to configure the interface IPv6 address?

- A. DHCPv6
- B. Auto-link
- C. ARP
- D. EUI-64

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 81

In a small network supporting IPv6, a network administrator wishes implement RIPng.

Which of the following commands should be used to enable this protocol?

- A. [RTA-GigabitEthernet0/0/0]ripng 1 enable
- B. [RTA]ripng 1 enable
- C. <RTA>ripng 1 enable
- D. [RTA-ripng-1]ripng 1 enable

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 82

In a network supporting IPv6, OSPF no longer supports which feature?

- A. multiple areas
- B. Router-ID
- C. authentication
- D. multicast updates

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 83

The network administrator has decided to configure link aggregation in the enterprise network.

Which of the following represent advantages of link aggregation? (Choose three)

- A. Load balancing.
- B. Improved bandwidth.
- C. Enhanced reliability.
- D. Improved security.

Correct Answer: ABC

Section: (none) Explanation

Explanation/Reference:

QUESTION 84

In port aggregation, "multiple" ports are aggregated to form a port aggregation group so that all the member ports in the group share the outgoing/incoming load.

At which layer is port aggregation implemented?

- A. Physical Layer
- B. Data Link Layer
- C. Network Layer
- D. Transport Layer

Correct Answer: B
Section: (none)
Explanation

Explanation/Reference:

QUESTION 85

What benefits does port aggregation yield? (Choose three)

- A. Improves link bandwidth
- B. Implements load sharing
- C. Improves network reliability
- D. Facilitates data copy for analysis

Correct Answer: ABC

Section: (none) Explanation

Explanation/Reference:

QUESTION 86

What is the maximum number of member interfaces supported by a single Eth-Trunk?

- A. 6
- B. 8
- C. 10
- D. 12

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 87

The Eth-Trunk frame forwarding mechanism used to prevent changes in the data sequence forwards frames based on which of the following parameters?

- A. The same source or destination IP address.
- B. The same source or destination MAC address.
- C. The same protocol type.
- D. The same source or destination port number.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 88

In Layer 2 mode, the transmission rate of an Eth-Trunk interface is determined by which of the following?

A. Maximum number of Up member links



- B. Minimum number of Up member links
- C. Number of Up member interfaces
- D. Number of interfaces.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 89

The network administrator wishes to forward data over an Eth-trunk, however associated member interfaces operate at different rates. In terms of the resulting behavior, which of the following is true?

- A. The two switches will not be able to communicate.
- B. The higher rate member interfaces may incur packet loss.
- C. The Eth-Trunk will work normally.
- D. The lower rate member interfaces may incur packet loss.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 90

The network administrator attempts to add interface G0/0/1 on Switch A to Eth-trunk 1, however the command fails.

Which of the following may cause this?

- A. The interface is operating in half-duplex mode.
- B. The interface has been shutdown.
- C. The interface is already associated with another Eth-trunk.
- D. The interface is an access port.

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 91

A network requires a solution to allow 50 private IP addresses to be translated, however only a single public address is available for use.

Which translation method can be used to support this requirement?

- A. Static NAT
- B. Dynamic NAT
- C. Easy-IP
- D. NAPT

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 92

NAPT allows for multiple internal addresses to be mapped to a single public address.

How does NAT distinguish between the different private addresses when mapping to the same public address?

- A. The source MAC address is used.
- B. The destination MAC address is used.
- C. The source port number is used.
- D. The destination port number is used.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 93

A web server in a private network is required to provide HTTP services to public users. The network administrator is required to configure NAT on RTA.

Which configuration should be used?

- A. [RTA-Serial1/0/1]nat server protocol tcp global 202.10.10.1 www inside 192.168.1.1 8080
- B. [RTA-Serial0/0/1]nat server protocol tcp global 192.168.1.1 www inside 202.10.10.1 8080
- C. [RTA-Gigabitethernet0/0/1]nat server protocol top global 202.10.10.1 www inside 192.168.1.1 8080
- D. [RTA- Gigabitethernet0/0/1]nat server protocol tcp global 192.168.1.1 www inside 202.10.10.1 8080

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 94

The network administrator needs to configure static NAT on RTA, in order to allow Host A to communicate with Host C.

Which command is correct?

- A. [RTA-Serial1/0/1]nat outbound 200.1.1.10
- B. [RTA-Serial1/0/1]nat static global 200.1.1.10 inside 192.168.1.0
- C. [RTA-Serial1/0/1]nat static global 192.168.1.1 inside 200.1.1.10
- D. [RTA-Serial1/0/1]nat static global 200.1.1.10 inside 192.168.1.1

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 95

[RTA-GigabitEthernet0/0/0]nat outbound 2000 address-group 1

Refer to the configuration output. What does the value "2000" refer to?

- A. It represents the ACL number.
- B. It represents the NAT number.
- C. It represents the translated port number.
- D. It represents the number of bytes that can be translated before the address is returned to the public address pool.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 96

NAPT uses the same public address but different port numbers to translate private addresses.

Which statement regarding the port number is correct?

- A. It is necessary to configure port number mapping manually.
- B. It is only necessary to configure the port number range.
- C. It is not necessary to configure port numbers.
- D. An access control list is needed to assign port numbers.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 97

A configured internal host of a private network wishes to access the internet. What must be configured on the enterprise network's edge router in order to achieve this? (Choose two)

- A. NAT EasyIP
- B. DHCP
- C. BGP
- D. Default route

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 98

Which of the following statements are correct about NAT? (Choose three)

- A. NAT is the abbreviation for "Network Address Translation".
- B. NAT is used for translation between private and public network addresss.
- C. When hosts inside a private network access the outside network, NAT is not required.
- D. NAT provides an effective way to solve the problem of insufficient IP addresses.

Correct Answer: ABD

Section:	(none)
Explanat	ion

Explanation/Reference:

QUESTION 99

Which of the following technologies can allow a host with IP address 10.0.0.1 to access the internet?

- A. Static route
- B. Dynamic route
- C. Route import
- D. NAT

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 100

Which of the following items can be translated by NAPT?

- A. MAC address + port number
- B. IP address + port number
- C. Only MAC address
- D. Only IP address

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 101

Which of the following statements about a designated port working in RIPv2 multicast mode are true? (Choose three)

- A. The port receives only RIPv2 multicast packets.
- B. The port does not receive RIPv1 broadcast packets.
- C. The port does not receive RIPv2 broadcast packets.
- D. The port receives only RIPv1 multicast packets.

Correct Answer: ABC Section: (none)

Explanation

Explanation/Reference:

QUESTION 102

Which of the following statements regarding the router ID in OSPF are incorrect? (Choose three)

- A. The router IDs of OSPF routers in the same area must be the same, but can be different in different areas.
- B. The router ID must be the IP address of an OSPF router interface.
- C. The router ID must be configured manually.
- D. A router running OSPF must have a router ID for it to operate properly.

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 103

The administrator wishes to configure OSPF on a router in the network however the router has no loopback interface.

Which value will be used as the router ID?

- A. The lowest IP address of the router's active interfaces.
- B. The highest IP address of the router's active interfaces.
- C. The IP address of the management interface.
- D. The priority value of the router.

Correct Answer: B Section: (none)

Explanation

Explanation/Reference:

QUESTION 104

An administrator of a company supporting a large enterprise network wishes to implement OSPF on the network as opposed to RIP. Which of the following points should the administrator use to support his reasoning for this change? (Choose three)

- A. OSPF has no hop count limitation.
- B. OSPF has a lower routing update overhead.
- C. OSPF has a simpler configuration.
- D. OSPF supports faster convergence.

Correct Answer: ABD Section: (none)
Explanation

Explanation/Reference:

QUESTION 105

Which of the following statements regarding single area OSPF are correct? (Choose three)

- A. An IP address needs to be configured on a loopback interface of each router before configuring an OSPF area.
- B. The value of an area can be from 0.0.0.0 to 255.255.255.255.
- C. A single area can be configured using any supported area number.
- D. All of the links of the network need to be advertised in Area 0.

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:

QUESTION 106

10.0.1.0/24 O_ASE 150 2 D 10.0.23.3 Serial2/0/0

Refer to the display output. Which of the following statements regarding route shown are true? (Choose two)

- A. The address 10.0.23.3 has been configured on the peer's serial 2/0/0 interface.
- B. The route preference has been changed by the administrator.
- C. The metric for the route 10.0.1.0 indicates that two hops are needed.
- D. The route has been learned via the OSPF protocol.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 107

Which of the following statements regarding link-state database and routing-table of a "single" OSPF area are correct? (Choose two)

- A. The link-state databases that all routers build are identical.
- B. The link-state databases that all routers build are different.
- C. The routing-tables that all routers calculate are different.
- D. The routing-tables that all routers calculate are identical.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 108

Which of the following steps are necessary to configure OSPF on a Huawei router? (Choose three)

- A. Configuration of a router ID
- B. Enabling of an OSPF process
- C. Specifying an OSPF area
- D. Configuration of the network segments within each area

Correct Answer: BCD

Section: (none)

Explanation

Explanation/Reference:

QUESTION 109

An OSPF area is a collection of a group of routers and networks. OSPF defines that routers that have the same () belong to the same OSPF area.

- A. neighbors
- B. LSDB
- C. LSA
- D. adjacency

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 110

Which of the following statements about router IDs are true? (Choose two)

- A. The routers contained in the same LSDB have the same router ID.
- B. Each router in an OSPF network must have a unique router ID.
- C. Two routers in different OSPF areas can have the same router ID.
- D. A router ID is expressed in a 32-bit dotted decimal format.

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 111

OSPF allows for "multiple" processes. By default, OSPF selects a process whose number is ().

A. 0

- B. 1
- C. 10
- D. 100

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 112

In a network supporting IPv6, OSPF no longer supports which feature?

- A. multiple areas
- B. Router-ID
- C. authentication



D. multicast updates

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 113

Two routers are configured with OSPFv3. OSPFv3 is enabled on all interfaces of each router.

Which of the following is true in the event that the network administrator does not configure a Router-ID?

A. The IP address of the loopback 0 interface will be used as the router ID.

- B. The IP address of the loopback 1 interface will be used as the router ID.
- C. The IP address of interface G0/0/0 will be used as the router ID.
- D. No router ID will be assigned to the router.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 114

Destination/Mask protocol pre Cost Nexthop Interface

9.0.0.0/8 OSPF 10 50 1.1.1.1 Serial 1/0/0 9.1.0.0/16 RIP 100 5 2.2.2 2 Ethernet 0/0/1

Refer to the graphic. Which of the following statements is correct when this router forwards the packet to the destination host 9.1.4.5?

- A. The router selects the first entry to match the destination address of the packet because the preference of OSPF is higher than the preference of RIP.
- B. The router selects the second entry to match the destination address of the packet because the cost of RIP is lower than that of OSPF.
- C. The router selects the second entry to match the destination address of the packet because the outgoing interface is an Ethernet interface. The forwarding speed of an Ethernet interface is faster than the forwarding speed of a serial interface
- D. The router selects the second entry to match the destination address of the packet because the router will match the most specific address.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 115

According to the default value of route preference on the VRP platform, which of the following represent the correct sequence for direct route, static route, RIP and OSPF if they are listed from high preference to low preference?

A. Direct, Static, RIP, OSPF

- B. Direct, OSPF, Static, RIP
- C. Direct, OSPF, RIP, Static
- D. Direct, RIP, Static, OSPF

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 116

A router has learned two routes for the same network with the same prefix. One route has been learned via OSPF with a metric of 4882, while the other route has been learned via RIPv2 with a metric of 4.

Which route (s) will be found in the routing table?

- A. The RIPv2 route.
- B. The OSPF and RIPv2 routes.
- C. The OSPF route.
- D. Neither of these routes will be found in the routing table.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 117

Two routers are connected via serial interfaces, for which the link-protocol is PPP. The network administrator wishes to configure PPP authentication to improve security on this link.

Which PPP authentication method provides a more secure solution?

- A. CHAP
- B. PAP
- C. MD5
- D. SSH

Correct Answer: A
Section: (none)
Explanation

Explanation/Reference:

QUESTION 118

If PPP authentication fails, which type of packet will be sent to the authenticated peer by the authenticator?

- A. Authenticate-Ack
- B. Authenticate-Nak
- C. Authenticate-Reject
- D. Authenticate-Reply

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 119

Two routers are connected via serial interfaces and the link-protocol is PPP, but the MRU of two serial interfaces are different, in PPP LCP negotiated stage, what will happen?

- A. LCP negotiation will fail
- B. Negotiation will use the smaller value
- C. Negotiation will use the larger value
- D. Negotiation will use 1500

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 120

PPP is more secure than HDLC because PPP supports authentication protocols such as (). (Choose two)

- A. PAP
- B. MD5
- C. CHAP
- D. SSH

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 121

A serial interface of a Huawei router currently using HDLC needs to assign PPP as the encapsulation protocol.

Which of the following commands is required to be configured at the serial interface view?

- A. link-protocol ppp
- B. encapsulation ppp
- C. enable ppp
- D. address ppp

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 122

When using VRP, which of the following commands is used to configure the PPP authentication method as PAP?

- A. ppp pap
- B. ppp authentication-pap
- C. ppp authentication-mode pap
- D. ppp pap-authentication

Correct Answer: C	
Section: (none)	
Explanation	

Explanation/Reference:

QUESTION 123

When configuring the PPP authentication method as PAP, which of the following operations are necessary? (Choose three)

- A. Add the user name and password of the authenticated party to the local user list.
- B. Configure the encapsulation type of the interface connected to the peer as PPP.
- C. Configure PPP authentication method as CHAP.
- D. On the authenticated party end, configure the user name and password that are sent to authenticator.

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 124

In the PPP protocol, which of the following encryption algorithms is used by CHAP?

- A. DES
- B. MD5
- C. AES
- D. None

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 125

What is the function of the "ip address ppp-negotiate" command?

- A. Enables the function of requesting for an IP address from the peer device.
- B. Enables the function of accepting the request for an IP address from the remote device.
- C. Enables the function of statically allocating IP addresses to the peer.
- D. None of the above.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:



Realtests H12-211 Connor 233q

Number: H12-211
Passing Score: 600
Time Limit: 120 min
File Version: 12.5



http://www.gratisexam.com/

Exam Code:H12-211



AAA

QUESTION 1

An administrator currently manages AR2200 devices in the network through a single password, however the company wishes to introduce another two administrators and provide unique user credentials and privilege levels for telnet access to the network devices. What action can be taken? (Three Anwsers)

- A. Configure three users under the AAA-view, and assign each a different password.
- B. The authentication mode must be changed to AAA.
- C. Each administrator must be assigned a privilege level.
- D. A public IP address must be assigned to each user for telnet access

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 2

Which of the following authentication methods are supported for Telnet users? (Select 3 Answers)

- A. Password authentication
- B. AAA local authentication
- C. MD5 authentication
- D. No authentication

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 3

Which authentication modes does AAA support? (Three Answers).



http://www.gratisexam.com/

- A. None
- B. Local
- C. Radius
- D. 802.1X

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 4

[RTA]aaa

[RTA-aaa]domain huawei

[RTA-aaa-domain-huawei]authentication-scheme au1 [RTA-aaa-domain-huawei]authentication-scheme au2

Refer to the configuration output. RTA has been configured using AAA as shown, and associated with the "huawei" domain. For users in the huawei domain, which authentication-scheme will be used

- A. au1
- B. au2
- C. au1 will be used. When au1 is deleted, users will use au2
- D. au2 will be used. When au2 is deleted, users will use au1

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 5

A user accesses a server supporting AAA, for which the authorization mode on the AAA server has been configured using the command "authorization-mode hwtacacs if-authenticated". Which of the following statements regarding this command are true? (Three Answers).

- A. If the hwtacacs server fails to respond, the user will be authenticated using local authentication.
- B. If the hwtacacs server fails to respond, the user will be authenticated using remote authentication.
- C. If the hwtacacs server fails to respond, the user will bypass authentication.
- D. The hwtacacs server will authorize the user.

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 6

Which of the following descriptions regarding eSight is not correct?

- A. eSight is used to monitor and manage enterprise networks.
- B. eSight supports only Huawei devices
- C. eSight supports WLAN management and monitoring of hotspot coverage.
- D. eSight supports the backup of configuration files and network traffic analysis.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

ACL

QUESTION 1

What of the following statements is correct regarding access control list types and ranges?

- A. A basic ACL value ranges from 1000-2999
- B. An advanced ACL value ranges from 3000-4000
- C. A layer 2 ACL value ranges from 4000-4999
- D. An interface ACL value ranges 1000-2000

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 2

Which of the following parameters is not used by Advanced ACL?

- A. Source interface
- B. Destination port number
- C. Protocol number
- D. Time-range

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 3

[RTA]acl 2001

[RTA-acl-basic-2001]rule permit source 10.0.1.0 0.0.0.255 [RTA-acl-basic-2001]rule deny source 10.0.1.0 0.0.0.255

Refer to the configuration output. Which of the following statements regarding ACL 2001 is correct?

- A. Packets from network 10.0.1.0/24 network will be denied.
- B. Packets from network 10.0.1.0/24 network will be permitted.
- C. Packets destined for network 10.0.1.0/24 will be denied.
- D. Packets destined for network 10.0.1.0/24 will be permitted.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 4

[RTA]acl 2002

[RTA-acl-basic-2002]rule permit source 20.1.1.1 0 [RTA-acl-basic-2002]rule permit source 30.1.1.1 0

Refer to the configuration output. A network administrator configured the ACL on router RTA, as shown. Which of the following statements regarding the rule order are correct? (Two Answers).



http://www.gratisexam.com/

- A. The rule-number of the first rule is 1
- B. The rule-number of the first rule is 5
- C. The rule-number of the second rule is 2
- D. The rule-number of the second rule is 10

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 5

Refer to the graphic. The network administrator has configured ACL 2000 to filter packets on RTA, as shown. Which of following statements regarding the subsequent behavior are correct? (Two Answers).

- A. RTA will forward packets received from Host A.
- B. RTA will drop packets received from Host A.
- C. RTA will forward packets received from Host B.
- D. RTA will drop packets received from Host B.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 6

Refer to the graphic. The network administrator wishes to deny Host A access to the HTTP server but allow access to all other servers. Which of the following ACL rules will achieve this?

- A. Rule deny tcp source 10.1.1.1 0 destination 202.100.1.12 0.0.0.0 destination-port eq 21
- B. Rule deny tcp source 10.1.1.1 0 destination 202.100.1.12 0.0.0.0 destination-port eq 80
- C. Rule deny udp source 10.1.1.1 0 destination 202.100.1.12 0.0.0.0 destination-port eq 21
- D. Rule deny udp source 10.1.1.1 0 destination 202.100.1.12 0.0.0.0 destination-port eq 80

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 7

Following a failure of services in the network, an administrator discovered that the configuration in one of the enterprise routers had been changed. What actions can be taken by the administrator to prevent further changes? (Three Answers)

A. The administrator should limit access by setting the login privilege of users to 0.

- B. The administrator should configure AAA to manage user authorization on the router.
- C. The administrator should configure an ACL to allow only the administrator to manage the router.
- D. The administrator should configure port-security on the router

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 8

[RTA]acl 2001

[RTA-acl-basic-2001]rule 20 permit source 20.1.1.0 0.0.0.255 [RTA-acl-basic-2001]rule 10 deny source 20.1.1.0 0.0.0.255

Refer to the configuration output. Which of the following statements is correct regarding the configuration of the ACL on RTA?

- A. Packets from network 20.1.1.0/24 network will be denied.
- B. Packets from network 20.1.1.0/24 network will be permitted.
- C. Packets destined for network 20.1.1.0/24 will be denied.
- D. Packets destined for network 20.1.1.0/24 will be permitted.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 9

[RTA]acl 2001

[RTA-acl-basic-2001]rule deny source 172.16.1.1 0.0.0.0 [RTA-acl-basic-2001]rule deny source 172.16.0.0 0.255.0.0

Refer to the configuration output. Which of the following statements are correct regarding the configuration of the ACL on RTA? (Two Answers).

- A. Packets from network 172.16.1.1/32 will be denied.
- B. Packets from network 172.16.1.0/24 will be denied
- C. Packets from network 172.17.1.0/24 will be denied
- D. Packets from network 172.18.0.0/16 will be denied.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

Basic IP Network

QUESTION 1

The network administrator wants to improve the performance of network transmission, what steps can the administrator take? (Two Answers)

- A. Change the work mode to full duplex of each end station.
- B. Link the end stations together using a switch.
- C. Change the work mode to half duplex of each end station.
- D. Link the end stations together using a hub.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 2

On Huawei switch, which of the following commands can be used to set port duplex mode as "auto negotiation"? (Select 2 Answers)

- A. duplex negotiation auto
- B. duplex auto-negotiation
- C. duplex auto
- D. undo duplex

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 3

The network administrator wishes to transmit data between two end stations. The network interface cards of both devices operates at 100Mbps however one supports half duplex while the other uses full duplex mode. What will occur as a result?

- A. The end stations cannot communicate.
- B. The end stations can communicate, but data may be lost during transmission of large amounts of traffic.
- C. The end stations will operate normally
- D. The end stations can communicate, but speed is different during transmission of large amounts of traffic.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 4

An Ethernet port can work one of three duplex modes, whereas an Optical Ethernet port only supports one single mode. Which of the following represents this mode?

- A. Full-duplex
- B. Half-duplex
- C. Auto-negotiation

D. Simplex

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 5

While inspecting packets in the network, a network administrator discovers a frame with the destination MAC address of 01-00-5E-A0-B1-C3. What can the administrator determine from this?

- A. The MAC address is a unicast address.
- B. The MAC address is a broadcast address
- C. The MAC address is a multicast address.
- D. The MAC address is incorrect

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 6

According to OSI reference model, which layer is responsible for end to end error checking and flow control?

- A. Physical layer
- B. Data link layer
- C. Network layer
- D. Transport layer

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 7

Which of the following mechanisms are used for flow control? (Select 3 Answers)

- A. Acknowledgement
- B. Buffering
- C. Source quench messages
- D. Windowing

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:



http://www.gratisexam.com/

QUESTION 8

Source Destination	on Protocol	Info
10.0.12.1 10.0.12.	2 TCP	50190 > telnet [SYN] Seq=0 Win=8192 Len=0 MSS=1460
10.0.12.2 10.0.12.	1 TCP	telnet> 50190 [SYN, ACK] Seq=0 Ack=1 Win=8192 Len=0 MSS=1460
10.0.12.1 10.0.12.	2 TCP	50190 > telnet [ACK] Seq=1 Ack=1 Win=8192 Len=0

Refer to the capture output. The administrator has captured three packets in the network. Which statement regarding the capured packets is incorrect?

- A. This packets represent a TCP three-way handshake process.
- B. 10.0.12.1 is the telnet server, while 10.0.12.2 is the telnet client.
- C. The three packets contain no application data.
- D. 10.0.12.1 uses port 50190 to buid the telnet connection.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 9

An Ethernet frame is captured by network protocol analyzer tool and the value of Type/Length field is 0x0800. Which of the following statements about the frame are correct? (Select 2 Answers)

- A. The frame structure of the frame is Ethernet_II
- B. The frame structure of the frame is 802.3
- C. Its upper layer protocol is IP
- D. Its upper layer protocol is IPX

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 10

Which of the following descriptions regarding the TTL field of the IP packet is correct?

- A. The TTL defines how many packets the source can send.
- B. The TTL defines the duration during which the source can send packets.
- C. The TTL value will decrement by 1 each time the packet is routed.
- D. The TTL value will increment by 1 each time the packet is routed.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 11

Which of the following statements are correct about TTL field in IP packet? (Select 2 Answers)

- <choice ident="A">
- <choice ident="B">
- <choice ident="C">
- <choice ident="D">
- A. The maximum value of TTL is 65535
- B. Normally, it's impossible for a router to receive a packet whose TTL is zero.
- C. The main purpose of TTL is to prevent IP packets from circulating endlessly in a network which can consume a lot of bandwidth
- D. TTL value will be decremented as a packet is passed through the network devices such as hub, LAN switch and router.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 12

In the case of Huawei router, what is the "-i" parameter in a Ping command issued on a VRP operating system used to set?

- A. Interface for sending an Echo Request packet
- B. Source IP address for sending an Echo Request packet
- C. Interface for receiving an Echo Reply packet
- D. Destination IP address for receiving an Echo Reply packet

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 13

To provide the information about the IP addresses that a user packet traverses along the path to the destination, which of the following does Tracert record in each expired ICMP TTL packet?

- A. Destination port
- B. Source port
- C. Destination address
- D. Source address

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 14

Which of the following statements regarding the verification of IP connectivity are false? (Three Answers)

- A. The ping 127.0.0.1 command can be used to check whether the network cable is correctly inserted into the host's Ethernet port.
- B. The ping command with the host IP address as the destination can be used to verify that the TCP/IP

protocol suite is functioning correctly.

- C. The ping command can be used to verify connectivity between the host and the local gateway.
- D. The command "ipconfig /release" can be used to check connectivity problems between the host and the local gateway.

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 15

A network administrator uses the ping command to check for points of failure in the network. Which protocols will be used during this process? (Two Answers)

<choice ident="A">

<choice ident="B">

<choice ident="C">

<choice ident="D">

A. ICMP.

B. TCP.

C. ARP.

D. UDP.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 16

A network administrator recently used tracert to trace the path to the destination IP address of an external website, however the trace path displayed only a timeout result. Which of the following statements correctly explains the reason for this? (Two Answers)

- A. The source router had shutdown the ICMP function.
- B. This destination IP address does not exist.
- C. The gateway canot find a route to the destination.
- D. This is a normal phenomenon.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 17

Ping 10.0.0.2:56 data bytes, press CTRL_C to break

Reply from 10.0.0.2 : bytes=800 Sequence=1 ttl=255 time=2 ms Reply from 10.0.0.2 : bytes=800 Sequence=2 ttl=255 time=10 ms

--- 10.0.0.2 ping statistics ---

2 packet(s) transmitted

2 packet(s) received

0.00% packet loss

round-trip min/avg/max = 2/6/10 ms

A network administrator uses the ping command to test connectivity to the destination 10.0.0.2 on a Huawei AR series router. Which statement regarding the output is correct?

- A. The network administrator used the command ping -c 2 -s 800 10.0.0.2
- B. The network administrator used the command ping -a 2 -v 800 10.0.0.2
- C. The path between the source and destination is not OK.
- D. The network administrator changed the default TTL value.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 18

Which of the following statements explains the behavior of the ICMP redirect function? (Two Answers)

- A. When a router receives data on the interface via which the same data needs to be forwarded, and the source is on the same segment as the next hop, an ICMP redirect message will be sent by the router to the source.
- B. When a router receives data on an interface, and the router's IP address matches the destination IP of the data, an ICMP redirect message will be sent by the router to the source.
- C. When a router receives data on the interface via which the same data needs to be forwarded, and the source is on the same segment as the next hop, an ICMP Redirect message will be sent by the source to the router.
- D. When a router receives data on the interface via which the same data needs to be forwarded, and the source is on a different segment from the next hop, an ICMP redirect message will be sent by the router to the source

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 19

Host A wishes to send data to host C, and generates an ARP request to obtain the destination MAC address. Which statement is true?

- A. The destination IP address of the ARP request is Host C
- B. The destination MAC address of this ARP request is Host C
- C. The destination IP address for the ARP request is a broadcast IP address.
- D. The destination MAC address of this frame is the MAC address of G0/0/0 on RTA.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 20

An ARP request is sent by host A to obtain the destination MAC address of host D. Which statement is true about regarding the ARP reply?

- A. The destination MAC address of this frame is the MAC address of Switch A.
- B. The destination IP address of this packet is the VLANIF1 IP address of Switch A.
- C. The destination MAC address of this frame is the MAC address of Host A.
- D. The destination IP address of this packet is a broadcast IP address.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 21

Which of the following applications can be used to detect the path along which the data packets are transmitted from the source to the destination?

- <choice ident="A">
- <choice ident="B">
- <choice ident="C">
- <choice ident="D">
- A. Route
- B. Netstat
- C. Tracert
- D. Send

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 22

How many probe packets are sent for each TTL value by default when "tracert" is used to detect the path along which packet is sent from source to destination?

- A. 3
- B. 4
- C. 6
- D. 8

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 23

Which of the following types can ICMP packets be classified into? (Select 2 Answers)

- A. ICMP transport packet
- B. ICMP error reporting packet
- C. ICMP query packet
- D. ICMP application packet

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 24

On VRP platform, which of the following parameters can be used together with the "ping" command to

specify the source address of an echo request message?

- A. A
- B. S
- C. D
- D. N

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 25

A router functioning as a Proxy receives an ARP request packet, but finds that the destination address in the packet is not intended for itself. In this case, what will the router do? (Select 2 Answers)

- A. Discard the packet.
- B. Check for a route that matches the destination address.
- C. Forward its MAC address to the ARP request sender after finding that a route to the destination address is available.
- D. Broadcast the ARP request packet.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 26

Two end stations in a point-to-point network perform address resolution. Which of the following statements is correct?

- A. The destination address of an ARP request from each station will be a unicast MAC address.
- B. The destination address of an ARP request from each station will be a broadcast IP address.
- C. The destination address of an ARP reply from each station will be a unicast MAC address
- D. The destination address of an ARP reply from each station will be a broadcast MAC address.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 27

What will the destination MAC address be at the moment a frame is transmitted by the host, when the router is the IP destination?

- A. The MAC address of the switch.
- B. The MAC address of the router interface G0/0/0.
- C. The MAC address of the host.
- D. The destination MAC address will be a broadcast MAC address.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 28

Which of the following statements about gratuitous ARP packets are true? (Select 2 Answers)

- A. A system can determine whether conflicting IP addresses are used by sending a gratuitous ARP packet
- B. A gratuitous ARP packet uses the same format as an ARP request packet.
- C. A gratuitous ARP packet can help to update an IP address.
- D. A gratuitous ARP packet uses the same format as an ARP reply packet.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 29

UDP is connectionless oriented, which of the following must be used in order to ensure reliability?

- A. Internet Protocol
- B. Application Layer Protocol
- C. Network Layer Protocol
- D. Transmission Control Protocol

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 30

The administrator has configured an IP address for Host A and Host B, but had forgotten to configure a default gateway. What effect will this have on the hosts?

- A. Neither host will be affected, and therefore will be able to communicate with the peer.
- B. Host A will be unable to connect to the router's G0/0/0 interface.
- C. Hosts will be unable to comminicate unless arp-proxy is enabled on the router.
- D. The host will be unable to reach neither the local nor remote network destinations .

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 31

A host has established a telnet connection with the router attached to interface G0/0/0. Which of the following statements are correct? (Two Answers)

- A. The destination address of a frame sent by the host will be the MAC address of the router interface.
- B. The destination address of a frame will be the MAC address of the switch interface.
- C. The destination port number in a segment header will have a value of 80.
- D. The destination IP address of a packet will be the IP address of the network interface of the router.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 32

The administrator uses the ping command on the host to test connectivity to the website www.huawei.com. The command line shows a request time out. The administrator displays the ARP entries for the host. Which entry will be found in the ARP cache table of the host?

- A. The MAC address of the destination www.huawei.com will exist in the ARP cache.
- B. The MAC address of the switch will exist in the ARP cache.
- C. The IP address of the destination www.huawei.com will exist in the ARP cache.
- D. The MAC address of router interface G0/0/0, will exist in the ARP cache.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 33

When R2 forwards data to R3 from R1, which of the following items will change? (Two Answers)

- A. The source MAC address
- B. The destination MAC address
- C. The source IP address
- D. The destination IP address

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 34

If Host B also configured the IP address as "192.168.1.1/24", an IP address confict will occur. What will happen as a result?

- A. Host B will send an ICMP request to the destination with the configured IP address. If a reply is received, the host will notify of an address conflict.
- B. Host A will send a gratuitous ARP request to resolve the MAC address of the destination 192.168.1.1, for which Host B will reply.
- C. Host B will send a gratuitous ARP request to resolve the MAC address of the destination 192.168.1.1, for which Host A will reply.
- D. Host A will ignore any received ARP request intended for destination 192.168.1.1.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 35

<Quidway>display mac-address

MAC Address VLAN/VSI	Learned-From	Туре
5489-98ec-f018 1/-	GE0/0/13	dynamic

Total items displayed = 1

Refer to the graphic. A switch attempts to forward a frame to the MAC destination 5489-98ec-f01. What operation will occur on the switch?

- A. The switch will send a request to obtain the MAC address of 5489-98ec-f011.
- B. The switch will report that the destination is unreachable and report this to the source.
- C. The switch will flood the frame via all ports, with exception of the port on which the frame was received.
- D. The switch will drop the frame because it does not have an entry in its MAC address table.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 36

Host A has been connected to switch A and configured with an IP address. When Host A initially forwards a frame, what action will be taken by Switch A?

- A. Switch A will drop this frame.
- B. Switch A will attempt to flood the frame to all ports except for the G0/0/1 interface.
- C. Switch A will forward the frame via ports G0/0/1, G0/0/2 and G0/0/3.
- D. Switch will receive this frame before returning the frame to G0/0/1.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 37

Which of the following statements describes the network shown? (Two Answers)

- A. There are 6 collision domains in the network.
- B. There are 2 broadcast domains in the network.
- C. There are 4 collision domains in the network.
- D. There are 6 broadcast domains in the network.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 38

A server is linked to port interface G0/0/1 of a switch. The administrator wishes to allow only this server to be linked to this interface on the switch. Which method can be used to achieve this?

- A. Configure a static ARP entry using the server's IP address and MAC address in the switch.
- B. Configure a static MAC address binding entry of the server's MAC address and the interface in the

switch.

- C. Configure the default gateway of the switch to be the same as the server's IP address.
- D. It is not possible to enable a single device to be associated with an interface.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 39

An administrator connects two switches together in a local enterprise network. The ports of one switch support Fast Ethernet, while the ports of the other switch support Gigabit Ethernet. Hosts connected to one switch are able to communicate, however communication between the two switches fails. What is the possible reason for this?

- A. The ports have disabled auto-negoatition.
- B. One port is supporting auto-negotiation, while auto-negotiation is disabled on the port of the other switch.
- C. The port of one switch is operating using half duplex mode, while the port of the other switch is using full duplex mode.
- D. A Fast Ethernet port cannot communicate directly with a Gigabit Ethernet port.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 40

A layer 2 LAN switch generates CAM table entries according to the () of the received frame.

- A. Source MAC address
- B. Destination MAC address
- C. Source IP address
- D. Destination IP address

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 41

Which of the following statements about collision domains and broadcast domains are correct? (Select 3 Answers)

- A. Devices connected to the same hub form a collision domain
- B. Devices connected to the same hub form a broadcast domain
- C. Devices connected to the same bridge form a collision domain
- D. Devices connected to the same bridge form a broadcast domain
- E. Devices connected to the same router form a broadcast domain

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 42

Which of the following statements regarding layer-2 switch is incorrect?

- A. The switch learns MAC addresses automatically
- B. The layer-3 header is modified before the received packet is transmitted
- C. The layer-2 header is modified before the received packet is transmitted.
- D. The layer-2 LAN switch operates at data link layer

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 43

[R1]display interface GigabitEthernet0/0/0

GigabitEthernet0/0/0 current state: Administratively DOWN

Line protocol current state: DOWN

Refer to the display output. What can be determined based on the output of the display command?

- A. Interface Gigabit Ethernet 0/0/0 is connected to a wrong cable
- B. Interface Gigabit Ethernet 0/0/0 is not associated with an IP address
- C. Interface Gigabit Ethernet 0/0/0 is not associated with a dynamically defined route.
- D. Interface Gigabit Ethernet 0/0/0 has been manually shut down by an administrator.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 44

Which of the following statements regarding static and dynamic routing is incorrect?

- A. The static route can be easily configured and managed on the enterprise network.
- B. The use of dynamic routing is more convenient for the administrator to manage the network following network convergence.
- C. The static route can automatically recover when a link failure is encountered.
- D. Dynamic routing will use more resources than static routes.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 45

Which of the following are routed protocols? (Select 2 Answers)

- A. IP
- B. OSPF
- C. BGP

D. IPX

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 46

Which of the following statements regarding the routing table are correct? (Select 2 Answers)

- A. The next hop in the routing table is redundant because the outgoing interface can be used for packet forwarding.
- B. The routes from generated by different protocols have different preferences.
- C. The metrics of different routing protocols are comparable.
- D. The metrics of different routing protocols are not comparable

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 47

Which of the following commands can be used to display the routing table on a Quidway router?

- A. display ip path
- B. display ip routing-table
- C. display interface
- D. display current-configuration

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 48

Which of the following entries is not included in the routing table?

- A. source address
- B. next hop
- C. destination address
- D. cost

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 49

Which of the following problems are caused by routing loops? (Select 3 Answers)

- A. Slow convergence
- B. Packets circulate between routers

- C. Router restarting
- D. Inconsistency of routing information

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 50

An administrator wishes to manage the router in the remote branch office, which method can be used?

- A. Telnet
- B. FTP
- C. Console Connection
- D. DHCP

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 51

The network administrator has configured the router as shown. Which statement is false?

- A. The configuration manages the user login through the console interface.
- B. The user login through vty 0 has the privilege to run level 2 commands.
- C. The user login through telnet has the privilege to run level 2 commands.
- D. The configuration manages the telnet user login.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 52

The administrator cannot use telnet to manage the AR2200. The administrator is able to verify connectivity to the router and has been informed that other administrators have no difficulties using telnet. Which statements describe the possible reasons for this problem? (Two Answers)

- A. The user's status has been blocked
- B. The user's priviledge level has been changed to 0.
- C. The user has been deleted.
- D. The telnet service in the AR2200 router has been disabled.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 53

A user logged into a VRP supported device through telnet, but when attempting to configure the device, found that he is unable to use the sytem-view command to enter the system-view. What are the possible

reasons for this? (Two Answers)

- A. The device's VTY interface only provides permission for some telnet users to run the sytem-view command.
- B. The user's telnet software restricts use of this command.
- C. The user's privilege level is lower than the level associated with the system-view command.
- D. The system-view command privilege level is lower than the level associated with the user.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 54

The users who log on the router through Telnet are not permitted to configure IP address. What is the possible reason?

- A. Communication failures occur between the user and the router.
- B. The authentication mode of Telnet is set incorrectly.
- C. Privilege level of Telnet is set incorrectly.
- D. SNMP parameters are set incorrectly.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 55

Which of the following statements are correct? (Two Answers)

- A. A single collision domain exists between RTA and SWC.
- B. A single broadcast domain exists between SWA and SWB.
- C. A single collision domain exists between SWA and SWC.
- D. A single broadcast domain exists between SWA and SWC.

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 56

On the interface serial 1/0/1 of RTA,the command "ip address unnumbered interface loopback 0" has been configured. Which following statements are correct? (Two Answers).

- A. The IP address of interface serial 1/0/1 is 10.1.1.1/24
- B. The IP address of interface serial 1/0/1 is 10.1.1.1/32
- C. The route entry 10.1.1.0/24 exists in RTA's routing-table
- D. The route entry 10.1.1.0/24 does not exist in RTA's routing-table

Correct Answer: BD Section: (none) Explanation

Device Configuration

QUESTION 1

Refer to the graphic. The host has a problem establishing a telnet connection with the router attached to interface G0/0/0, Which of the following steps can be used to help the administrator identify the problem? (Two Answers)

- <choice ident="A">
- <choice ident="B">
- <choice ident="C">
- <choice ident="D">
- A. Check whether the host has configured the gateway IP address.
- B. Check whether the switch has configured the gateway IP address.
- C. Use the ping tool to check connectivity between host and router.
- D. Check the telnet server configuration is right on the router.

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 2

Which of the following methods are supported by VRP platform to configure the router? (Select 3 Answers)

- A. Through the Console port
- B. Through Telnet
- C. Through the AUX port
- D. Through FTP

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 3

The administrator wishes to update the configuration file of an AR2200 router using a USB cable. How can this be achieved? (Two Answers)

- A. The administrator should connect the USB cable between the terminal and the mini USB port of the AR2200 router.
- B. The administrator should connect the USB cable between the terminal and the USB port of the AR2200 router.
- C. The AR2200 router cannot support configuration updates through a USB cable.
- D. The administrator should install the mini USB drivers on the terminal after connecting the USB.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 4

The administrator wishes to manage a network through telnet from a user's terminal to a router. How can this be achieved?

- A. A connection should be established between the ethernet port of the terminal and the console port of the router.
- B. A connection should be established between the ethernet port of the terminal and the ethernet port of the router.
- C. A connection should be established between the console port of the terminal and the ethernet port of the router.use console cable connect pc's ethernet port and router's console port.
- D. A connection should be established between the COM port of the terminal and the console port of the router.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 5

Whilst configuring a device, an administrator experiences trouble remembering certain commands. Which of the following will help support the administrator? (Two Answers)

- A. TAB
- B. question mark
- C. ctrl+b
- D. ctrl+c

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 6

<Huawei> system-view

[Huawei] user-interface console 0

[Huawei-ui-console0] user privilege level 15

[Huawei-ui-console0] authentication-mode password

[Huawei-ui-console0] set authentication password cipher huawei2012

[Huawei-ui-console0] quit



http://www.gratisexam.com/

Refer to the configuration output. The administrator configured the device using the commands in the configuration output. Regarding these commands, which statement is false?

- A. The administrator wishes to enable management through the console interface.
- B. Following configuration, the administrator cannot manage the device remotely.
- C. A user that logs-in through the console interface is assigned the highest privilege level.
- D. The password of a user logged in through console is 'cipher huawei2012'

Correct Answer: D Section: (none) Explanation

QUESTION 7

Which of the following is abbreviation of VRP?

- A. Versatile Routine Platform
- B. Virtual Routing Platform
- C. Virtual Routing Plane
- D. Versatile Routing Platform

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 8

Which of the following must be used to establish the configuration environment when a router is powered on for the first time?

- A. SSL
- B. SSH
- C. Console port
- D. Telnet

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 9

Which of the following parameter settings for terminal emulation are correct when configuring a Huawei router through the Console port?

- A. 4800bps, 8 data bits,1 stop bits, odd parity check, and no flow control
- B. 9600bps, 8 data bits, 1 stop bits, no parity check, and no flow control
- C. 9600bps, 8 data bits, 1 stop bits, even parity check, and hardware flow control
- D. 19200bps, 8 data bits, 1 stop bits, no parity check, and no flow control

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 10

Which of the following commands is used to enter the system-view from the user view on a Huawei router?

- A. system-view
- B. enable
- C. configure terminal
- D. interface system

Correct Answer: A Section: (none)

Explanation

Explanation/Reference:

QUESTION 11

On VRP platform, the command lines are classified into four levels in increasing priority: Visit level, Monitoring level, Configuration level, and Management level. At which level, the operator is permitted to configure service but is not permitted to operate the file system?

- A. Visit level
- B. Monitoring level
- C. Configuration level
- D. Management level

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 12

On Huawei VRP platform, which of the following can be used to invoke the history command saved by the command line interface? (Select 2 Answers)

- <choice ident="A">
- <choice ident="B">
- <choice ident="C">
- <choice ident="D">
- A. Up cursor key < >
- B. Left cursor key < >
- C. Ctrl+P
- D. Ctrl+U

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 13

Which of the following commands can be used to view the current configurations on a Huawei router?

- A. display current-configuration
- B. display saved-configuration
- C. view saved-configuration
- D. show startup-configuration

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 14

The administrator wishes to change name of the router. Under which view should the administrator be in order to achieve this?

- A. User-view
- B. System-view
- C. Interface-view
- D. Protocol-view

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 15

<Huawei> system-view

[Huawei]command-privilege level 3 view user save

Refer to the command output. What is the result of the shown command?

- A. The command adjusts the save command of a user to privilege level 3.
- B. The command adjusts the save command in the user view to privilege level 3.
- C. The command adjusts the user view command privilege level to 3, and saves the configuration.
- D. The command adjusts the privilege level of a user to 3, and saves the configuration.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 16

<Huawei>system-view

[Huawei]history-command max-size 20

Refer to the command output. Which statements regarding the shown command are true? (Two answers)

- A. The command is used to adjust the size of the history command buffer
- B. The default value of the history command buffer is 5.
- C. The command should be configured in the user-interface view.
- D. Once configured, commands totalling up to 20 bytes can be saved in the buffer.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 17

An AR2200 router is required to be reconfigured from scratch. Which steps are needed to achieve this? (Two Answers)

- A. Reset the saved configuration
- B. Clear the current configuration
- C. Reboot the AR2200.
- D. Assign the configuration file to be used at next startup.

Correct Answer: AC

Section: (none) Explanation

Explanation/Reference:

QUESTION 18

An administrator has been requested to replace the configuration file of a router in the network. The administrator has been instructed that after logging into the router, he must first permenantly erase the current configuration file config.zip from the system. Which command should he use to achieve this?

- A. delete /force config.zip
- B. delete /unreserved config.zip
- C. reset config.zip
- D. clear config.zip

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 19

Which of the following commands can switch a view from the system view to the user view?

- A. System-view
- B. Router
- C. Quit
- D. User-view

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 20

Which of the following storage devices are supported by Huawei router? (Select 4 Answers)

- A. SDRAM
- B. NVRAM
- C. Flash
- D. Hard Disk
- E. CF Card

Correct Answer: ABCE

Section: (none) Explanation

Explanation/Reference:

QUESTION 21

Which of the following storage devices is used to store the startup configuration files in a router?

- <choice ident="A">
- <choice ident="B">
- <choice ident="C">
- <choice ident="D">

- A. SDRAM
- B. NVRAM
- C. Flash
- D. BootROM

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 22

<Huawei>reset saved-configuration

Warning: The action will delete the saved configuration in the device. The configuration will be erased to reconfigure. Continue? [Y/N]:

Refer to the configuration output. Which of the following statements are true? (Select two answers)

- A. A user should enter 'Y' when wishing to clear the saved configuration file.
- B. The saved-configuration file that the device starts with can be erased.
- C. The saved-configuration will be deleted after typing N
- D. The saved-configuration file will be replaced with the current-configuration.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 23

When a router is powered on, the router reads the configuration file saved in the default save directory to get itself initialized. If the configuration file does not exist in the default save directory, what does the router use to initialize itself?

- A. New configuration file
- B. Initial configuration file
- C. Default parameters
- D. Current configuration file

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 24

<Huawei>display startup

MainBoard:

Startup system software: sd1:/ar2220-v200r003c00spc200.cc Next startup system software: sd1:/ar2220-v200r003c00spc200.cc

Backup system software for next startup: null
Startup saved-configuration file: null
Next startup saved-configuration file: null
Startup license file: null
Next startup license file: null
Startup patch package: null
Next startup patch package: null

Startup voice-files: null
Next startup voice-files: null

Refer to the display output. Which statement is false?

- A. The current configuration file has not been saved.
- B. The current startup system software is ar2220-v200r003c00spc200.cc
- C. The next startup system software cannot be changed.
- D. The next startup system software can be changed by using the "startup system software <startup-software-name>.cc" command.

Correct Answer: C Section: (none) Explanation

DHCP

QUESTION 1

<Huawei>

Warning: Auto-Config is working. Before configuring the device, stop Auto-Config. If you perform configurations when Auto-Config is running, the DHCP, routing, DNS, and VTY configurations will be lost. Do you want to stop Auto-Config? [y/n]:

When an administrator first initializes the router, a warning is displayed. Which statement regarding this warning is correct?

- A. If Auto-Config is required, the administrator should select 'y'
- B. If Auto-Config is not required, the administrator should select 'n', for which subsequent configuration of the DHCP server, routing, DNS server and VTY user configuration is lost
- C. When a device is started for the first time, the Auto-Config function is active.
- D. When a device is started for the first time, the Auto-Config function is inactive.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 2

An AR2200 router in the company network cannot boot. In order to resolve this, the administrator wishes to update the VRP software. What should he/she do?

- A. The administrator should use a console cable to connect the router and host, and directly upgrade the device.
- B. The administrator should use FTP to transfer the VRP software, by configuring the AR2200 router as an FTP client.
- C. The administrator should use DHCP to boot the AR2200, and then use the AR2200 router as a TFTP client to download the VRP software from the server.
- D. The administrator should use the telnet command on the client to remote access the device, and upgrade the VRP software.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 3

<Huawei>

Warning: Auto-Config is working. Before configuring the device, stop Auto-Config. If you perform configurations when Auto-Config is running, the DHCP, routing, DNS, and VTY configurations will be lost. Do you want to stop Auto-Config? [y/n]:

Refer to the output. When the administrator first starts the router, a system notice is displayed, however after rebooting this router, the notice disappeared. What is the reason for this? (Two Answers)

- A. This notice only appears during the very first device startup.
- B. The administrator has configured the device and saved the configuration, causing the notice to disappear.
- C. The administrator selected 'n' and did not save the configuration
- D. The administrator selected 'y' and saved the configuration.

Correct Answer: BD Section: (none)

Explanation

Explanation/Reference:

QUESTION 4

An end system is unable to communicate with a DHCP server following the startup process. Which IP address may be used by the client?

A. 0.0.0.0

B. 127.0.0.1

C. 169.254.2.33

D. 255.255.255.255

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 5

[Huawei]ip pool pool1 Info: It's successful to create an IP address pool.

[Huawei-ip-pool-pool1]network 10.10.10.0 mask 255.255.255.0

[Huawei-ip-pool-pool1]gateway-list 10.10.10.1

Refer to the configuration output. The administrator wishes to configure the DHCP server pool in order to assign an IP address to the customer's terminal device. Which command should be included in the configuration to provide the minimal lease period for IP addresses?

- A. dhcp select relay
- B. lease day 1
- C. lease 24
- D. lease 0

Correct Answer: B Section: (none) Explanation

Explanation/Reference:



http://www.gratisexam.com/

QUESTION 6

A DHCP server has been established in the enterprise network. After the client has obtained an IP address from the DHCP server, the user decided to modify the IP address manually. In what way may this affect the enterprise network? (Two Answers).

- A. The client may experience an IP address conflict.
- B. The client may access the network normally.
- C. The client's interface connection will shutdown.
- D. The client will associate with another DHCP server.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 7

Refer to the graphic. Two switches have been connected as shown and both support STP. The administrator has configured switch A as a DHCP server and set interface VLANIF1 of switch B to obtain an IP address from switch A. A link failure occurs on port interface G0/0/1 of switch B. What action will occur as a result?

- A. The two switches will be unable to communicate.
- B. Switch B will send a DHCP Discovery message to obtain a new IP address.
- C. Swich B will continue to use the IP address obtained from Switch A
- D. Switch B will send a DHCP Release message to release the IP address.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 8

A DHCP server in the enterprise network is being used to allocated IP addresses to hosts. An administrator discovers however that some hosts are obtaining IP addresses outside of the scope of the DHCP server's address pool. What are the possible reasons for this? (Three Answers).

- A. Another DHCP server exists in the network and is allocating IP addresses to hosts that happen to be within a closer proximity than the authorized DHCP server
- B. The hosts were unable to discover a DHCP server and therefore generated their own address in the 169.254.0.0 address range.
- C. The hosts were unable to discover a DHCP server and therefore generated their own address in the 127.254.0.0 address range.
- D. All addresses from the DHCP pool have been assigned

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 9

Router] ip pool pool1

[Router-ip-pool-pool1] network 10.10.10.0 mask 255.255.255.0

[Router-ip-pool-pool1] gateway-list 10.10.10.1

[Router-ip-pool-pool1] quit

[Router] ip pool pool2

[Router-ip-pool-pool2] network 10.20.20.0 mask 255.255.255.0

[Router-ip-pool-pool2] gateway-list 10.20.20.1

[Router-ip-pool-pool2] quit

[Router] interface GigabitEthernet 0/0/1

[Router-GigabitEthernet0/0/1] ip address 10.10.10.1 24

[Router-GigabitEthernet0/0/1] dhcp select global

Refer to the configuration output. Following configuration, a host is connected to the interface Gigabit Ethernet 0/0/1 of the router. Which IP address will the client obtain?

<choice ident="A">

<choice ident="B">

<choice ident="C">
<choice ident="D">

- A. An IP address from network 10.10.10.0/24 will be assigned.
- B. An IP address from network 10.20.20.0/24 will be assigned.
- C. The host will be unable to obtain an IP address.
- D. An IP address may be assigned from either 10.10.10.0/24 or 10.20.20.0/24.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 10

The IP addresses of clients in the network are deployed via a DHCP server. When a host reboots, which message will the host first send to the DHCP server?

- A. DHCP DISCOVER
- **B. DHCP REQUEST**
- C. DHCP OFFER
- D. DHCP ACK

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 11

A DHCP Unique Identifier (DUID) in DHCPv6 can be configured in VRP using which formats? (Two Answers).

- A. DUID-LL
- B. DUID-LLT
- C. DUID-EN
- D. DUID-LLC

Correct Answer: AB Section: (none) Explanation

DOMAIN

QUESTION 1

Which of the following statements about the information contained in a Database Description packet are true? (Select 3 Answers)

- A. A Database Description packet contains all information about each LSA.
- B. A Database Description packet contains only the header of an LSA.
- C. The header of an LSA is the unique identifier of the LSA.
- D. The header of an LSA is only a small portion of all the data of the LSA.

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:

QUESTION 2

What is the default authentication mode for the default admin domain?

- A. None
- B. Local
- C. Radius
- D. 802.1X

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 3

How many domains can be configured on a Huawei router?

A. 30



http://www.gratisexam.com/

- B. 31
- C. 32
- D. 33

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 4

An authenticator router has been configured with two domains named "Area1" and "Area2", following which a user is created with the username "huawei" and the password "hello" for authentication. Which domain does this user belongs to?

<choice ident="A">
<choice ident="B">
<choice ident="C">
<choice ident="D">

- A. Area1 domain
- B. Area2 domain
- C. default domain
- D. default_admin domain

Correct Answer: C Section: (none) Explanation

FRAME RELAY

QUESTION 1

In order to check if the interface serial 1/0/0 is working in either DCE or DTE mode, command () is used.

- A. display mode serial 1/0/0
- B. display controller
- C. display interface serial 1/0/0
- D. display current-config

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 2

How is mapping performed on a DTE device in a Frame Relay network?

- A. The local DLCI number is mapped to a remote IP address.
- B. The local IP address is mapped to a remote DLCI number.
- C. The local DLCI number is mapped to a local IP address.
- D. The remote DLCI number is mapped to a remote IP address.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 3

If Frame Relay implements dynamic address mapping for the PVC, which protocol will be used?

- A. LMI protocol.
- B. ARP protocol.
- C. RARP protocol.
- D. InARP protocol

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 4

Refer to the graphic. Which of the following statements correctly describe the Frame Relay devices? (Two Answers)

- A. RTA is a DTE device.
- B. FRA is a DTE device.
- C. FRB is a DCE device.
- D. The interface on RTA is a DCE interface

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 5

Refer to the graphic. RTA and RTB are connected over a Frame Relay network using a DLCI, as shown. Static mapping is required on RTA. Which of the following commands will achieve this?

- A. [RTA-Serial1/0/1]fr map ip 172.16.1.1 30
- B. [RTA-Serial1/0/1]fr map ip 172.16.1.1 31
- C. [RTA-Serial1/0/1]fr map ip 172.16.2.1 30
- D. [RTA-Serial1/0/1]fr map ip 172.16.2.1 31

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 6

Refer to the graphic. RTA is a DTE device connected to a Frame Relay switch, and uses dynamic address mapping to establish the PVC. With regards to the configuration, which of the following commands are not necessary? (Two Answers).



http://www.gratisexam.com/

- A. [RTA-Serial1/0/1]ip address 172.16.1.1 24
- B. [RTA-Serial1/0/1]link-protocol FR
- C. [RTA-Serial1/0/1]fr interface-type dte
- D. [RTA-Serial1/0/1]fr inarp

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 7

Which command should be used to check the mapping between protocol addresses and frame relay addresses?

- A. display fr interface
- B. display fr map-info
- C. display fr inarp-info
- D. display interface brief

Correct Answer: B Section: (none) Explanation

QUESTION 8

Which of the following protocols is used in Frame Relay to map the address to DLCI dynamically?

- <choice ident="A">
- <choice ident="B">
- <choice ident="C">
- <choice ident="D">
- A. ARP protocol
- B. RARP protocol
- C. InARP protocol
- D. Map protocol

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 9

Which of the following parameters must be specified when configuring static mapping for Frame Relay network? (Select 2 Answers)

- A. Local DLCI
- B. Remote DLCI
- C. Local network layer protocol address
- D. Remote network layer protocol address

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 10

Which of the following regarding Frame Relay DLCI are correct? (Select 3 Answers)

- A. DLCI is locally significant
- B. DLCI is allocated by DTE
- C. The range of DLCI value that can be used is from 16-1007
- D. The same DLCI can be configured on different physical interfaces

Correct Answer: ACD Section: (none) Explanation

Explanation/Reference:

QUESTION 11

Which of the following commands is used to enable dynamic address mapping protocol in the interface encapsulated with Frame Relay?

- A. fr inarp
- B. fr reverse-arp
- C. inverse-arp
- D. reverse-arp

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 12

What is the meaning of 200 in the command "fr map ip 10.1.1.2 200"?

- A. remote logical channel ID
- B. local DLCI
- C. remote interface ID
- D. remote node ID

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 13

Refer to the graphic.RTA and RTB connect to a Frame Relay switch and use dynamic address mapping. The command "fr map ip 10.0.1.1 32" is then configured on RTB, without using the undo inarp command. What will occur as a result? (Two Answers).

- A. RTB will be unable to communicate with RTA
- B. 10.0.1.1 will still be mapped to DLCI 31 on RTB
- C. 10.0.1.1 will still be mapped to DLCI 32 on RTB
- D. DLCI 32 will be activated on RTB

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 14

Refer to the graphic. RTA and RTB are connected to the same Frame Relay switch and use same DLCI number, which following is correct? (Two Answers).

- A. RTA and RTB must be associated with the same PVC
- B. RTA and RTB can be associated with different PVC's
- C. The DLCI on the different physical interfaces can be the same
- D. The DLCI on the different physical interfaces cannot be the same

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 15

Which of the following commands can be used to display mapping relationship between network address and DLCI?

- A. display fr interface
- B. display fr
- C. display fr map-info
- D. display fr brief

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 16

Which of following may be the reasons that cause Frame Relay PVC to work abnormally? (Select 3 Answers)

- A. Same DLCI number is configured on the same router
- B. LMI type mismatch
- C. Frame Relay encapsulation type mismatch
- D. Incorrect configuration of the DLCI number

Correct Answer: BCD Section: (none) Explanation

FTP

QUESTION 1

An administrator wishes to update the VRP software of company's AR2200 router. How can this be achieved? (Three Answers)

- A. The administrator can use FTP to transfer the VRP software, with the AR2200 router as the FTP client.
- B. The administrator can use FTP to transfer the VRP software, with the AR2200 router as the FTP server.
- C. The administrator can use TFTP to transfer the VRP software, with the AR2200 router as the TFTP server.
- D. The administrator can use TFTP to transfer the VRP software, with the AR2200 router as the TFTP client.

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 2

An administrator wishes to implement new features in the network, but the VRP version of one AR2200 router is out of date. The administrator needs to upgrade the VRP software. Which of the following options regarding file transfer is false?

- A. The AR2200 router can function as a TFTP client to support the upgrade.
- B. The AR2200 router can function as the TFTP server to support the upgrade.
- C. The AR2200 router can function as the FTP server to support the upgrade.
- D. The AR2200 router can function as an FTP client to support the upgrade.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 3

FTP and TFTP can be used to update the system file on Huawei routers. Which of the following statements are correct? (Select 3 Answers)

<choice ident="A">

<choice ident="B">

<choice ident="C">

<choice ident="D">

- A. Huawei router can be configured as FTP Client
- B. Huawei router can be configured as FTP Server
- C. Huawei router can be configured as TFTP Client
- D. Huawei router can be configured as TFTP Server

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 4

An administrator discovered he/she was unable to use TFTP to transfer files to the router. Which of the following describes the likely reason for this?



http://www.gratisexam.com/

- A. The TFTP service had been disabled on the router.
- B. TCP port 69 of the server had been blocked.
- C. UDP port 69 of the server had been blocked.
- D. The username and password had been modified.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 5

FTP may be used to upgrade a router's VRP image. Which of the following transmission modes should be used to achieve this?

- A. binary mode
- B. ASCII mode
- C. byte mode
- D. letter mode

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 6

A client failed to transfer a file to the FTP server, but found the IP connectivity was without problem. The client assumed that the problem was with the port configuration. The blocking of which ports would likely cause this problem? (Two Answers)

- A. 21
- B. 80
- C. 20
- D. 50649

Correct Answer: AC Section: (none) Explanation

GRE

QUESTION 1

Refer to the graphic. RTA and RTB have established a GRE tunnel, but only RTA has enabled the keepalive function. When RTB receive a keepalive message from RTA, how will RTB respond?

- A. RTB will discard the keepalive message.
- B. RTB willl record receipt of the keepalive message but won't reply
- C. RTB will send a keepalive in response.
- D. RTB will send a keepalive reply and begin to actively send keepalive messages.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 2

Refer to the graphic. Two hosts communicate through a GRE tunnel. When the GRE tunnel is up, the network administrator configures a static route on RTA to route packets to Host B. Which of the following commands will achieve this?



http://www.gratisexam.com/

- A. ip route-static 10.1.2.0 24 GigabitEthernet0/0/1
- B. ip route-static 10.1.2.0 24 200.2.2.1
- C. ip route-static 10.1.2.0 24 200.1.1.1
- D. ip route-static 10.1.2.0 24 tunnel 0/0/1

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 3

When using VRP, which of the following commands is used to configure the data link layer encapsulation type of a serial interface as HDLC?

- A. encapsulation hdlc
- B. link-protocol hdlc
- C. hdlc enable
- D. link-protocol ppp

Correct Answer: B Section: (none) Explanation

IPSEC

QUESTION 1

Refer to the graphic. Packet encapsulation in the IPsec architecture is performed as shown. Which IPsec mode is being used to encapsulate the packet?

- A. normal mode
- B. transport mode
- C. tunnel mode
- D. this encapsulation is wrong

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 2

Refer to the graphic. IPsec VPN uses ESP to encrypt which fields?

- A. TCP, Data and ESP Trailer
- B. ESP, TCP and Data
- C. ESP, TCP, Data and ESP Trailer
- D. ESP, TCP, Data, ESP Trailer and ESP Auth

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 3

Refer to the graphic. In order to improve security, the two hosts use IPsec VPN to transmit data. Which IPsec mode and protocol can be used to hide the host's IP address? (Two Answers).

- A. AH
- B. transport mode
- C. tunnel mode
- D. ESP

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 4

If AH and ESP are both required to protect data streams between IPsec peers, how many Security Associations (SA) are required in total?



http://www.gratisexam.com/

- A. 1
- B. 2
- C. 3
- D. 4

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 5

Refer to the graphic. The data is transmitted using IPsec tunnel mode. The fields of which headers will be authenticated?

- A. TCP and Data
- B. Origin IP, TCP and Data
- C. AH, Origin IP, TCP and Data
- D. The fields of all headers

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 6

Two routers establish an IPsec tunnel, which of the following does not need to be the same on both peering devices?

- A. Encapsulation mode
- B. Transform mode
- C. Proposal name
- D. authentication algorithm

Correct Answer: C Section: (none) Explanation

IPv6

QUESTION 1

Which of the following formats represent an accurate condensing of the IPv6 address 2031:0000:720C:0000:0000:09E0:839A:130B? (Two Answers).

A. 2031:0:720C:0:0:9E0:839A:130BB. 2031:0:720C:0:0:9E:839A:130BC. 2031::720C::9E0:839A:130BD. 2031:0:720C::9E0:839A:130B

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 2

Which of the following IPv6 addresses can be configured on a router's interface? (Two Answers).

A. fe80:13dc::1/64B. ff00:8a3c::9b/64

C. ::1/128

D. 2001:12e3:1b02::21/64

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 3

The IPv6 address achitecture does not include which of the following address types?

- A. unicast
- B. multicast
- C. broadcast
- D. anycast

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 4

Which of the following descriptions regarding IPv6 addresses are correct? (Two Answers)

- A. IPv6 addresses are 64 bits in length.
- B. IPv6 addresses are 128 bits in length.
- C. IPv6 extension headers are processed in order.
- D. IPv6 extension headers are processed randomly.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:



http://www.gratisexam.com/

QUESTION 5

Interface G0/0/1 on RTA contains a MAC address of 00e0-fc03-aa73 and is configured with the IPv6 address 2001::2E0:FCFF:FE03:AA73. Which method is most likely to have been used to configure the interface IPv6 address?

- A. DHCPv6
- B. Auto-link
- C. ARP
- D. EUI-64

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 6

In a small network suppporting IPv6, a network administrator wishes implement RIPng. Which of the following commands should be used to enable this protocol?

- A. [RTA-GigabitEthernet0/0/0]ripng 1 enable
- B. [RTA]ripng 1 enable
- C. <RTA>ripng 1 enable
- D. [RTA-ripng-1]ripng 1 enable

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 7

In a network supporting IPv6, OSPF no longer supports which feature?

- A. multiple areas
- B. Router-ID
- C. authentication
- D. multicast updates

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 8

Refer to the graphic. RTA and RTB have established an IPv6 network for which an IPv6 address has been configured only on the G0/0/1 interface. RTA is unable to ping RTB. The administrator then configures v3 along with a router-id on both routers, and enables OSPFv3 on G0/0/1 of both RTA and RTB. Which of the following statements are correct? (Two Answers).

- A. RTA and RTB can establish an OSPFv3 neighbor relationship.
- B. RTA and RTB cannot establish an OSPFv3 neighbor relationship.
- C. RTA can ping RTB.
- D. RTA cannot ping RTB.

Correct Answer: AD Section: (none) Explanation

LINK AGGREGATION

QUESTION 1

The network administrator has decided to configure link aggregation in the enterprise network. Which of the following represent advantages of link aggregation? (Three Answers)

- A. Load balancing.
- B. Improved bandwidth.
- C. Enhanced reliability.
- D. Improved security.

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 2

In port aggregation, "multiple" ports are aggregated to form a port aggregation group so that all the member ports in the group share the outgoing/incoming load. At which layer is port aggregation implemented?

- A. Physical Layer
- B. Data Link Layer
- C. Network Layer
- D. Transport Layer

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 3

What benefits does port aggregation yield? (Select 3 Answers)

- A. Improves link bandwidth
- B. Implements load sharing
- C. Improves network reliability
- D. Facilitates data copy for analysis

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 4

Refer to the graphic. The network administrator wishes to aggregate the two links as member interfaces of Eth-trunk 1. Which statement is correct?

- A. The interfaces will be aggregated with load balancing.
- B. The interfaces will be aggregated, but only interface GE0/0/1 will send data flow.
- C. The interfaces will be aggregated, but the Eth-trunk will not be active.
- D. The interfaces cannot be aggregated.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 5

What is the maximum number of member interfaces supported by a single Eth-Trunk?



http://www.gratisexam.com/

- A. 6.
- B. 8.
- C. 10
- D. 12.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 6

The Eth-Trunk frame forwarding mechanism used to prevent changes in the data sequence forwards frames based on which of the following parameters?

- A. The same source or destination IP address
- B. The same source or destination MAC address.
- C. The same protocol type.
- D. The same source or destination port number.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 7

In Layer 2 mode, the transmission rate of an Eth-Trunk interface is determined by which of the following?

- A. Maximum number of Up member links
- B. Minimum number of Up member links
- C. Number of Up member interfaces
- D. Number of interfaces.

Correct Answer: AC Section: (none) Explanation

QUESTION 8

The network administrator wishes to forward data over an Eth-trunk, however associated member interfaces operate at different rates. In terms of the resulting behavior, which of the following is true?

- A. The two switches will not be able to communicate.
- B. The higher rate member interfaces may incur packet loss.
- C. The Eth-Trunk will work normally.
- D. The lower rate member interfaces may incur packet loss.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 9

The network administrator attempts to add interface G0/0/1 on Switch A to Eth-trunk 1, however the command fails. Which of the following may cause this?

- A. The interface is operating in half-duplex mode.
- B. The interface has been shutdown.
- C. The interface is already associated with another Eth-trunk.
- D. The interface is an access port.

Correct Answer: CD Section: (none) Explanation

NAT

QUESTION 1

A network requires a solution to allow 50 private IP addresses to be translated, however only a single public address is available for use. Which translation method can be used to support this requirement?

- A. Static NAT
- B. Dynamic NAT
- C. Easy-IP
- D. NAPT

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 2

NAPT allows for multiple internal addresses to be mapped to a single public address. How does NAT distinguish between the different private addresses when mapping to the same public address

- A. The source MAC address is used.
- B. The destination MAC address is used.
- C. The source port number is used.
- D. The destination port number is used.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 3

Refer to the graphic. Host A is located in a private network. It is required that Host A not only be capable of routing traffic over the public network, but also that public users are able to actively communicate with Host A. Which NAT translation method should be configured on the gateway?

- A. Static NAT
- B. Dynamic NAT
- C. Easy-IP
- D. NAPT

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 4

Refer to the graphic. In the private network, RTA dynamically assigns a public address from the address pool to hosts without port translation. Host C wishes to access the public network while pool addresses are assigned to Host A and Host B. What will occur as a result?

- A. The first public address will be allocated to Host C, and Host A will be forced offline.
- B. The last public address will be allocated to Host C, and Host B will be forced offline.
- C. Host C will be unable to forward traffic over the public network.

D. All hosts will have access to the public network through pool address swapping.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 5

A web server in a private network is required to provide HTTP services to public users. The network administrator is required to configure NAT on RTA. Which configuration should be used?

- A. [RTA-Serial1/0/1]nat server protocol tcp global 202.10.10.1 www inside 192.168.1.1 8080
- B. [RTA-Serial0/0/1]nat server protocol tcp global 192.168.1.1 www inside 202.10.10.1 8080
- C. [RTA-Gigabitethernet0/0/1]nat server protocol tcp global 202.10.10.1 www inside 192.168.1.1 8080
- D. [RTA- Gigabitethernet0/0/1]nat server protocol tcp global 192.168.1.1 www inside 202.10.10.1 8080

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 6

The network administrator needs to configure static NAT on RTA, in order to allow Host A to communicate with Host C. Which command is correct?



http://www.gratisexam.com/

- A. [RTA-Serial1/0/1]nat outbound 200.1.1.10
- B. [RTA-Serial1/0/1]nat static global 200.1.1.10 inside 192.168.1.0
- C. [RTA-Serial1/0/1]nat static global 192.168.1.1 inside 200.1.1.10
- D. [RTA-Serial1/0/1]nat static global 200.1.1.10 inside 192.168.1.1

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 7

[RTA-GigabitEthernet0/0/0]nat outbound 2000 address-group 1

Refer to the configuration output. What does the value "2000" refer to?

- A. It represents the ACL number.
- B. It represents the NAT number.
- C. It represents the translated port number .
- D. It represents the number of bytes that can be translated before the address is returned to the public address pool.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 8

NAPT uses the same public address but different port numbers to translate private addresses. Which statement regarding the port number is correct?

- A. It is necessary to configure port number mapping manually.
- B. It is only necessary to configure the port number range.
- C. It is not necessary to configure port numbers.
- D. An access control list is needed to assign port numbers.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 9

A configured internal host of a private network wishes to access the internet. What must be configured on the enterprise network's edge router in order to achieve this? (Two Answers)

- A. NAT EasylP
- B. DHCP
- C. BGP
- D. Default route

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 10

Which of the following statements are correct about NAT? (Select 3 Answers)

- A. NAT is the abbreviation for "Network Address Translation"
- B. NAT is used for translation between private and public network addresss.
- C. When hosts inside a private network access the outside network, NAT is not required.
- D. NAT provides an effective way to solve the problem of insufficient IP addresses.

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 11

Which of the following technologies can allow a host with IP address 10.0.0.1 to access the internet?

- A. Static route
- B. Dynamic route
- C. Route import

D. NAT

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 12

Which of the following items can be translated by NAPT?

- A. MAC address + port number
- B. IP address + port number
- C. Only MAC address
- D. Only IP address

Correct Answer: B Section: (none) Explanation

OSPF

QUESTION 1

Which of the following statements about a designated port working in RIPv2 multicast mode are true? (Select 3 Answers)

- A. The port receives only RIPv2 multicast packets.
- B. The port does not receive RIPv1 broadcast packets.
- C. The port does not receive RIPv2 broadcast packets.
- D. The port receives only RIPv1 multicast packets.

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 2

Which of the following statements regarding the router ID in OSPF are incorrect? (Select 3 Answers)

- A. The router IDs of OSPF routers in the same area must be the same, but can be different in different areas.
- B. The router ID must be the IP address of an OSPF router interface.
- C. The router ID must be configured manually.
- D. A router running OSPF must have a router ID for it to operate properly.

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 3

Which of the following statements regarding Designated Routers in OSPF are correct? (Select 3 Answers)

- A. DR is elected by all the routers in the same network segment.
- B. If the priorities of two routers are different, the router with the lower priority will be elected as DR.
- C. If the priorities of two routers are equal, the router with the higher Router ID will be elected as DR.
- D. DR and BDR must be adjacent.

Correct Answer: ACD Section: (none) Explanation

Explanation/Reference:

QUESTION 4

On the VRP platform, which of the following commands is used to configure the Router ID of a router as 1.1.1.1?

- A. <Huawei>router id 1.1.1.1
- B. [Huawei]router id 1.1.1.1
- C. [Huawei]router-id 1.1.1.1
- D. [Huawei]router id 1.1.1.1 255.255.255.255

Correct Answer: B

Section: (none) Explanation

Explanation/Reference:

QUESTION 5

Which of the following OSPF versions is specific to IPv6?

- A. OSPFv1
- B. OSPFv2
- C. OSPFv3
- D. OSPFv4

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 6

The administrator wishes to configure OSPF on a router in the network, however the router has no loopback interface. Which value will be used as the router ID?

- A. The lowest IP address of the router's active interfaces.
- B. The highest IP address of the router's active interfaces.



http://www.gratisexam.com/

- C. The IP address of the management interface
- D. The priority value of the router.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 7

An administrator of a company supporting a large enterprise network wishes to implement OSPF on the network as opposed to RIP. Which of the following points should the administrator use to support his reasoning for this change? (Three Answers)

- A. OSPF has no hop count limitation
- B. OSPF has a lower routing update overhead
- C. OSPF has a simpler configuration.
- D. OSPF supports faster convergence.

Correct Answer: ABD Section: (none) Explanation

QUESTION 8

Which of the following statements regarding single area OSPF are correct? (Three Answers)

- A. An IP address needs to be configured on a loopback interface of each router before configuring an OSPF area.
- B. The value of an area can be from 0.0.0.0 to 255.255.255.255.
- C. A single area can be configured using any supported area number.
- D. All of the links of the network need to be advertised in Area 0.

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:

QUESTION 9

10.0.1.0/24 O ASE 150 2 D 10.0.23.3 Serial2/0/0

Refer to the display output. Which of the following statements regarding route shown are true? (Two Answers)

- A. The address 10.0.23.3 has been configured on the peer's serial 2/0/0 interface.
- B. The route preference has been changed by the adminstrator.
- C. The metric for the route 10.0.1.0 indicates that two hops are needed.
- D. The route has been learned via the OSPF protocol.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 10

Which of the following statements regarding link-state database and routing-table of a "single" OSPF area are correct? (Select 2 Answers)

- A. The link-state databases that all routers build are identical.
- B. The link-state databases that all routers build are different.
- C. The routing-tables that all routers calculate are different.
- D. The routing-tables that all routers calculate are identical.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 11

Which of the following steps are necessary to configure OSPF on a Huawei router? (Select 3 Answers)

- A. Configuration of a router ID
- B. Enabling of an OSPF process
- C. Specifying an OSPF area
- D. Configuration of the network segments within each area

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:

QUESTION 12

Which of the following statements regarding the DR in an OSPF network are correct? (Select 2 Answers)

- A. There must be at least one DR in an OSPF area.
- B. A DR must be elected among the routers through the negotiations that are defined by OSPF protocol.
- C. Only the router with highest priority will be elected as DR.
- D. Only NBMA or Broadcast networks need to elect DR

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 13

Which of the following VRP commands can be used to enter area 0 view? (Select 2 Answers)

- A. [Huawei]ospf area 0
- B. [Huawei-ospf-1]area 0
- C. [Huawei-ospf-1]area 0.0.0.0
- D. [Huawei-ospf-1]area 0 enable

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 14

Which of the following commands is used to display the OSPF neighbor relationship establishment?

- A. display ospf neighbor
- B. display ospf brief
- C. display ospf peer
- D. display ospf interface

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 15

With what kind of routers does a DRother router exchange link state information and route information? (Select 2 Answers)

- A. DR
- B. BDR
- C. DRother

D. All OSPF neighbors

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 16

An OSPF area is a collection of a group of routers and networks. OSPF defines that routers that have the same () belong to the same OSPF area.

- A. neighbors
- B. LSDB
- C. LSA
- D. adjacency

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 17

Which of the following statements about router IDs are true? (Select 2 Answers)

- A. The routers contained in the same LSDB have the same router ID.
- B. Each router in an OSPF network must have a unique router ID.
- C. Two routers in different OSPF areas can have the same router ID.
- D. A router ID is expressed in a 32-bit dotted decimal format.

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 18

OSPF allows for "multiple" processes. By default, OSPF selects a process whose number is ().

- A. 0
- B. 1
- C. 10
- D. 100

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 19

In a network supporting IPv6, OSPF no longer supports which feature?

- A. multiple areas
- B. Router-ID

- C. authentication
- D. multicast updates

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 20

Two routers are configured with OSPFv3. OSPFv3 is enabled on all interfaces of each router. Which of the following is true in the event that the network administrator does not configure a Router-ID?

- A. The IP address of the loopback 0 interface will be used as the router ID
- B. The IP address of the loopback 1 interface will be used as the router ID
- C. The IP address of interface G0/0/0 will be used as the router ID
- D. No router ID will be assigned to the router.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 21

Destination/Mask protocol pre Cost Nexthop Interface 9.0.0.0/8 OSPF 10 50 1.1.1.1 Serial 1/0/0 9.1.0.0/16 RIP 100 5 2.2.2.2 Ethernet 0/0/1

Refer to the graphic. Which of the following statements is correct when this router forwards the packet to the destination host 9.1.4.5?

- A. The router selects the first entry to match the destination address of the packet because the preference of OSPF is higher than the preference of RIP.
- B. The router selects the second entry to match the destination address of the packet because the cost of RIP is lower than that of OSPF.
- C. The router selects the second entry to match the destination address of the packet because the outgoing interface is an Ethernet interface. The forwarding speed of an Ethernet interface is faster than the forwarding speed of a serial interface
- D. The router selects the second entry to match the destination address of the packet because the router will match the most specific address.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 22

According to the default value of route preference on the VRP platform, which of the following represent the correct sequence for direct route, static route, RIP and OSPF if they are listed from high preference to low preference?

- A. Direct, Static, RIP, OSPF
- B. Direct, OSPF, Static, RIP
- C. Direct, OSPF, RIP, Static
- D. Direct, RIP, Static, OSPF

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 23

A router has learned two routes for the same network with the same prefix. One route has been learned via OSPF with a metric of 4882, while the other route has been learned via RIPv2 with a metric of 4. Which route(s) will be found in the routing table?

- A. The RIPv2 route.
- B. The OSPF and RIPv2 routes.
- C. The OSPF route.
- D. Neither of these routes will be found in the routing table.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 24

Assume that the router has learnt the best route to the same destination by using RIP, OSPF and Static Route respectively. By default, the Huawei router will select the route learnt via () as the best route.

- A. RIP
- B. OSPF
- C. RIPv2
- D. Static route

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 25

After checking the OSPF neighbor state, the administrator discovers that the router has established a TWO-WAY state with the peering router. What can be understood from this information? (Two Answers)

- A. The routers are configured using the same process ID
- B. The routers are configured using the same area ID
- C. The routers are configured using wrong router ID
- D. The routers are considered DROthers in a broadcast network

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 26

Refer to the graphic. An administrator has configured OSPF on the two routers, following which he then implements the command silent-interface s0/0/1 on RTA. What effect will this command have on the

network? (Two Answers)

- A. The link information advertised by RTB will be maintained in the Link State Database of RTA.
- B. The OSPF neighbor relationship will fail between two routers.
- C. The configuration will not affect the OSPF neighbor relationship between the two routers.
- D. The link information advertised by RTB will no longer be maintained in the Link State Database of RTA.

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 27

Refer to the graphic. Which statements correctly explains the forwarding behavior between RTA and RTE? (Two Answers)

- A. When the network uses OSPF, data will be forwarded along the path via S1/0/0
- B. When the network uses RIPv2, data will be forwarded along the path via S1/0/0.
- C. When the network uses OSPF, data will be forwarded along the path from via E0/0/1.
- D. When the network uses RIPv2, data will be forwarded along the path via S2/0/0.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 28

What functions does a Hello packet of OSPF implement? (Select 2 Answers)

- A. Neighbor discovery
- B. Deletion of unreachable neighbors.
- C. Maintaining of neighbor relationships.
- D. Negotiation of parameters among adjacent ports.

Correct Answer: AC Section: (none) Explanation

PPP

QUESTION 1

Refer to the graphic. The link between RTA and RTB is encapsulated using PPP. The IP addresses of serial 1/0/1 of RTA and serial 1/0/1 of RTB are in different network segments. Which following is correct? (Two Answers).

- A. RTA can ping 10.1.1.2 successfully
- B. RTA cannot ping 10.1.1.2
- C. The route entry 10.1.1.0/24 exists in the routing-table of RTA
- D. The route entry 10.1.1.2/32 exists in the routing-table of RTA

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 2

Two routers are connected through serial interfaces and support PPP encapsulation. Which parameters must be negotiated to establish the PPP connection? (Three Answers).

- A. MRU
- B. Authentication password
- C. Magic-Number
- D. IP address

Correct Answer: ACD Section: (none) Explanation

Explanation/Reference:

QUESTION 3

What are the three protocol components defined by PPP? (Three Answers).

- A. Data encapsulation.
- B. LCP
- C. NCP
- D. IPCP

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 4

Two routers are connected via serial interfaces, for which the link-protocol is PPP. The network administrator wishes to configure PPP authentication to improve security on this link. Which PPP authentication method provides a more secure solution?

- A. CHAP
- B. PAP
- C. MD5
- D. SSH

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 5

If PPP authentication fails, which type of packet will be sent to the authenticated peer by the authenticator?

- A. Authenticate-Ack
- B. Authenticate-Nak
- C. Authenticate-Reject
- D. Authenticate-Reply

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 6

Two routers are connected via serial interfaces and the link-protocol is PPP, but the MRU of two serial interface's are different, in PPP LCP negotiated stage, what will happen?

- A. LCP negotiation will fail
- B. Negotiation will use the smaller value
- C. Negotiation will use the larger value
- D. Negotiation will use 1500

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 7

PPP is more secure than HDLC because PPP supports authentication protocols such as (). (Select 2 Answers)

- A. PAP
- B. MD5
- C. CHAP
- D. SSH

Correct Answer: AC Section: (none) Explanation



http://www.gratisexam.com/

QUESTION 8

When both ends running PPP protocol detect that the physical link is active, the link state will transit from dead to establish. Which of the following protocols is used to negotiate the link parameters during this phase?

- A. IP
- B. DHCP
- C. LCP
- D. NCP

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 9

A serial interface of a Huawei router currently using HDLC needs to assign PPP as the encapsulation protocol. Which of the following commands is required to be configured at the serial interface view?

- A. link-protocol ppp
- B. encapsulation ppp
- C. enable ppp
- D. address ppp

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 10

When using VRP, which of the following commands is used to configure the PPP authentication method as PAP?

- A. ppp pap
- B. ppp authentication-pap
- C. ppp authentication-mode pap
- D. ppp pap-authentication

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 11

When configuring the PPP authentication method as PAP, which of the following operations are

necessary? (Select 3 Answers)

- A. Add the user name and password of the authenticated party to the local user list
- B. Configure the encapsulation type of the interface connected to the peer as PPP.
- C. Configure PPP authentication method as CHAP
- D. On the authenticated party end, configure the user name and password that are sent to authenticator

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 12

In the PPP protocol, which of the following encryption algorithms is used by CHAP?

- A. DES
- B. MD5
- C. AES
- D. None

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 13

What is the function of the "ip address ppp-negotiate" command?

- A. Enables the function of requesting for an IP address from the peer device.
- B. Enables the function of accepting the request for an IP address from the remote device.
- C. Enables the function of statically allocating IP addresses to the peer.
- D. None of the above

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 14

Two routers have established a point-to-point network using PPP. The administrator has configured the routers to run OSPF in the same area with the same router ID, what will behavior will occur as a result of the configuration?

- A. The routers will build a neighbor relationship even though both routers are using the same router ID.
- B. VRP will notify of a router ID conflict between the two routers.
- C. The routers will build an adjacency even though both routers are using the same router ID.
- D. The routers will not send hello packets to each other because they are using the same router ID.

Correct Answer: B Section: (none) Explanation

PPPoE

QUESTION 1

The PPPoE session establishment process can be divided into which stages? (Two Answers).

- A. Discovery stage
- B. DHCP stage
- C. PPPoE Session stage
- D. PPP connecting stage.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 2

To establish multiple PPP point-to-point connections in the Ethernet network, a PPPoE server establishes connections with multiple PPPoE clients on one Ethernet port. How does PPPoE differentiate between each connection?

- A. MAC address.
- B. IP address and MAC address
- C. MAC address and ppp-id
- D. MAC address and session-id

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 3

When configuring a router as a PPPoE client, which configuration is not necessary?

- A. Configuration of the dialer-rule
- B. Configuration of the dialer interface
- C. Configuration of an IP address on the dialer interface
- D. Configuration of a password on the dialer interface

Correct Answer: C Section: (none) Explanation

Explanation/Reference:



http://www.gratisexam.com/

QUESTION 4

Refer to the graphic. RTA is a PPPoE client, and sends PADI packets to Server A. Which distribution method is used for sending PADI packets?

- A. unicast
- B. multicast
- C. broadcast
- D. anycast

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 5

Refer to the graphic. RTA is a PPPoE client, and following transmission of PADI, Server A responds with PADO packets to RTA. Which distribution method is used for sending PADO packets?

- A. unicast
- B. multicast
- C. broadcast
- D. anycast

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 6

In the PPPoE discovery stage, the PPPoE server assigns a session-id to the PPPoE client in which packet?

- A. PADI
- B. PADO
- C. PADR
- D. PADS

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 7

Which command can be used to check the PPPoE client session status?

- A. display ip interface brief
- B. display current-configuration
- C. display pppoe-client session packet
- D. display pppoe-client session summary

Correct Answer: D Section: (none) Explanation

RIP

QUESTION 1

[Huawei]rip 1

[Huawei-rip-1]version 2

Refer to the command output. An administrator wishes to configure RIP. Which other command needs to configured for RIP routes to be advertised?

- A. import-route GigabitEthernet 0/0/1
- B. network 192.168.1.0 0.0.0.255
- C. network GigabitEthernet 0/0/1
- D. network 192.168.1.0

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 2

Refer to the graphic. RTA and RTB are running RIPv1. RTA has advertised 10.0.0.0 and 192.168.1.0 to the RIP network. Which routes will exist in the IP routing table of RTB? (Two Answers)

- A. 10.0.0.0/8
- B. 192.168.1.1/32
- C. 10.1.12.1/32
- D. 192.168.1.0/24

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 3

Refer to the graphic. Two peering routers are running RIP. RTA is using RIPv1 to advertise its routes, while RTB is using RIPv2. What effect will this have on learned routes?

- A. RTA and RTB will both learn the routes advertised by RIP.
- B. RTA will learn the RIP route advertised by RTB, however RTB is unable to learn the route advertised by RTA.
- C. RTB will learn the RIP route advertised by RTA, however RTA is unable to learn the route advertised by RTB.
- D. Neither RTA nor RTB are able to learn the RIP routes advertised by the peer.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 4

Refer to the graphic. Two peering routers are running RIP. RTA is using RIPv1 to advertise its routes, while RTB is using RIPv2 to advertise the route 1.1.1.1/32. How will the route 1.1.1.1/32 appear in the IP routing table of RTA?

- A. This route will not appear in the IP routing table of RTA.
- B. This route will appear in the IP routing table of RTA as 1.0.0.0/8.
- C. This route will appear in the IP routing table of RTA as 1.0.0.0/24.
- D. This route will appear in the IP routing table of RTA as 1.0.0.0/32.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 5

Refer to the graphic. Two peering routers are running RIP. RTA is using RIPv2 to advertise its routes, while RTB is using RIPv1 to advertise the route 1.1.1.1/32. The administrator configures "RIP version 2 multicast" for interface G0/0/1 of RTB. How will the route 1.1.1.1/32 appear in the the IP routing table of RTA?

- A. This route will not appear in the IP routing table of RTA.
- B. This route will appear in the IP routing table of RTA as 1.0.0.0/8.
- C. This route will appear in the IP routing table of RTA as 1.0.0.0/24.
- D. This route will appear in the IP routing table of RTA as 1.0.0.0/32.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 6

A RIP router receives the routing update information from its neighbor. Which of the following statements regarding routing update are correct? (Select 3 Answers)

- A. The received route that is not in the routing table will be added only when its hop count value is less than 16.
- B. The received route that already exists in the routing table will be updated only when the next hop is the router's neighbor and the cost value is smaller.
- C. The received route that already exists in the routing table will be updated only when the next hop is not the router's neighbor and the cost value is smaller.
- D. The received route that already exists in the routing table will be updated only when the next hop is the router's neighbor and the cost value has been changed.

Correct Answer: ACD Section: (none) Explanation

Explanation/Reference:

QUESTION 7

Which of the following commands is used to display the current running state and configuration of RIP?

- A. display protocol rip
- B. show rip
- C. display rip
- D. display this rip

Correct Answer: C Section: (none)

Explanation

Explanation/Reference:

QUESTION 8

A user can view the information for the RIP protocol on a router. What does "Age time" in the returned result of the command mean?

- A. The interval of updating an RIP packet
- B. The aging time of an RIP route
- C. The suppression time of an RIP route
- D. The time spent on switching between RIP routes

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 9

After a command for displaying RIP route information is entered on a router, peer 192.168.1.2 on Serial1/0/0 is displayed in the returned result. What does 192.168.1.2 stand for?

- A. Address of a RIP neighbor
- B. Address of the port with the RIP protocol enabled
- C. Next hop address of the RIP route
- D. Transmission address of the RIP protocol

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 10

Refer to the grapic. An administrator has configured RIPv2 on the two routers, following which he implements the command silent-interface s0/0/1 on RTA. What effect will this command have on the network? (Two Answers)

- A. RTA will continue to learn routes from RTB
- B. RTB will continue to learn routes from RTA
- C. RTA will have no neighbor relationship with RTB
- D. RTB will have no adjacency relationship with RTA

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 11

Refer to the graphic. R1,R2 and R3 are running RIPv1. R1 and R3 both advertise 172.16.0.0 to the RIP network. How will this affect R2?

- A. R2 will not have a route to the networks 172.16.1.0/24 and 172.16.2.0/24
- B. R2 will only have a route to 172.16.1.0/24

- C. R2 will only have a route to 172.16.2.0/24
- D. R2 will have a route to both networks 172.16.1.0/24 and 172.16.2.0/24, but some packets for these destinations will be lost.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 12

<R2>debugging rip 1

Sep 13 2013 11:07:20.974.1-05:13 R2 RIP/7/DBG: 6: 13414: RIP 1: Receiving v1 response on GigabitEthernet0/0/0 from 10.0.12.1 with 1 RTE

Sep 13 2013 11:07:20.974.2-05:13 R2 RIP/7/DBG: 6: 13465: RIP 1: Receive response from 10.0.12.1 on GigabitEthernet0/0/0

Sep 13 2013 11:07:20.974.3-05:13 R2 RIP/7/DBG: 6: 13476: Packet: Version 1, Cmd response, Length 24

Sep 13 2013 11:07:20.974.4-05:13 R2 RIP/7/DBG: 6: 13527: Dest 1.0.0.0, Cost 1

Sep 13 2013 11:07:20.974.5-05:13 R2 RIP/7/DBG: 6: 2688: RIP 1: Ignoring packet. This version is not configured.

Refer to the debug output. Following configuration of R2, the administrator discovers that the behavior is not as expected and performs debugging. Based on the output from the debug, what is the source of the problem?

- A. R2 has configured an ACL to block the route to network 1.0.0.0
- B. R2 has enabled split horizon.
- C. R1 is using authentication, however R2 is not.
- D. R2 is operating using RIPv2, while R1 is using RIPv1.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 13

Refer to the graphic. An administrator has configed RIPv2 in the two routers shows in the figure. What will happen after configuring the following commands:

[RTA-Serial0/0/1]rip output

[RTA-rip-1]silent-interface s0/0/1

(Two Answers)

- A. RTA will have the route learned from the RTB
- B. RTB will have the route learn from the RTA
- C. RTA will have no neighbor relationship with RTB
- D. RTB will have no neighbor relationship with RTB

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 14

Which of the following statements about a designated port working in RIPv2 multicast mode are true? (Select 3 Answers)

- A. The port receives only RIPv2 multicast packets.
- B. The port does not receive RIPv1 broadcast packets.
- C. The port does not receive RIPv2 broadcast packets.
- D. The port receives only RIPv1 multicast packets.

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:



http://www.gratisexam.com/

H12-211.exam.123q

Number: H12-211 Passing Score: 800 Time Limit: 120 min



H12-211

Huawei Certified Network Associate- Huawei Networking Technology and Device

Exam A

QUESTION 1

The network administrator wishes to transmit data between two end stations. The network interface cards of both devices operates at 100Mbps however one supports half duplex while the other uses full duplex mode.

What will occur as a result?



- A. The end stations cannot communicate.
- B. The end stations can communicate, but data may be lost during transmission of large amounts of traffic.
- C. The end stations will operate normally
- D. The end stations can communicate, but speed is different during transmission of large amounts of traffic.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 2

An Ethernet port can work one of three duplex modes, whereas an Optical Ethernet port only supports one single mode.

Which of the following represents this mode?

- A. Full-duplex
- B. Half-duplex
- C. Auto-negotiation
- D. Simplex

Correct Answer: A Section: (none)

Explanation

Explanation/Reference:

QUESTION 3

While inspecting packets in the network, a network administrator discovers a frame with the destination MAC address of 01-00-5E-A0-B1-C3.

What can the administrator determine from this?

- A. The MAC address is a unicast address.
- B. The MAC address is a broadcast address
- C. The MAC address is a multicast address.
- D. The MAC address is incorrect.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 4

According to OSI reference model, which layer is responsible for end to end error checking and flow control?

- A. Physical layer
- B. Data link layer
- C. Network layer
- D. Transport layer

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 5

Which of the following mechanisms are used for flow control? (Choose three)

- A. Acknowledgement
- B. Buffering
- C. Source quench messages
- D. Windowing

Correct Answer: BCD Section: (none)
Explanation

Explanation/Reference:

QUESTION 6

Source Destination Protocol Info 10.0.12.1 10.0.12.2 TCP 50190 > telnet [SYN] Seq=0 Win=8192 Len=0 MSS=1460 10.0.12.2 10.0.12.1 TCP telnet> 50190 [SYN, ACK] Seq=0 Ack=1 Win=8192 Len=0 MSS=1460 10.0.12.1 10.0.12.2 TCP 50190 > telnet [ACK] Seq=1 Ack=1 Win=8192 Len=0

Refer to the capture output. The administrator has captured three packets in the network. Which statement regarding the captured packets is incorrect?

- A. This packets represent a TCP three-way handshake process.
- B. 10.0.12.1 is the telnet server, while 10.0.12.2 is the telnet client.
- C. The three packets contain no application data.
- D. 10.0.12.1 uses port 50190 to build the telnet connection.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 7

An Ethernet frame is captured by network protocol analyzer tool and the value of Type/Length field is 0x0800.

Which of the following statements about the frame are correct? (Choose two)

- A. The frame structure of the frame is Ethernet II
- B. The frame structure of the frame is 802.3
- C. Its upper layer protocol is IP
- D. Its upper layer protocol is IPX

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 8

Which of the following descriptions regarding the TTL field of the IP packet is correct?

- A. The TTL defines how many packets the source can send.
- B. The TTL defines the duration during which the source can send packets.
- C. The TTL value will decrement by 1 each time the packet is routed.
- D. The TTL value will increment by 1 each time the packet is routed.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 9

Which of the following statements are correct about TTL field in IP packet? (Choose two)

- <choice ident="A">
- <choice ident="B">
- <choice ident="C">
- <choice ident="D">



- A. The maximum value of TTL is 65535.
- B. Normally, it's impossible for a router to receive a packet whose TTL is zero.
- C. The main purpose of TTL is to prevent IP packets from circulating endlessly in a network which can consume a lot of bandwidth.
- D. TTL value will be decremented as a packet is passed through the network devices such as hub, LAN switch and router.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 10

A network administrator recently used tracert to trace the path to the destination IP address of an external website, however the trace path displayed only a timeout result.

Which of the following statements correctly explains the reason for this? (Choose two)

- A. The source router had shutdown the ICMP function.
- B. This destination IP address does not exist.
- C. The gateway cannot find a route to the destination.
- D. This is a normal phenomenon.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 11

Ping 10.0.0.2: 56 data bytes, press CTRL_C to break
Reply from 10.0.0.2: bytes=800 Sequence=1 ttl=255 time=2 ms
Reply from 10.0.0.2: bytes=800 Sequence=2 ttl=255 time=10 ms
--- 10.0.0.2 ping statistics --2 packet(s) transmitted
2 packet(s) received
0.00% packet loss
round-trip min/avg/max = 2/6/10 ms

A network administrator uses the ping command to test connectivity to the destination 10.0.0.2 on a Huawei AR series router.

Which statement regarding the output is correct?

- A. The network administrator used the command ping -c 2 -s 800 10.0.0.2
- B. The network administrator used the command ping -a 2 -v 800 10.0.0.2
- C. The path between the source and destination is not OK.
- D. The network administrator changed the default TTL value.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 12

An ARP request is sent by host A to obtain the destination MAC address of host D.

Which statement is true about regarding the ARP reply?

- A. The destination MAC address of this frame is the MAC address of Switch A.
- B. The destination IP address of this packet is the VLANIF1 IP address of Switch A.
- C. The destination MAC address of this frame is the MAC address of Host A.
- D. The destination IP address of this packet is a broadcast IP address.

Correct Answer: C Section: (none)

Explanation Explanation/Reference: **QUESTION 13** Which of the following applications can be used to detect the path along which the data packets are transmitted from the source to the destination? <choice ident="A"> <choice ident="B"> <choice ident="C"> <choice ident="D"> A. Route B. Netstat C. Tracert D. Send Correct Answer: C Section: (none) Explanation Explanation/Reference: **QUESTION 14** How many probe packets are sent for each TTL value by default when "tracert" is used to detect the path along which packet is sent from source to destination? A. 3 B. 4 C. 6 D. 8 Correct Answer: A Section: (none)

Explanation/Reference:

Explanation

QUESTION 15

Which of the following types can ICMP packets be classified into? (Choose two)

- A. ICMP transport packet
- B. ICMP error reporting packet
- C. ICMP query packet
- D. ICMP application packet

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 16

On VRP platform, which of the following parameters can be used together with the "ping" command to specify the source address of an echo request message?

- A. A
- B. S
- C. D
- D. N

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 17

A router functioning as a Proxy receives an ARP request packet, but finds that the destination address in the packet is not intended for itself. In this case, what will the router do? (Choose two)

- A. Discard the packet.
- B. Check for a route that matches the destination address.
- C. Forward its MAC address to the ARP request sender after finding that a route to the destination address is available.

D. Broadcast the ARP request packet.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 18

Two end stations in a point-to-point network perform address resolution.

Which of the following statements is correct?

- A. The destination address of an ARP request from each station will be a unicast MAC address.
- B. The destination address of an ARP request from each station will be a broadcast IP address.
- C. The destination address of an ARP reply from each station will be a unicast MAC address.
- D. The destination address of an ARP reply from each station will be a broadcast MAC address.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 19

What will the destination MAC address be at the moment a frame is transmitted by the host, when the router is the IP destination?

- A. The MAC address of the switch.
- B. The MAC address of the router interface G0/0/0.
- C. The MAC address of the host.
- D. The destination MAC address will be a broadcast MAC address.

Correct Answer: D Section: (none) Explanation

Which of the following statements about gratuitous ARP packets are true? (Choose two)

A. A system can determine whether conflicting IP addresses are used by sending a gratuitous ARP packet



- B. A gratuitous ARP packet uses the same format as an ARP request packet.
- C. A gratuitous ARP packet can help to update an IP address.
- D. A gratuitous ARP packet uses the same format as an ARP reply packet.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 21

UDP is connectionless oriented, which of the following must be used in order to ensure reliability?

- A. Internet Protocol
- B. Application Layer Protocol
- C. Network Layer Protocol
- D. Transmission Control Protocol

Correct Answer: B Section: (none) Explanation

The administrator has configured an IP address for Host A and Host B, but had forgotten to configure a default gateway.

What effect will this have on the hosts?

- A. Neither host will be affected, and therefore will be able to communicate with the peer.
- B. Host A will be unable to connect to the router's G0/0/0 interface.
- C. Hosts will be unable to communicate unless arp-proxy is enabled on the router.
- D. The host will be unable to reach neither the local nor remote network destinations.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 23

A host has established a telnet connection with the router attached to interface G0/0/0.

Which of the following statements are correct? (Choose two)

- A. The destination address of a frame sent by the host will be the MAC address of the router interface.
- B. The destination address of a frame will be the MAC address of the switch interface.
- C. The destination port number in a segment header will have a value of 80.
- D. The destination IP address of a packet will be the IP address of the network interface of the router.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 24

The administrator uses the ping command on the host to test connectivity to the website www.huawei.com.

The command line shows a request time out. The administrator displays the ARP entries for the host.

Which entry will be found in the ARP cache table of the host?

- A. The MAC address of the destination www.huawei.com will exist in the ARP cache.
- B. The MAC address of the switch will exist in the ARP cache.
- C. The IP address of the destination www.huawei.com will exist in the ARP cache.
- D. The MAC address of router interface G0/0/0, will exist in the ARP cache.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 25

When R2 forwards data to R3 from R1, which of the following items will change? (Choose two)

- A. The source MAC address
- B. The destination MAC address
- C. The source IP address
- D. The destination IP address

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 26

If Host B also configured the IP address as "192.168.1.1/24", an IP address config will occur. What will happen as a result?

- A. Host B will send an ICMP request to the destination with the configured IP address. If a reply is received, the host will notify of an address conflict.
- B. Host A will send a gratuitous ARP request to resolve the MAC address of the destination 192.168.1.1, for which Host B will reply.
- C. Host B will send a gratuitous ARP request to resolve the MAC address of the destination 192.168.1.1, for which Host A will reply.
- D. Host A will ignore any received ARP request intended for destination 192.168.1.1.

Correct Answer: C

Section:	(none)
Explanat	ion

Explanation/Reference:

QUESTION 27

<quidway>display mac-address</quidway>	
MAC Address VLAN/VSI Learned-From Type	
5489-98ec-f018 1/- GE0/0/13 dynamic	220
Total items displayed = 1	985

Refer to the graphic. A switch attempts to forward a frame to the MAC destination 5489-98ec-f01. What operation will occur on the switch?

- A. The switch will send a request to obtain the MAC address of 5489-98ec-f011.
- B. The switch will report that the destination is unreachable and report this to the source.
- C. The switch will flood the frame via all ports, with exception of the port on which the frame was received.
- D. The switch will drop the frame because it does not have an entry in its MAC address table.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 28

Host A has been connected to switch A and configured with an IP address.

When Host A initially forwards a frame, what action will be taken by Switch A?

- A. Switch A will drop this frame.
- B. Switch A will attempt to flood the frame to all ports except for the G0/0/1 interface.

- C. Switch A will forward the frame via ports G0/0/1, G0/0/2 and G0/0/3.
- D. Switch will receive this frame before returning the frame to G0/0/1.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 29

A server is linked to port interface G0/0/1 of a switch. The administrator wishes to allow only this server to be linked to this interface on the switch.

Which method can be used to achieve this?

- A. Configure a static ARP entry using the server's IP address and MAC address in the switch.
- B. Configure a static MAC address binding entry of the server's MAC address and the interface in the switch.
- C. Configure the default gateway of the switch to be the same as the server's IP address.
- D. It is not possible to enable a single device to be associated with an interface.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 30

An administrator connects two switches together in a local enterprise network. The ports of one switch support Fast Ethernet, while the ports of the other switch support Gigabit Ethernet. Hosts connected to one switch are able to communicate, however communication between the two switches fails.

What is the possible reason for this?

- A. The ports have disabled auto-negotiation.
- B. One port is supporting auto-negotiation, while auto-negotiation is disabled on the port of the other switch.
- C. The port of one switch is operating using half duplex mode, while the port of the other switch is using full duplex mode.
- D. A Fast Ethernet port cannot communicate directly with a Gigabit Ethernet port.

Correct Answer: A

Section: (none) Explanation

Explanation/Reference:

QUESTION 31

A layer 2 LAN switch generates CAM table entries according to the () of the received frame.

- A. Source MAC address
- B. Destination MAC address
- C. Source IP address
- D. Destination IP address

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 32

Which of the following statements about collision domains and broadcast domains are correct? (Choose three)

- A. Devices connected to the same hub form a collision domain
- B. Devices connected to the same hub form a broadcast domain.
- C. Devices connected to the same bridge form a collision domain
- D. Devices connected to the same bridge form a broadcast domain
- E. Devices connected to the same router form a broadcast domain

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 33

Which of the following are routed protocols? (Choose two)

- A. IP
- B. OSPF
- C. BGP
- D. IPX

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 34

Which of the following statements regarding the routing table are correct? (Choose two)

- A. The next hop in the routing table is redundant because the outgoing interface can be used for packet forwarding.
- B. The routes from generated by different protocols have different preferences.
- C. The metrics of different routing protocols are comparable.
- D. The metrics of different routing protocols are not comparable

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 35

Which of the following commands can be used to display the routing table on a Quidway router?



https://www.gratisexam.com/

- A. display ip path
- B. display ip routing-table

- C. display interface
- D. display current-configuration

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 36

Which of the following entries is not included in the routing table?

- A. source address
- B. next hop
- C. destination address
- D. cost

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 37

Which of the following problems are caused by routing loops? (Choose three)

- A. Slow convergence
- B. Packets circulate between routers
- C. Router restarting
- D. Inconsistency of routing information

Correct Answer: ABD Section: (none) Explanation

An administrator wishes to manage the router in the remote branch office, which method can be used?

- A. Telnet
- B. FTP
- C. Console Connection
- D. DHCP

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 39

The administrator cannot use telnet to manage the AR2200. The administrator is able to verify connectivity to the router and has been informed that other administrators have no difficulties using telnet.

Which statements describe the possible reasons for this problem? (Choose two)

- A. The user's status has been blocked
- B. The user's privilege level has been changed to 0.
- C. The user has been deleted.
- D. The telnet service in the AR2200 router has been disabled.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 40

A user logged into a VRP supported device through telnet, but when attempting to configure the device, found that he is unable to use the system-view command to enter the system-view.

What are the possible reasons for this? (Choose two)

- A. The device's VTY interface only provides permission for some telnet users to run the system-view command.
- B. The user's telnet software restricts use of this command.
- C. The user's privilege level is lower than the level associated with the system-view command.
- D. The system-view command privilege level is lower than the level associated with the user.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 41

The users who log on the router through Telnet are not permitted to configure IP address.

What is the possible reason?

- A. Communication failures occur between the user and the router.
- B. The authentication mode of Telnet is set incorrectly.
- C. Privilege level of Telnet is set incorrectly.
- D. SNMP parameters are set incorrectly.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 42

Which of the following statements are correct? (Choose two)

- A. A single collision domain exists between RTA and SWC.
- B. A single broadcast domain exists between SWA and SWB.
- C. A single collision domain exists between SWA and SWC.
- D. A single broadcast domain exists between SWA and SWC.

Correct Answer: CD Section: (none)

Explanation

Explanation/Reference:

QUESTION 43

On the interface serial 1/0/1 of RTA, the command "ip address unnumbered interface loopback 0" has been configured.

Which following statements are correct? (Choose two).

- A. The IP address of interface serial 1/0/1 is 10.1.1.1/24
- B. The IP address of interface serial 1/0/1 is 10.1.1.1/32
- C. The route entry 10.1.1.0/24 exists in RTA's routing-table
- D. The route entry 10.1.1.0/24 does not exist in RTA's routing-table

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 44

Refer to the graphic. The host has a problem establishing a telnet connection with the router attached to interface G0/0/0. Which of the following steps can be used to help the administrator identify the problem? (Choose two)

<choice ident="A"> <choice ident="B"> <choice ident="C"> <choice ident="D">

- A. Check whether the host has configured the gateway IP address.
- B. Check whether the switch has configured the gateway IP address.
- C. Use the ping tool to check connectivity between host and router.
- D. Check the telnet server configuration is right on the router.

Correct Answer: CD

Section:	(none)
Explanati	ion

Explanation/Reference:

QUESTION 45

Which of the following methods are supported by VRP platform to configure the router? (Choose three)

- A. Through the Console port
- B. Through Telnet
- C. Through the AUX port
- D. Through FTP

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 46

The administrator wishes to update the configuration file of an AR2200 router using a USB cable.

How can this be achieved? (Choose two)

- A. The administrator should connect the USB cable between the terminal and the mini USB port of the AR2200 router.
- B. The administrator should connect the USB cable between the terminal and the USB port of the AR2200 router.
- C. The AR2200 router cannot support configuration updates through a USB cable.
- D. The administrator should install the mini USB drivers on the terminal after connecting the USB.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 47

The administrator wishes to manage a network through telnet from a user's terminal to a router.

How can this be achieved?

- A. A connection should be established between the ethernet port of the terminal and the console port of the router.
- B. A connection should be established between the ethernet port of the terminal and the ethernet port of the router.
- C. A connection should be established between the console port of the terminal and the ethernet port of the router.use console cable connect pc's ethernet port and router's console port.
- D. A connection should be established between the COM port of the terminal and the console port of the router.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 48

Whilst configuring a device, an administrator experiences trouble remembering certain commands.

Which of the following will help support the administrator? (Choose two)

A. TAB

B. question mark

C. ctrl+b

D. ctrl+c

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 49

<Huawei> system-view

[Huawei] user-interface console 0

[Huawei-ui-console0] user privilege level 15

[Huawei-ui-console0] authentication-mode password

[Huawei-ui-console0] set authentication password cipher huawei2012

[Huawei-ui-console0] quit

Refer to the configuration output. The administrator configured the device using the commands in the configuration output. Regarding these commands, which statement is false?



- A. The administrator wishes to enable management through the console interface.
- B. Following configuration, the administrator cannot manage the device remotely.
- C. A user that logs-in through the console interface is assigned the highest privilege level.
- D. The password of a user logged in through console is 'cipher huawei2012'.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 50

Which of the following commands is used to enter the system-view from the user view on a Huawei router?

- A. system-view
- B. enable
- C. configure terminal
- D. interface system

Correct Answer: A

Section: (none) Explanation

Explanation/Reference:

QUESTION 51

On VRP platform, the command lines are classified into four levels in increasing priority: Visit level, Monitoring level, Configuration level, and Management level. At which level, the operator is permitted to configure service but is not permitted to operate the file system?

- A. Visit level
- B. Monitoring level
- C. Configuration level
- D. Management level

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 52

On Huawei VRP platform, which of the following can be used to invoke the history command saved by the command line interface? (Choose two)

- <choice ident="A">
- <choice ident="B">
- <choice ident="C">
- <choice ident="D">
- A. Up cursor key < >
- B. Left cursor key <>
- C. Ctrl+P
- D. Ctrl+U

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 53

Which of the following commands can be used to view the current configurations on a Huawei router?

- A. display current-configuration
- B. display saved-configuration
- C. view saved-configuration
- D. show startup-configuration

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 54

The administrator wishes to change name of the router. Under which view should the administrator be in order to achieve this?

- A. User-view
- B. System-view
- C. Interface-view
- D. Protocol-view

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 55

<Huawei> system-view [Huawei]command-privilege level 3 view user save

Refer to the command output. What is the result of the shown command?

- A. The command adjusts the save command of a user to privilege level 3.
- B. The command adjusts the save command in the user view to privilege level 3.
- C. The command adjusts the user view command privilege level to 3, and saves the configuration.
- D. The command adjusts the privilege level of a user to 3, and saves the configuration.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 56

Which of the following storage devices are supported by Huawei router? (Select four)

- A. SDRAM
- B. NVRAM
- C. Flash
- D. Hard Disk
- E. CF Card

Correct Answer: ABCE

Section: (none) Explanation

Explanation/Reference:

QUESTION 57

Which of the following storage devices is used to store the startup configuration files in a router?

- <choice ident="A"> <choice ident="B">
- <choice ident="C">
- <choice ident="D">
- A. SDRAM
- B. NVRAM

- C. Flash
- D. BootROM

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 58

<Huawei>reset saved-configuration

Warning: The action will delete the saved configuration in the device. The configuration will be erased to reconfigure. Continue? [Y/N]:

Refer to the configuration output. Which of the following statements are true? (Select two answers)

- A. A user should enter 'Y' when wishing to clear the saved configuration file.
- B. The saved-configuration file that the device starts with can be erased.
- C. The saved-configuration will be deleted after typing N
- D. The saved-configuration file will be replaced with the current-configuration.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 59

When a router is powered on, the router reads the configuration file saved in the default save directory to get itself initialized. If the configuration file does not exist in the default save directory, what does the router use to initialize itself?

- A. New configuration file
- B. Initial configuration file
- C. Default parameters
- D. Current configuration file

Correct Answer: C

Section: (none) Explanation

Explanation/Reference:

QUESTION 60

<Huawei>display startup

MainBoard:

Startup system software: sd1:/ar2220-v200r003c00spc200.cc Next startup system software: sd1:/ar2220-v200r003c00spc200.cc

Backup system software for next startup: null

Startup saved-configuration file: null Next startup saved-configuration file: null

Startup license file: null Next startup license file: null Startup patch package: null Next startup patch package: null

Startup voice-files: null Next startup voice-files: null

Refer to the display output. Which statement is false?

- A. The current configuration file has not been saved.
- B. The current startup system software is ar2220-v200r003c00spc200.cc
- C. The next startup system software cannot be changed.
- D. The next startup system software can be changed by using the "startup system software <startup-softwarename>.cc" command.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 61

<Huawei>

Warning: Auto-Config is working. Before configuring the device, stop Auto-Config. If you perform configurations when Auto-Config is running, the DHCP, routing, DNS, and VTY configurations will be lost. Do you want to stop Auto-Config? [y/n]:

When an administrator first initializes the router, a warning is displayed. Which statement regarding this warning is correct?



- A. If Auto-Config is required, the administrator should select 'v'.
- B. If Auto-Config is not required, the administrator should select 'n', for which subsequent configuration of the DHCP server, routing, DNS server and VTY user configuration is lost.
- C. When a device is started for the first time, the Auto-Config function is active.
- D. When a device is started for the first time, the Auto-Config function is inactive.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 62

An AR2200 router in the company network cannot boot. In order to resolve this, the administrator wishes to update the VRP software.

What should he/she do?

- A. The administrator should use a console cable to connect the router and host, and directly upgrade the device.
- B. The administrator should use FTP to transfer the VRP software, by configuring the AR2200 router as an FTP client.
- C. The administrator should use DHCP to boot the AR2200, and then use the AR2200 router as a TFTP client to download the VRP software from the server.
- D. The administrator should use the telnet command on the client to remote access the device, and upgrade the VRP software.

Correct Answer: B Section: (none) Explanation

<Huawei>

Warning: Auto-Config is working. Before configuring the device, stop Auto-Config. If you perform configurations when Auto-Config is running, the DHCP, routing, DNS, and VTY configurations will be lost. Do you want to stop Auto-Config? [y/n]:

Refer to the output. When the administrator first starts the router, a system notice is displayed, however after rebooting this router, the notice disappeared. What is the reason for this? (Choose two)

- A. This notice only appears during the very first device startup.
- B. The administrator has configured the device and saved the configuration, causing the notice to disappear.
- C. The administrator selected 'n' and did not save the configuration.
- D. The administrator selected 'v' and saved the configuration.

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 64

An end system is unable to communicate with a DHCP server following the startup process.

Which IP address may be used by the client?

A. 0.0.0.0

B. 127.0.0.1

C. 169.254.2.33

D. 255.255.255.255

Correct Answer: C Section: (none) Explanation

[Huawei]ip pool pool1

Info: It's successful to create an IP address pool.

[Huawei-ip-pool-pool1]network 10.10.10.0 mask 255.255.255.0

[Huawei-ip-pool-pool1]gateway-list 10.10.10.1

Refer to the configuration output. The administrator wishes to configure the DHCP server pool in order to assign an IP address to the customer's terminal device.

Which command should be included in the configuration to provide the minimal lease period for IP addresses?

- A. dhcp select relay
- B. lease day 1
- C. lease 24
- D. lease 0

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 66

A DHCP server has been established in the enterprise network. After the client has obtained an IP address from the DHCP server, the user decided to modify the IP address manually.

In what way may this affect the enterprise network? (Choose two).

- A. The client may experience an IP address conflict.
- B. The client may access the network normally.
- C. The client's interface connection will shutdown.
- D. The client will associate with another DHCP server.

Correct Answer: AB Section: (none) Explanation

A DHCP server in the enterprise network is being used to allocated IP addresses to hosts. An administrator discovers however that some hosts are obtaining IP addresses outside of the scope of the DHCP server's address pool.

What are the possible reasons for this? (Choose three).

- A. Another DHCP server exists in the network and is allocating IP addresses to hosts that happen to be within a closer proximity than the authorized DHCP server.
- B. The hosts were unable to discover a DHCP server and therefore generated their own address in the 169.254.0.0 address range.
- C. The hosts were unable to discover a DHCP server and therefore generated their own address in the 127.254.0.0 address range.
- D. All addresses from the DHCP pool have been assigned.

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 68

Router] ip pool pool1

[Router-ip-pool-pool1] network 10.10.10.0 mask 255.255.255.0

[Router-ip-pool-pool1] gateway-list 10.10.10.1

[Router-ip-pool-pool1] quit

[Router] ip pool pool2

[Router-ip-pool-pool2] network 10.20.20.0 mask 255.255.255.0

[Router-ip-pool-pool2] gateway-list 10.20.20.1

[Router-ip-pool-pool2] quit

[Router] interface GigabitEthernet 0/0/1

[Router-GigabitEthernet0/0/1] ip address 10.10.10.1 24

[Router-GigabitEthernet0/0/1] dhcp select global

Refer to the configuration output. Following configuration, a host is connected to the interface Gigabit Ethernet 0/0/1 of the router. Which IP address will the client obtain?

- <choice ident="A"> <choice ident="B"> <choice ident="C"> <choice ident="D">
- A. An IP address from network 10.10.10.0/24 will be assigned.
- B. An IP address from network 10.20.20.0/24 will be assigned.
- C. The host will be unable to obtain an IP address.
- D. An IP address may be assigned from either 10.10.10.0/24 or 10.20.20.0/24.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 69

An authenticator router has been configured with two domains named "Area1" and "Area2", following which a user is created with the username "huawei" and the password "hello" for authentication. Which domain does this user belongs to?

<choice ident="A"> <choice ident="B"> <choice ident="C"> <choice ident="D">

- A. Area1 domain
- B. Area2 domain
- C. default domain
- D. default admin domain

Correct Answer: C Section: (none) Explanation

In order to check if the interface serial 1/0/0 is working in either DCE or DTE mode, command () is used.

- A. display mode serial 1/0/0
- B. display controller
- C. display interface serial 1/0/0
- D. display current-config

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 71

How is mapping performed on a DTE device in a Frame Relay network?

- A. The local DLCI number is mapped to a remote IP address.
- B. The local IP address is mapped to a remote DLCI number.
- C. The local DLCI number is mapped to a local IP address.
- D. The remote DLCI number is mapped to a remote IP address.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 72

If Frame Relay implements dynamic address mapping for the PVC, which protocol will be used?

- A. LMI protocol
- B. ARP protocol
- C. RARP protocol
- D. InARP protocol

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 73

Which command should be used to check the mapping between protocol addresses and frame relay addresses?

- A. display fr interface
- B. display fr map-info



- C. display fr inarp-info
- D. display interface brief

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 74

Which of the following protocols is used in Frame Relay to map the address to DLCI dynamically?

- <choice ident="A">
- <choice ident="B">
- <choice ident="C">
- <choice ident="D">
- A. ARP protocol

- B. RARP protocol
- C. InARP protocol
- D. Map protocol

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 75

Which of the following parameters must be specified when configuring static mapping for Frame Relay network? (Choose two)

- A. Local DLCI
- B. Remote DLCI
- C. Local network layer protocol address
- D. Remote network layer protocol address

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 76

Which of the following regarding Frame Relay DLCI are correct? (Choose three)

- A. DLCI is locally significant
- B. DLCI is allocated by DTE
- C. The range of DLCI value that can be used is from 16-1007
- D. The same DLCI can be configured on different physical interfaces

Correct Answer: ACD Section: (none)
Explanation

Which of the following commands is used to enable dynamic address mapping protocol in the interface encapsulated with Frame Relay?

- A. fr inarp
- B. fr reverse-arp
- C. inverse-arp
- D. reverse-arp

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 78

What is the meaning of 200 in the command "fr map ip 10.1.1.2 200"?

- A. remote logical channel ID
- B. local DLCI
- C. remote interface ID
- D. remote node ID

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 79

Which of the following commands can be used to display mapping relationship between network address and DLCI?

- A. display fr interface
- B. display fr
- C. display fr map-info
- D. display fr brief

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 80

Which of following may be the reasons that cause Frame Relay PVC to work abnormally? (Choose three)

- A. Same DLCI number is configured on the same router
- B. LMI type mismatch
- C. Frame Relay encapsulation type mismatch
- D. Incorrect configuration of the DLCI number

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:

QUESTION 81

An administrator wishes to update the VRP software of company's AR2200 router. How can this be achieved? (Choose three)

- A. The administrator can use FTP to transfer the VRP software, with the AR2200 router as the FTP client.
- B. The administrator can use FTP to transfer the VRP software, with the AR2200 router as the FTP server.
- C. The administrator can use TFTP to transfer the VRP software, with the AR2200 router as the TFTP server.
- D. The administrator can use TFTP to transfer the VRP software, with the AR2200 router as the TFTP client.

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 82

An administrator wishes to implement new features in the network, but the VRP version of one AR2200 router is out of date. The administrator needs to upgrade the VRP software.

Which of the following options regarding file transfer is false?

- A. The AR2200 router can function as a TFTP client to support the upgrade.
- B. The AR2200 router can function as the TFTP server to support the upgrade.
- C. The AR2200 router can function as the FTP server to support the upgrade.
- D. The AR2200 router can function as an FTP client to support the upgrade.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 83

FTP and TFTP can be used to update the system file on Huawei routers. Which of the following statements are correct? (Choose three)

<choice ident="A">
<choice ident="B">
<choice ident="C">
<choice ident="D">

- A. Huawei router can be configured as FTP Client
- B. Huawei router can be configured as FTP Server
- C. Huawei router can be configured as TFTP Client
- D. Huawei router can be configured as TFTP Server

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 84

Which of the following IPv6 addresses can be configured on a router's interface? (Choose two).

A. fe80:13dc::1/64B. ff00:8a3c::9b/64

C. ::1/128

D. 2001:12e3:1b02::21/64

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 85

The IPv6 address achitecture does not include which of the following address types?

- A. unicast
- B. multicast
- C. broadcast
- D. anycast

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 86

Which of the following descriptions regarding IPv6 addresses are correct? (Choose two)

- A. IPv6 addresses are 64 bits in length.
- B. IPv6 addresses are 128 bits in length.
- C. IPv6 extension headers are processed in order.
- D. IPv6 extension headers are processed randomly.

Correct Answer: BC

Section: (none) Explanation

Explanation/Reference:

QUESTION 87

Interface G0/0/1 on RTA contains a MAC address of 00e0-fc03-aa73 and is configured with the IPv6 address 2001::2E0:FCFF:FE03:AA73. Which method is most likely to have been used to configure the interface IPv6 address?

- A. DHCPv6
- B. Auto-link
- C. ARP
- D. EUI-64

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 88

In a small network supporting IPv6, a network administrator wishes implement RIPng.

Which of the following commands should be used to enable this protocol?



- A. [RTA-GigabitEthernet0/0/0]ripng 1 enable
- B. [RTA]ripng 1 enable
- C. <RTA>ripng 1 enable
- D. [RTA-ripng-1]ripng 1 enable

Correct Answer: A

Section: (none) Explanation
Explanation/Reference:
QUESTION 89 In a network supporting IPv6, OSPF no longer supports which feature?
A. multiple areasB. Router-IDC. authenticationD. multicast updates
Correct Answer: C Section: (none) Explanation
Explanation/Reference:
QUESTION 90 The network administrator has decided to configure link aggregation in the enterprise network.
Which of the following represent advantages of link aggregation? (Choose three)
A. Load balancing.B. Improved bandwidth.C. Enhanced reliability.D. Improved security.
Correct Answer: ABC Section: (none) Explanation
Explanation/Reference:
QUESTION 91

In port aggregation, "multiple" ports are aggregated to form a port aggregation group so that all the member ports in the group share the outgoing/incoming load.

At which layer is port aggregation implemented?

- A. Physical Layer
- B. Data Link Layer
- C. Network Layer
- D. Transport Layer

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 92

What benefits does port aggregation yield? (Choose three)

- A. Improves link bandwidth
- B. Implements load sharing
- C. Improves network reliability
- D. Facilitates data copy for analysis

Correct Answer: ABC

Section: (none) Explanation

Explanation/Reference:

QUESTION 93

What is the maximum number of member interfaces supported by a single Eth-Trunk?

- A. 6
- B. 8
- C. 10
- D. 12

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 94

The Eth-Trunk frame forwarding mechanism used to prevent changes in the data sequence forwards frames based on which of the following parameters?

- A. The same source or destination IP address.
- B. The same source or destination MAC address.
- C. The same protocol type.
- D. The same source or destination port number.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 95

In Layer 2 mode, the transmission rate of an Eth-Trunk interface is determined by which of the following?

- A. Maximum number of Up member links
- B. Minimum number of Up member links
- C. Number of Up member interfaces
- D. Number of interfaces.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 96

The network administrator wishes to forward data over an Eth-trunk, however associated member interfaces operate at different rates. In terms of the resulting

behavior, which of the following is true?

- A. The two switches will not be able to communicate.
- B. The higher rate member interfaces may incur packet loss.
- C. The Eth-Trunk will work normally.
- D. The lower rate member interfaces may incur packet loss.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 97

[RTA-GigabitEthernet0/0/0]nat outbound 2000 address-group 1

Refer to the configuration output. What does the value "2000" refer to?

- A. It represents the ACL number.
- B. It represents the NAT number.
- C. It represents the translated port number.
- D. It represents the number of bytes that can be translated before the address is returned to the public address pool.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 98

NAPT uses the same public address but different port numbers to translate private addresses.

Which statement regarding the port number is correct?

- A. It is necessary to configure port number mapping manually.
- B. It is only necessary to configure the port number range.
- C. It is not necessary to configure port numbers.

D. An access control list is needed to assign port numbers.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 99

A configured internal host of a private network wishes to access the internet. What must be configured on the enterprise network's edge router in order to achieve this? (Choose two)

- A. NAT EasyIP
- B. DHCP
- C. BGP
- D. Default route

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 100

Which of the following statements are correct about NAT? (Choose three)

- A. NAT is the abbreviation for "Network Address Translation".
- B. NAT is used for translation between private and public network addresss.
- C. When hosts inside a private network access the outside network, NAT is not required.
- D. NAT provides an effective way to solve the problem of insufficient IP addresses.

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 101

Which of the following technologies can allow a host with IP address 10.0.0.1 to access the internet?

- A. Static route
- B. Dynamic route
- C. Route import
- D. NAT

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 102

Which of the following items can be translated by NAPT?

- A. MAC address + port number
- B. IP address + port number
- C. Only MAC address
- D. Only IP address

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 103

Which of the following statements about a designated port working in RIPv2 multicast mode are true? (Choose three)

A. The port receives only RIPv2 multicast packets.



- B. The port does not receive RIPv1 broadcast packets.
- C. The port does not receive RIPv2 broadcast packets.
- D. The port receives only RIPv1 multicast packets.

Correct Answer: ABC

Section: (none) Explanation

Explanation/Reference:

QUESTION 104

Which of the following statements regarding the router ID in OSPF are incorrect? (Choose three)

- A. The router IDs of OSPF routers in the same area must be the same, but can be different in different areas.
- B. The router ID must be the IP address of an OSPF router interface.
- C. The router ID must be configured manually.
- D. A router running OSPF must have a router ID for it to operate properly.

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 105

Which of the following statements regarding Designated Routers in OSPF are correct? (Choose three)

- A. DR is elected by all the routers in the same network segment.
- B. If the priorities of two routers are different, the router with the lower priority will be elected as DR.

- C. If the priorities of two routers are equal, the router with the higher Router ID will be elected as DR.
- D. DR and BDR must be adjacent.

Correct Answer: ACD Section: (none)

Explanation

Explanation/Reference:

QUESTION 106

On the VRP platform, which of the following commands is used to configure the Router ID of a router as 1.1.1.1?

- A. <Huawei>router id 1.1.1.1
- B. [Huawei]router id 1.1.1.1
- C. [Huawei]router-id 1.1.1.1
- D. [Huawei]router id 1.1.1.1 255.255.255.255

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 107

Which of the following OSPF versions is specific to IPv6?

- A. OSPFv1
- B. OSPFv2
- C. OSPFv3
- D. OSPFv4

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 108

The administrator wishes to configure OSPF on a router in the network however the router has no loopback interface.

Which value will be used as the router ID?

- A. The lowest IP address of the router's active interfaces.
- B. The highest IP address of the router's active interfaces.
- C. The IP address of the management interface.
- D. The priority value of the router.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 109

An administrator of a company supporting a large enterprise network wishes to implement OSPF on the network as opposed to RIP. Which of the following points should the administrator use to support his reasoning for this change? (Choose three)

- A. OSPF has no hop count limitation.
- B. OSPF has a lower routing update overhead.
- C. OSPF has a simpler configuration.
- D. OSPF supports faster convergence.

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 110

Which of the following statements regarding single area OSPF are correct? (Choose three)

- A. An IP address needs to be configured on a loopback interface of each router before configuring an OSPF area.
- B. The value of an area can be from 0.0.0.0 to 255.255.255.255.

- C. A single area can be configured using any supported area number.
- D. All of the links of the network need to be advertised in Area 0.

Correct Answer: BCD Section: (none)
Explanation

Explanation/Reference:

QUESTION 111

10.0.1.0/24 O ASE 150 2 D 10.0.23.3 Serial2/0/0

Refer to the display output. Which of the following statements regarding route shown are true? (Choose two)

- A. The address 10.0.23.3 has been configured on the peer's serial 2/0/0 interface.
- B. The route preference has been changed by the administrator.
- C. The metric for the route 10.0.1.0 indicates that two hops are needed.
- D. The route has been learned via the OSPF protocol.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 112

Which of the following statements regarding link-state database and routing-table of a "single" OSPF area are correct? (Choose two)

- A. The link-state databases that all routers build are identical.
- B. The link-state databases that all routers build are different.
- C. The routing-tables that all routers calculate are different.
- D. The routing-tables that all routers calculate are identical.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 113

With what kind of routers does a DRother router exchange link state information and route information? (Choose two)

- A. DR
- B. BDR
- C. DRother
- D. All OSPF neighbors

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 114

An OSPF area is a collection of a group of routers and networks. OSPF defines that routers that have the same () belong to the same OSPF area.

- A. neighbors
- B. LSDB
- C. LSA
- D. adjacency

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 115

Which of the following statements about router IDs are true? (Choose two)

- A. The routers contained in the same LSDB have the same router ID.
- B. Each router in an OSPF network must have a unique router ID.
- C. Two routers in different OSPF areas can have the same router ID.

D. A router ID is expressed in a 32-bit dotted decimal format.

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 116

OSPF allows for "multiple" processes. By default, OSPF selects a process whose number is ().



https://www.gratisexam.com/

A. 0

B. 1

C. 10

D. 100

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 117

In a network supporting IPv6, OSPF no longer supports which feature?

- A. multiple areas
- B. Router-ID
- C. authentication
- D. multicast updates

Correct Answer: C

Section: (none) Explanation

Explanation/Reference:

QUESTION 118

Two routers are configured with OSPFv3. OSPFv3 is enabled on all interfaces of each router.

Which of the following is true in the event that the network administrator does not configure a Router-ID?

- A. The IP address of the loopback 0 interface will be used as the router ID.
- B. The IP address of the loopback 1 interface will be used as the router ID.
- C. The IP address of interface G0/0/0 will be used as the router ID.
- D. No router ID will be assigned to the router.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 119

Destination/Mask protocol pre Cost Nexthop Interface

9.0.0.0/8 OSPF 10 50 1.1.1.1 Serial 1/0/0 9.1.0.0/16 RIP 100 5 2.2.2.2 Ethernet 0/0/1

Refer to the graphic. Which of the following statements is correct when this router forwards the packet to the destination host 9.1.4.5?

- A. The router selects the first entry to match the destination address of the packet because the preference of OSPF is higher than the preference of RIP.
- B. The router selects the second entry to match the destination address of the packet because the cost of RIP is lower than that of OSPF.
- C. The router selects the second entry to match the destination address of the packet because the outgoing interface is an Ethernet interface. The forwarding speed of an Ethernet interface is faster than the forwarding speed of a serial interface
- D. The router selects the second entry to match the destination address of the packet because the router will match the most specific address.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 120

According to the default value of route preference on the VRP platform, which of the following represent the correct sequence for direct route, static route, RIP and OSPF if they are listed from high preference to low preference?

- A. Direct, Static, RIP, OSPF
- B. Direct, OSPF, Static, RIP
- C. Direct, OSPF, RIP, Static
- D. Direct, RIP, Static, OSPF

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 121

Two routers are connected through serial interfaces and support PPP encapsulation.

Which parameters must be negotiated to establish the PPP connection? (Choose three).

- A. MRU
- B. Authentication password
- C. Magic-Number
- D. IP address

Correct Answer: ACD

Section: (none) Explanation

Explanation/Reference:

QUESTION 122

What are the three protocol components defined by PPP? (Choose three).

- A. Data encapsulation.
- B. LCP
- C. NCP
- D. IPCP

Correct Answer: ABC Section: (none)
Explanation

Explanation/Reference:

QUESTION 123

Two routers are connected via serial interfaces and the link-protocol is PPP, but the MRU of two serial interfaces are different, in PPP LCP negotiated stage, what will happen?

- A. LCP negotiation will fail
- B. Negotiation will use the smaller value
- C. Negotiation will use the larger value
- D. Negotiation will use 1500

Correct Answer: B Section: (none) Explanation

Explanation/Reference:



H12-211.exam.120q

Number: H12-211
Passing Score: 800
Time Limit: 120 min
File Version: 1

Huawei H12-211



Huawei Certified Network Associate- Huawei Networking Technology and Device

Exam -

QUESTION 1

Which of the following applications can be used to detect the path along which the data packets are transmitted from the source to the destination?

<choice ident="A">

<choice ident="B">

<choice ident="C">

<choice ident="D">

- A. Route
- B. Netstat
- C. Tracert
- D. Send

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 2

How many probe packets are sent for each TTL value by default when "tracert" is used to detect the path along which packet is sent from source to destination?



https://www.gratisexam.com/

- A. 3
- B. 4
- C. 6
- D. 8

Correct Answer: A Section: (none)

Explanation

Explanation/Reference:

QUESTION 3

Which of the following types can ICMP packets be classified into? (Choose two)

- A. ICMP transport packet
- B. ICMP error reporting packet
- C. ICMP query packet
- D. ICMP application packet

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 4

On VRP platform, which of the following parameters can be used together with the "ping" command to specify the source address of an echo request message?

- A. A
- B. S
- C. D
- D. N

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 5

A router functioning as a Proxy receives an ARP request packet, but finds that the destination address in the packet is not intended for itself. In this case, what will the router do? (Choose two)

- A. Discard the packet.
- B. Check for a route that matches the destination address.
- C. Forward its MAC address to the ARP request sender after finding that a route to the destination address is available.
- D. Broadcast the ARP request packet.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 6

Two end stations in a point-to-point network perform address resolution.

Which of the following statements is correct?

- A. The destination address of an ARP request from each station will be a unicast MAC address.
- B. The destination address of an ARP request from each station will be a broadcast IP address.
- C. The destination address of an ARP reply from each station will be a unicast MAC address.
- D. The destination address of an ARP reply from each station will be a broadcast MAC address.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 7

What will the destination MAC address be at the moment a frame is transmitted by the host, when the router is the IP destination?

- A. The MAC address of the switch.
- B. The MAC address of the router interface G0/0/0.
- C. The MAC address of the host.
- D. The destination MAC address will be a broadcast MAC address.

Correct Answer: D Section: (none)

Explanation

Explanation/Reference:

QUESTION 8

Which of the following statements about gratuitous ARP packets are true? (Choose two)



https://www.gratisexam.com/

- A. A system can determine whether conflicting IP addresses are used by sending a gratuitous ARP packet
- B. A gratuitous ARP packet uses the same format as an ARP request packet.
- C. A gratuitous ARP packet can help to update an IP address.
- D. A gratuitous ARP packet uses the same format as an ARP reply packet.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 9

UDP is connectionless oriented, which of the following must be used in order to ensure reliability?

- A. Internet Protocol
- B. Application Layer Protocol
- C. Network Layer Protocol
- D. Transmission Control Protocol

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 10

The administrator has configured an IP address for Host A and Host B, but had forgotten to configure a default gateway.

What effect will this have on the hosts?

- A. Neither host will be affected, and therefore will be able to communicate with the peer.
- B. Host A will be unable to connect to the router's G0/0/0 interface.
- C. Hosts will be unable to communicate unless arp-proxy is enabled on the router.
- D. The host will be unable to reach neither the local nor remote network destinations.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 11

A host has established a telnet connection with the router attached to interface G0/0/0.

Which of the following statements are correct? (Choose two)

- A. The destination address of a frame sent by the host will be the MAC address of the router interface.
- B. The destination address of a frame will be the MAC address of the switch interface.
- C. The destination port number in a segment header will have a value of 80.
- D. The destination IP address of a packet will be the IP address of the network interface of the router.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 12

The administrator uses the ping command on the host to test connectivity to the website www.huawei.com.

The command line shows a request time out. The administrator displays the ARP entries for the host.

Which entry will be found in the ARP cache table of the host?

- A. The MAC address of the destination www.huawei.com will exist in the ARP cache.
- B. The MAC address of the switch will exist in the ARP cache.
- C. The IP address of the destination www.huawei.com will exist in the ARP cache.
- D. The MAC address of router interface G0/0/0, will exist in the ARP cache.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 13

When R2 forwards data to R3 from R1, which of the following items will change? (Choose two)

- A. The source MAC address
- B. The destination MAC address
- C. The source IP address
- D. The destination IP address

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 14

If Host B also configured the IP address as "192.168.1.1/24", an IP address config will occur. What will happen as a result?

- A. Host B will send an ICMP request to the destination with the configured IP address. If a reply is received, the host will notify of an address conflict.
- B. Host A will send a gratuitous ARP request to resolve the MAC address of the destination 192.168.1.1, for which Host B will reply.
- C. Host B will send a gratuitous ARP request to resolve the MAC address of the destination 192.168.1.1, for which Host A will reply.
- D. Host A will ignore any received ARP request intended for destination 192.168.1.1.

Correct Answer: C
Section: (none)
Explanation

Explanation/Reference:

QUESTION 15

<quidway>display mac-address</quidway>	
MAC Address VLAN/VSI Learned-From Type	
5489-98ec-f018 1/- GE0/0/13 dynamic	
Total items displayed = 1	

Refer to the graphic. A switch attempts to forward a frame to the MAC destination 5489-98ec-f01. What operation will occur on the switch?

- A. The switch will send a request to obtain the MAC address of 5489-98ec-f011.
- B. The switch will report that the destination is unreachable and report this to the source.
- C. The switch will flood the frame via all ports, with exception of the port on which the frame was received.
- D. The switch will drop the frame because it does not have an entry in its MAC address table.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 16

Host A has been connected to switch A and configured with an IP address.

When Host A initially forwards a frame, what action will be taken by Switch A?



https://www.gratisexam.com/

- A. Switch A will drop this frame.
- B. Switch A will attempt to flood the frame to all ports except for the G0/0/1 interface.
- C. Switch A will forward the frame via ports G0/0/1, G0/0/2 and G0/0/3.
- D. Switch will receive this frame before returning the frame to G0/0/1.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 17

A server is linked to port interface G0/0/1 of a switch. The administrator wishes to allow only this server to be linked to this interface on the switch.

Which method can be used to achieve this?

- A. Configure a static ARP entry using the server's IP address and MAC address in the switch.
- B. Configure a static MAC address binding entry of the server's MAC address and the interface in the switch.
- C. Configure the default gateway of the switch to be the same as the server's IP address.
- D. It is not possible to enable a single device to be associated with an interface.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 18

An administrator connects two switches together in a local enterprise network. The ports of one switch support Fast Ethernet, while the ports of the other switch support Gigabit Ethernet. Hosts connected to one switch are able to communicate, however communication between the two switches fails.

What is the possible reason for this?

- A. The ports have disabled auto-negotiation.
- B. One port is supporting auto-negotiation, while auto-negotiation is disabled on the port of the other switch.
- C. The port of one switch is operating using half duplex mode, while the port of the other switch is using full duplex mode.
- D. A Fast Ethernet port cannot communicate directly with a Gigabit Ethernet port.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 19

A layer 2 LAN switch generates CAM table entries according to the () of the received frame.

- A. Source MAC address
- B. Destination MAC address
- C. Source IP address
- D. Destination IP address

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 20

Which of the following statements about collision domains and broadcast domains are correct? (Choose three)

- A. Devices connected to the same hub form a collision domain
- B. Devices connected to the same hub form a broadcast domain
- C. Devices connected to the same bridge form a collision domain
- D. Devices connected to the same bridge form a broadcast domain
- E. Devices connected to the same router form a broadcast domain

Correct Answer: ABD Section: (none)
Explanation

Explanation/Reference:

QUESTION 21

Which of the following statements regarding layer-2 switch is incorrect?

- A. The switch learns MAC addresses automatically.
- B. The layer-3 header is modified before the received packet is transmitted.
- C. The layer-2 header is modified before the received packet is transmitted.
- D. The layer-2 LAN switch operates at data link layer.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 22

[R1]display interface GigabitEthernet0/0/0

GigabitEthernet0/0/0 current state: Administratively DOWN

Line protocol current state: DOWN

Refer to the display output. What can be determined based on the output of the display command?

- A. Interface Gigabit Ethernet 0/0/0 is connected to a wrong cable
- B. Interface Gigabit Ethernet 0/0/0 is not associated with an IP address
- C. Interface Gigabit Ethernet 0/0/0 is not associated with a dynamically defined route.
- D. Interface Gigabit Ethernet 0/0/0 has been manually shut down by an administrator.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 23

Which of the following statements regarding static and dynamic routing is incorrect?

- A. The static route can be easily configured and managed on the enterprise network.
- B. The use of dynamic routing is more convenient for the administrator to manage the network following network convergence.
- C. The static route can automatically recover when a link failure is encountered.
- D. Dynamic routing will use more resources than static routes.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 24

Which of the following are routed protocols? (Choose two)

- A. IP
- B. OSPF
- C. BGP
- D. IPX

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 25

Which of the following statements regarding the routing table are correct? (Choose two)



https://www.gratisexam.com/

- A. The next hop in the routing table is redundant because the outgoing interface can be used for packet forwarding.
- B. The routes from generated by different protocols have different preferences.
- C. The metrics of different routing protocols are comparable.
- D. The metrics of different routing protocols are not comparable

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 26

Which of the following commands can be used to display the routing table on a Quidway router?

- A. display ip path
- B. display ip routing-table
- C. display interface
- D. display current-configuration

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 27

Which of the following entries is not included in the routing table?

- A. source address
- B. next hop

- C. destination address
- D. cost

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 28

Which of the following problems are caused by routing loops? (Choose three)

- A. Slow convergence
- B. Packets circulate between routers
- C. Router restarting
- D. Inconsistency of routing information

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 29

An administrator wishes to manage the router in the remote branch office, which method can be used?

- A. Telnet
- B. FTP
- C. Console Connection
- D. DHCP

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 30

The administrator cannot use telnet to manage the AR2200. The administrator is able to verify connectivity to the router and has been informed that other administrators have no difficulties using telnet.

Which statements describe the possible reasons for this problem? (Choose two)

- A. The user's status has been blocked
- B. The user's privilege level has been changed to 0.
- C. The user has been deleted.
- D. The telnet service in the AR2200 router has been disabled.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 31

A user logged into a VRP supported device through telnet, but when attempting to configure the device, found that he is unable to use the system-view command to enter the system-view.

What are the possible reasons for this? (Choose two)

- A. The device's VTY interface only provides permission for some telnet users to run the system-view command.
- B. The user's telnet software restricts use of this command.
- C. The user's privilege level is lower than the level associated with the system-view command.
- D. The system-view command privilege level is lower than the level associated with the user.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 32

The users who log on the router through Telnet are not permitted to configure IP address.

What is the possible reason?

- A. Communication failures occur between the user and the router.
- B. The authentication mode of Telnet is set incorrectly.
- C. Privilege level of Telnet is set incorrectly.
- D. SNMP parameters are set incorrectly.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 33

Which of the following statements are correct? (Choose two)

- A. A single collision domain exists between RTA and SWC.
- B. A single broadcast domain exists between SWA and SWB.
- C. A single collision domain exists between SWA and SWC.
- D. A single broadcast domain exists between SWA and SWC.

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 34

On the interface serial 1/0/1 of RTA, the command "ip address unnumbered interface loopback 0" has been configured.

Which following statements are correct? (Choose two).

- A. The IP address of interface serial 1/0/1 is 10.1.1.1/24
- B. The IP address of interface serial 1/0/1 is 10.1.1.1/32
- C. The route entry 10.1.1.0/24 exists in RTA's routing-table
- D. The route entry 10.1.1.0/24 does not exist in RTA's routing-table

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 35

Refer to the graphic. The host has a problem establishing a telnet connection with the router attached to interface G0/0/0. Which of the following steps can be used to help the administrator identify the problem? (Choose two)

<choice ident="A"> <choice ident="B"> <choice ident="C"> <choice ident="D">

- A. Check whether the host has configured the gateway IP address.
- B. Check whether the switch has configured the gateway IP address.
- C. Use the ping tool to check connectivity between host and router.
- D. Check the telnet server configuration is right on the router.

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 36

Which of the following methods are supported by VRP platform to configure the router? (Choose three)



A. Through the Console port

- B. Through Telnet
- C. Through the AUX port
- D. Through FTP

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 37

The administrator wishes to update the configuration file of an AR2200 router using a USB cable.

How can this be achieved? (Choose two)

- A. The administrator should connect the USB cable between the terminal and the mini USB port of the AR2200 router.
- B. The administrator should connect the USB cable between the terminal and the USB port of the AR2200 router.
- C. The AR2200 router cannot support configuration updates through a USB cable.
- D. The administrator should install the mini USB drivers on the terminal after connecting the USB.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 38

The administrator wishes to manage a network through telnet from a user's terminal to a router.

How can this be achieved?

- A. A connection should be established between the ethernet port of the terminal and the console port of the router.
- B. A connection should be established between the ethernet port of the terminal and the ethernet port of the router.
- C. A connection should be established between the console port of the terminal and the ethernet port of the router.use console cable connect pc's ethernet port and router's console port.
- D. A connection should be established between the COM port of the terminal and the console port of the router.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 39

Whilst configuring a device, an administrator experiences trouble remembering certain commands.

Which of the following will help support the administrator? (Choose two)

A. TAB

B. question mark

C. ctrl+b

D. ctrl+c

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 40

<Huawei> system-view

[Huawei] user-interface console 0

[Huawei-ui-console0] user privilege level 15

[Huawei-ui-console0] authentication-mode password

[Huawei-ui-console0] set authentication password cipher huawei2012

[Huawei-ui-console0] quit

Refer to the configuration output. The administrator configured the device using the commands in the configuration output. Regarding these commands, which statement is false?

- A. The administrator wishes to enable management through the console interface.
- B. Following configuration, the administrator cannot manage the device remotely.

- C. A user that logs-in through the console interface is assigned the highest privilege level.
- D. The password of a user logged in through console is 'cipher huawei2012'.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 41

Which of the following is abbreviation of VRP?

- A. Versatile Routine Platform
- B. Virtual Routing Platform
- C. Virtual Routing Plane
- D. Versatile Routing Platform

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 42

Which of the following must be used to establish the configuration environment when a router is powered on for the first time?

- A. SSL
- B. SSH
- C. Console port
- D. Telnet

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 43

Which of the following parameter settings for terminal emulation are correct when configuring a Huawei router through the Console port?

- A. 4800bps, 8 data bits,1 stop bits, odd parity check, and no flow control
- B. 9600bps, 8 data bits, 1 stop bits, no parity check, and no flow control
- C. 9600bps, 8 data bits, 1 stop bits, even parity check, and hardware flow control
- D. 19200bps, 8 data bits, 1 stop bits, no parity check, and no flow control

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 44

Which of the following commands is used to enter the system-view from the user view on a Huawei router?

- A. system-view
- B. enable
- C. configure terminal
- D. interface system

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 45

On VRP platform, the command lines are classified into four levels in increasing priority: Visit level, Monitoring level, Configuration level, and Management level. At which level, the operator is permitted to configure service but is not permitted to operate the file system?

- A. Visit level
- B. Monitoring level
- C. Configuration level
- D. Management level

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 46

On Huawei VRP platform, which of the following can be used to invoke the history command saved by the command line interface? (Choose two)

<choice ident="A">

<choice ident="B">

<choice ident="C">

<choice ident="D">

A. Up cursor key <>

B. Left cursor key <>

C. Ctrl+P

D. Ctrl+U

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 47

Which of the following commands can be used to view the current configurations on a Huawei router?



https://www.gratisexam.com/

A. display current-configuration

- B. display saved-configuration
- C. view saved-configuration
- D. show startup-configuration

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 48

The administrator wishes to change name of the router. Under which view should the administrator be in order to achieve this?

- A. User-view
- B. System-view
- C. Interface-view
- D. Protocol-view

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 49

<Huawei> system-view [Huawei]command-privilege level 3 view user save

Refer to the command output. What is the result of the shown command?

- A. The command adjusts the save command of a user to privilege level 3.
- B. The command adjusts the save command in the user view to privilege level 3.
- C. The command adjusts the user view command privilege level to 3, and saves the configuration.
- D. The command adjusts the privilege level of a user to 3, and saves the configuration.

Correct Answer: B Section: (none)

Explanation

Explanation/Reference:

QUESTION 50

<Huawei>system-view
[Huawei]history-command max-size 20

Refer to the command output. Which statements regarding the shown command are true? (Choose two)

- A. The command is used to adjust the size of the history command buffer.
- B. The default value of the history command buffer is 5.
- C. The command should be configured in the user-interface view.
- D. Once configured, commands totaling up to 20 bytes can be saved in the buffer.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 51

An AR2200 router is required to be reconfigured from scratch. Which steps are needed to achieve this? (Choose two)

- A. Reset the saved configuration.
- B. Clear the current configuration.
- C. Reboot the AR2200.
- D. Assign the configuration file to be used at next startup.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 52

An administrator has been requested to replace the configuration file of a router in the network. The administrator has been instructed that after logging into the

router, he must first permanently erase the current configuration file config.zip from the system.

Which command should he use to achieve this?

- A. delete /force config.zip
- B. delete /unreserved config.zip
- C. reset config.zip
- D. clear config.zip

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 53

Which of the following commands can switch a view from the system view to the user view?

- A. System-view
- B. Router
- C. Quit
- D. User-view

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 54

Which of the following storage devices are supported by Huawei router? (Select four)

- A. SDRAM
- B. NVRAM
- C. Flash
- D. Hard Disk

E. CF Card

Correct Answer: ABCE

Section: (none) Explanation

Explanation/Reference:

QUESTION 55

Which of the following storage devices is used to store the startup configuration files in a router?

<choice ident="A"> <choice ident="B"> <choice ident="C"> <choice ident="D">

- A. SDRAM
- B. NVRAM
- C. Flash
- D. BootROM

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 56

<Huawei>reset saved-configuration

Warning: The action will delete the saved configuration in the device. The configuration will be erased to reconfigure. Continue? [Y/N]:

Refer to the configuration output. Which of the following statements are true? (Select two answers)

- A. A user should enter 'Y' when wishing to clear the saved configuration file.
- B. The saved-configuration file that the device starts with can be erased.

- C. The saved-configuration will be deleted after typing N
- D. The saved-configuration file will be replaced with the current-configuration.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 57

When a router is powered on, the router reads the configuration file saved in the default save directory to get itself initialized. If the configuration file does not exist in the default save directory, what does the router use to initialize itself?

- A. New configuration file
- B. Initial configuration file
- C. Default parameters
- D. Current configuration file

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 58

<Huawei>display startup

MainBoard:

Startup system software: sd1:/ar2220-v200r003c00spc200.cc Next startup system software: sd1:/ar2220-v200r003c00spc200.cc

Backup system software for next startup: null

Startup saved-configuration file: null Next startup saved-configuration file: null

Startup license file: null Next startup license file: null Startup patch package: null Next startup patch package: null

Startup voice-files: null Next startup voice-files: null

Refer to the display output. Which statement is false?

- A. The current configuration file has not been saved.
- B. The current startup system software is ar2220-v200r003c00spc200.cc
- C. The next startup system software cannot be changed.
- D. The next startup system software can be changed by using the "startup system software <startup-softwarename>.cc" command.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 59

<Huawei>

Warning: Auto-Config is working. Before configuring the device, stop Auto-Config. If you perform configurations when Auto-Config is running, the DHCP, routing, DNS, and VTY configurations will be lost. Do you want to stop Auto-Config? [y/n]:

When an administrator first initializes the router, a warning is displayed. Which statement regarding this warning is correct?



https://www.gratisexam.com/

- A. If Auto-Config is required, the administrator should select 'y'.
- B. If Auto-Config is not required, the administrator should select 'n', for which subsequent configuration of the DHCP server, routing, DNS server and VTY user configuration is lost.
- C. When a device is started for the first time, the Auto-Config function is active.
- D. When a device is started for the first time, the Auto-Config function is inactive.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 60

An AR2200 router in the company network cannot boot. In order to resolve this, the administrator wishes to update the VRP software.

What should he/she do?

- A. The administrator should use a console cable to connect the router and host, and directly upgrade the device.
- B. The administrator should use FTP to transfer the VRP software, by configuring the AR2200 router as an FTP client.
- C. The administrator should use DHCP to boot the AR2200, and then use the AR2200 router as a TFTP client to download the VRP software from the server.
- D. The administrator should use the telnet command on the client to remote access the device, and upgrade the VRP software.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 61

<Huawei>

Warning: Auto-Config is working. Before configuring the device, stop Auto-Config. If you perform configurations when Auto-Config is running, the DHCP, routing, DNS, and VTY configurations will be lost. Do you want to stop Auto-Config? [y/n]:

Refer to the output. When the administrator first starts the router, a system notice is displayed, however after rebooting this router, the notice disappeared. What is the reason for this? (Choose two)

- A. This notice only appears during the very first device startup.
- B. The administrator has configured the device and saved the configuration, causing the notice to disappear.
- C. The administrator selected 'n' and did not save the configuration.
- D. The administrator selected 'y' and saved the configuration.

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 62

An end system is unable to communicate with a DHCP server following the startup process.

Which IP address may be used by the client?

A. 0.0.0.0

B. 127.0.0.1

C. 169.254.2.33

D. 255.255.255.255

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 63

[Huawei]ip pool pool1

Info: It's successful to create an IP address pool.

[Huawei-ip-pool-pool1]network 10.10.10.0 mask 255.255.255.0

[Huawei-ip-pool-pool1]gateway-list 10.10.10.1

Refer to the configuration output. The administrator wishes to configure the DHCP server pool in order to assign an IP address to the customer's terminal device.

Which command should be included in the configuration to provide the minimal lease period for IP addresses?

- A. dhcp select relay
- B. lease day 1
- C. lease 24
- D. lease 0

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 64

A DHCP server has been established in the enterprise network. After the client has obtained an IP address from the DHCP server, the user decided to modify the IP address manually.

In what way may this affect the enterprise network? (Choose two).

- A. The client may experience an IP address conflict.
- B. The client may access the network normally.
- C. The client's interface connection will shutdown.
- D. The client will associate with another DHCP server.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 65

A DHCP server in the enterprise network is being used to allocated IP addresses to hosts. An administrator discovers however that some hosts are obtaining IP addresses outside of the scope of the DHCP server's address pool.

What are the possible reasons for this? (Choose three).

- A. Another DHCP server exists in the network and is allocating IP addresses to hosts that happen to be within a closer proximity than the authorized DHCP server.
- B. The hosts were unable to discover a DHCP server and therefore generated their own address in the 169.254.0.0 address range.
- C. The hosts were unable to discover a DHCP server and therefore generated their own address in the 127.254.0.0 address range.
- D. All addresses from the DHCP pool have been assigned.

Correct Answer: ABD Section: (none)
Explanation

Explanation/Reference:

QUESTION 66

Router-ip-pool-pool1 [Router-ip-pool-pool1] network 10.10.10.0 mask 255.255.255.0 [Router-ip-pool-pool1] gateway-list 10.10.10.1 [Router-ip-pool-pool1] quit

[Router] ip pool pool2

[Router-ip-pool-pool2] network 10.20.20.0 mask 255.255.255.0

[Router-ip-pool-pool2] gateway-list 10.20.20.1

[Router-ip-pool-pool2] quit

[Router] interface GigabitEthernet 0/0/1

[Router-GigabitEthernet0/0/1] ip address 10.10.10.1 24

[Router-GigabitEthernet0/0/1] dhcp select global

Refer to the configuration output. Following configuration, a host is connected to the interface Gigabit Ethernet 0/0/1 of the router. Which IP address will the client obtain?

- <choice ident="A">
 <choice ident="B">
 <choice ident="C">
 <choice ident="D">
- A. An IP address from network 10.10.10.0/24 will be assigned.
- B. An IP address from network 10.20.20.0/24 will be assigned.
- C. The host will be unable to obtain an IP address.
- D. An IP address may be assigned from either 10.10.10.0/24 or 10.20.20.0/24.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 67

The IP addresses of clients in the network are deployed via a DHCP server. When a host reboots, which message will the host first send to the DHCP server?

- A. DHCP DISCOVER
- B. DHCP REQUEST
- C. DHCP OFFER
- D. DHCP ACK

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 68

A DHCP Unique Identifier (DUID) in DHCPv6 can be configured in VRP using which formats? (Choose two).

- A. DUID-LL
- B. DUID-LLT
- C. DUID-EN

D. DUID-LLC

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 69

Which of the following statements about the information contained in a Database Description packet are true? (Choose three)

- A. A Database Description packet contains all information about each LSA.
- B. A Database Description packet contains only the header of an LSA.
- C. The header of an LSA is the unique identifier of the LSA.
- D. The header of an LSA is only a small portion of all the data of the LSA.

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:

QUESTION 70

What is the default authentication mode for the default admin domain?



https://www.gratisexam.com/

- A. None
- B. Local
- C. Radius
- D. 802.1X

Correct Answer: B

Section:	(none)
Explanat	ion

Explanation/Reference:

QUESTION 71

How many domains can be configured on a Huawei router?

- A. 30
- B. 31
- C. 32
- D. 33

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 72

An authenticator router has been configured with two domains named "Area1" and "Area2", following which a user is created with the username "huawei" and the password "hello" for authentication. Which domain does this user belongs to?

- <choice ident="A"> <choice ident="B"> <choice ident="C"> <choice ident="D">
- A. Area1 domain
- B. Area2 domain
- C. default domain
- D. default admin domain

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 73

In order to check if the interface serial 1/0/0 is working in either DCE or DTE mode, command () is used.

- A. display mode serial 1/0/0
- B. display controller
- C. display interface serial 1/0/0
- D. display current-config

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 74

How is mapping performed on a DTE device in a Frame Relay network?

- A. The local DLCI number is mapped to a remote IP address.
- B. The local IP address is mapped to a remote DLCI number.
- C. The local DLCI number is mapped to a local IP address.
- D. The remote DLCI number is mapped to a remote IP address.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 75

If Frame Relay implements dynamic address mapping for the PVC, which protocol will be used?

- A. LMI protocol
- B. ARP protocol

- C. RARP protocol
- D. InARP protocol

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 76

Which command should be used to check the mapping between protocol addresses and frame relay addresses?

- A. display fr interface
- B. display fr map-info
- C. display fr inarp-info
- D. display interface brief

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 77

Which of the following protocols is used in Frame Relay to map the address to DLCI dynamically?

- <choice ident="A">
- <choice ident="B">
- <choice ident="C">
- <choice ident="D">
- A. ARP protocol
- B. RARP protocol
- C. InARP protocol
- D. Map protocol

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 78

Which of the following parameters must be specified when configuring static mapping for Frame Relay network? (Choose two)

- A. Local DLCI
- B. Remote DLCI
- C. Local network layer protocol address
- D. Remote network layer protocol address

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 79

Which of the following regarding Frame Relay DLCI are correct? (Choose three)

- A. DLCI is locally significant
- B. DLCI is allocated by DTE
- C. The range of DLCI value that can be used is from 16-1007
- D. The same DLCI can be configured on different physical interfaces

Correct Answer: ACD Section: (none) Explanation

Explanation/Reference:

QUESTION 80

Which of the following commands is used to enable dynamic address mapping protocol in the interface encapsulated with Frame Relay?

- A. fr inarp
- B. fr reverse-arp
- C. inverse-arp
- D. reverse-arp

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 81

What is the meaning of 200 in the command "fr map ip 10.1.1.2 200"?

- A. remote logical channel ID
- B. local DLCI
- C. remote interface ID
- D. remote node ID

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 82

Which of the following commands can be used to display mapping relationship between network address and DLCI?



https://www.gratisexam.com/

- A. display fr interface
- B. display fr

- C. display fr map-info
- D. display fr brief

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 83

Which of following may be the reasons that cause Frame Relay PVC to work abnormally? (Choose three)

- A. Same DLCI number is configured on the same router
- B. LMI type mismatch
- C. Frame Relay encapsulation type mismatch
- D. Incorrect configuration of the DLCI number

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:

QUESTION 84

An administrator wishes to update the VRP software of company's AR2200 router. How can this be achieved? (Choose three)

- A. The administrator can use FTP to transfer the VRP software, with the AR2200 router as the FTP client.
- B. The administrator can use FTP to transfer the VRP software, with the AR2200 router as the FTP server.
- C. The administrator can use TFTP to transfer the VRP software, with the AR2200 router as the TFTP server.
- D. The administrator can use TFTP to transfer the VRP software, with the AR2200 router as the TFTP client.

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 85

An administrator wishes to implement new features in the network, but the VRP version of one AR2200 router is out of date. The administrator needs to upgrade the VRP software.

Which of the following options regarding file transfer is false?

- A. The AR2200 router can function as a TFTP client to support the upgrade.
- B. The AR2200 router can function as the TFTP server to support the upgrade.
- C. The AR2200 router can function as the FTP server to support the upgrade.
- D. The AR2200 router can function as an FTP client to support the upgrade.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 86

FTP and TFTP can be used to update the system file on Huawei routers. Which of the following statements are correct? (Choose three)

<choice ident="A"> <choice ident="B"> <choice ident="C"> <choice ident="D">

- A. Huawei router can be configured as FTP Client
- B. Huawei router can be configured as FTP Server
- C. Huawei router can be configured as TFTP Client
- D. Huawei router can be configured as TFTP Server

Correct Answer: ABC Section: (none)
Explanation

Explanation/Reference:

QUESTION 87

An administrator discovered he/she was unable to use TFTP to transfer files to the router.

Which of the following describes the likely reason for this?

- A. The TFTP service had been disabled on the router.
- B. TCP port 69 of the server had been blocked.
- C. UDP port 69 of the server had been blocked.
- D. The username and password had been modified.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 88

FTP may be used to upgrade a router's VRP image.

Which of the following transmission modes should be used to achieve this?

- A. binary mode
- B. ASCII mode
- C. byte mode
- D. letter mode

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 89

A client failed to transfer a file to the FTP server, but found the IP connectivity was without problem. The client assumed that the problem was with the port configuration.

The blocking of which ports would likely cause this problem? (Choose two)

- A. 21
- B. 80
- C. 20
- D. 50649

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 90

When using VRP, which of the following commands is used to configure the data link layer encapsulation type of a serial interface as HDLC?

- A. encapsulation hdlc
- B. link-protocol hdlc
- C. hdlc enable
- D. link-protocol ppp

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 91

A configured internal host of a private network wishes to access the internet. What must be configured on the enterprise network's edge router in order to achieve this? (Choose two)

- A. NAT EasyIP
- B. DHCP
- C. BGP
- D. Default route

Correct Answer: AD

Section: (none) Explanation

Explanation/Reference:

QUESTION 92

Which of the following statements are correct about NAT? (Choose three)

- A. NAT is the abbreviation for "Network Address Translation".
- B. NAT is used for translation between private and public network addresss.
- C. When hosts inside a private network access the outside network, NAT is not required.
- D. NAT provides an effective way to solve the problem of insufficient IP addresses.

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 93

Which of the following technologies can allow a host with IP address 10.0.0.1 to access the internet?

- A. Static route
- B. Dynamic route
- C. Route import
- D. NAT

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 94

Which of the following items can be translated by NAPT?



https://www.gratisexam.com/

- A. MAC address + port number
- B. IP address + port number
- C. Only MAC address
- D. Only IP address

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 95

Which of the following statements about a designated port working in RIPv2 multicast mode are true? (Choose three)

- A. The port receives only RIPv2 multicast packets.
- B. The port does not receive RIPv1 broadcast packets.
- C. The port does not receive RIPv2 broadcast packets.
- D. The port receives only RIPv1 multicast packets.

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 96

Which of the following statements regarding the router ID in OSPF are incorrect? (Choose three)

- A. The router IDs of OSPF routers in the same area must be the same, but can be different in different areas.
- B. The router ID must be the IP address of an OSPF router interface.

- C. The router ID must be configured manually.
- D. A router running OSPF must have a router ID for it to operate properly.

Correct Answer: ABC Section: (none)
Explanation

Explanation/Reference:

QUESTION 97

Which of the following statements regarding Designated Routers in OSPF are correct? (Choose three)

- A. DR is elected by all the routers in the same network segment.
- B. If the priorities of two routers are different, the router with the lower priority will be elected as DR.
- C. If the priorities of two routers are equal, the router with the higher Router ID will be elected as DR.
- D. DR and BDR must be adjacent.

Correct Answer: ACD Section: (none) Explanation

Explanation/Reference:

QUESTION 98

On the VRP platform, which of the following commands is used to configure the Router ID of a router as 1.1.1.1?

- A. <Huawei>router id 1.1.1.1
- B. [Huawei]router id 1.1.1.1
- C. [Huawei]router-id 1.1.1.1
- D. [Huawei]router id 1.1.1.1 255.255.255.255

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 99

Which of the following OSPF versions is specific to IPv6?

- A. OSPFv1
- B. OSPFv2
- C. OSPFv3
- D. OSPFv4

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 100

The administrator wishes to configure OSPF on a router in the network however the router has no loopback interface.

Which value will be used as the router ID?

- A. The lowest IP address of the router's active interfaces.
- B. The highest IP address of the router's active interfaces.
- C. The IP address of the management interface.
- D. The priority value of the router.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 101

An administrator of a company supporting a large enterprise network wishes to implement OSPF on the network as opposed to RIP. Which of the following points should the administrator use to support his reasoning for this change? (Choose three)

- A. OSPF has no hop count limitation.
- B. OSPF has a lower routing update overhead.

- C. OSPF has a simpler configuration.
- D. OSPF supports faster convergence.

Correct Answer: ABD Section: (none)
Explanation

Explanation/Reference:

QUESTION 102

Which of the following statements regarding single area OSPF are correct? (Choose three)

- A. An IP address needs to be configured on a loopback interface of each router before configuring an OSPF area.
- B. The value of an area can be from 0.0.0.0 to 255.255.255.255.
- C. A single area can be configured using any supported area number.
- D. All of the links of the network need to be advertised in Area 0.

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:

QUESTION 103

10.0.1.0/24 O_ASE 150 2 D 10.0.23.3 Serial2/0/0

Refer to the display output. Which of the following statements regarding route shown are true? (Choose two)

- A. The address 10.0.23.3 has been configured on the peer's serial 2/0/0 interface.
- B. The route preference has been changed by the administrator.
- C. The metric for the route 10.0.1.0 indicates that two hops are needed.
- D. The route has been learned via the OSPF protocol.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 104

Which of the following statements regarding link-state database and routing-table of a "single" OSPF area are correct? (Choose two)

- A. The link-state databases that all routers build are identical.
- B. The link-state databases that all routers build are different.
- C. The routing-tables that all routers calculate are different.
- D. The routing-tables that all routers calculate are identical.

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 105

Which of the following steps are necessary to configure OSPF on a Huawei router? (Choose three)

- A. Configuration of a router ID
- B. Enabling of an OSPF process
- C. Specifying an OSPF area
- D. Configuration of the network segments within each area

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:

QUESTION 106

Which of the following statements regarding the DR in an OSPF network are correct? (Choose two)

- A. There must be at least one DR in an OSPF area.
- B. A DR must be elected among the routers through the negotiations that are defined by OSPF protocol.
- C. Only the router with highest priority will be elected as DR.

D. Only NBMA or Broadcast networks need to elect DR.

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 107

Which of the following VRP commands can be used to enter area 0 view? (Choose two)



- A. [Huawei]ospf area 0
- B. [Huawei-ospf-1]area 0
- C. [Huawei-ospf-1]area 0.0.0.0
- D. [Huawei-ospf-1]area 0 enable

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 108

Which of the following commands is used to display the OSPF neighbor relationship establishment?

- A. display ospf neighbor
- B. display ospf brief
- C. display ospf peer
- D. display ospf interface

Correct Answer: C

Section: (none) Explanation
Explanation/Reference:
QUESTION 109 With what kind of routers does a DRother router exchange link state information and route information? (Choose two)
A. DRB. BDRC. DRotherD. All OSPF neighbors
Correct Answer: AB Section: (none) Explanation
Explanation/Reference:
QUESTION 110 An OSPF area is a collection of a group of routers and networks. OSPF defines that routers that have the same () belong to the same OSPF area.
A. neighbors B. LSDB C. LSA D. adjacency
Correct Answer: B Section: (none) Explanation
Explanation/Reference:
QUESTION 111 Which of the following statements about router IDs are true? (Choose two)

- A. The routers contained in the same LSDB have the same router ID.
- B. Each router in an OSPF network must have a unique router ID.
- C. Two routers in different OSPF areas can have the same router ID.
- D. A router ID is expressed in a 32-bit dotted decimal format.

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 112

OSPF allows for "multiple" processes. By default, OSPF selects a process whose number is ().

- A. 0
- B. 1
- C. 10
- D. 100

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 113

In a network supporting IPv6, OSPF no longer supports which feature?

- A. multiple areas
- B. Router-ID
- C. authentication
- D. multicast updates

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 114

Two routers are configured with OSPFv3. OSPFv3 is enabled on all interfaces of each router.

Which of the following is true in the event that the network administrator does not configure a Router-ID?

- A. The IP address of the loopback 0 interface will be used as the router ID.
- B. The IP address of the loopback 1 interface will be used as the router ID.
- C. The IP address of interface G0/0/0 will be used as the router ID.
- D. No router ID will be assigned to the router.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 115

Destination/Mask protocol pre Cost Nexthop Interface

9.0.0.0/8 OSPF 10 50 1.1.1.1 Serial 1/0/0 9.1.0.0/16 RIP 100 5 2.2.2.2 Ethernet 0/0/1

Refer to the graphic. Which of the following statements is correct when this router forwards the packet to the destination host 9.1.4.5?



- A. The router selects the first entry to match the destination address of the packet because the preference of OSPF is higher than the preference of RIP.
- B. The router selects the second entry to match the destination address of the packet because the cost of RIP is lower than that of OSPF.

- C. The router selects the second entry to match the destination address of the packet because the outgoing interface is an Ethernet interface. The forwarding speed of an Ethernet interface is faster than the forwarding speed of a serial interface
- D. The router selects the second entry to match the destination address of the packet because the router will match the most specific address.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 116

According to the default value of route preference on the VRP platform, which of the following represent the correct sequence for direct route, static route, RIP and OSPF if they are listed from high preference to low preference?

- A. Direct, Static, RIP, OSPF
- B. Direct, OSPF, Static, RIP
- C. Direct, OSPF, RIP, Static
- D. Direct, RIP, Static, OSPF

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 117

A router has learned two routes for the same network with the same prefix. One route has been learned via OSPF with a metric of 4882, while the other route has been learned via RIPv2 with a metric of 4.

Which route (s) will be found in the routing table?

- A. The RIPv2 route.
- B. The OSPF and RIPv2 routes.
- C. The OSPF route.
- D. Neither of these routes will be found in the routing table.

Correct Answer: C

Se	ction:	(n	one)
Ex	plana	tio	n

Explanation/Reference:

QUESTION 118

Assume that the router has learnt the best route to the same destination by using RIP, OSPF and Static Route respectively. By default, the Huawei router will select the route learnt via () as the best route.

- A. RIP
- B. OSPF
- C. RIPv2
- D. Static route

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 119

After checking the OSPF neighbor state, the administrator discovers that the router has established a TWOWAY state with the peering router.

What can be understood from this information? (Choose two)

- A. The routers are configured using the same process ID
- B. The routers are configured using the same area ID
- C. The routers are configured using wrong router ID
- D. The routers are considered DROthers in a broadcast network

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 120

What functions does a Hello packet of OSPF implement? (Choose two)

- A. Neighbor discovery
- B. Deletion of unreachable neighbors
- C. Maintaining of neighbor relationships
- D. Negotiation of parameters among adjacent ports

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:





Huawei.Premium.H12-211.by.VCEplus.201q

Number: H12-211 VCEplus

Passing Score: 800 Time Limit: 120 min File Version: 6.1



VCEplus

VCE To PDF - Free Practice Exam

Exam Code: H12-211

Exam Name: HCNA-HNTD (Huawei Certified Network Associate-Huawei Network Technology and Device)

Certification Provider: Huawei

Corresponding Certification: HCNA-HNTD

Website: www.vceplus.com

Free Exam: https://vceplus.com/exam-h12-211-hcna-hntd/

Questions & Answers Exam Engine is rigorously checked before being put up for sale. We make sure there is nothing irrelevant in H12-211 exam products and you get latest questions. We strive to deliver the best H12-211 exam product for top grades in your first attempt.

VCE to PDF Converter: https://vceplus.com/vce-to-pdf/Facebook: https://www.facebook.com/VCE.For.All.VN/

Twitter: https://twitter.com/VCE_Plus

Google+: https://plus.google.com/+Vcepluscom **LinkedIn:** https://www.linkedin.com/company/vceplus



QUESTION 1

An administrator currently manages AR2200 devices in the network through a single password, however the company wishes to introduce another two administrators and provide unique user credentials and privilege levels for telnet access to the network devices. What action can be taken? (choose three)

- A. Configure three users under the AAA-view, and assign each a different password.
- B. The authentication mode must be changed to AAA.
- C. Each administrator must be assigned a privilege level.
- D. A public IP address must be assigned to each user for telnet access

Correct Answer: ABC Section: (none) **Explanation**

Explanation/Reference:

QUESTION 2
Which of the following authentication methods are supported for Telnet users? (Choose three)

- A. Password authentication
- B. AAA local authentication
- C. MD5 authentication
- D. No authentication

Correct Answer: ABD Section: (none) **Explanation**

Explanation/Reference:

QUESTION 3

Which authentication modes does AAA support? (Choose three)

- A. None
- B. Local



C. Radius

D. 802.1X

Correct Answer: ABC Section: (none) **Explanation**

Explanation/Reference:

QUESTION 4

[RTA]aaa


[RTA-aaa]domain huawei

[RTA-aaa-domain-huawei]authentication-scheme au1 [RTA-aaa-domain-huawei]authentication-scheme au2

Refer to the configuration output. RTA has been configured using AAA as shown, and associated with the "huawei" domain. For users in the huawei domain, which authentication-scheme will be used?

A. au1

B. au2



D. au2 will be used when au2 is deleted, users will use au1

Correct Answer: B Section: (none) **Explanation**

Explanation/Reference:

QUESTION 5

A user accesses a server supporting AAA, for which the authorization mode on the AAA server has been configured using the command "authorization-mode hwtacacs if-authenticated".

Which of the following statements regarding this command are true? (Choose three).

- A. If the hwtacacs server fails to respond, the user will be authenticated using local authentication.
- B. If the hwtacacs server fails to respond, the user will be authenticated using remote authentication.
- C. If the hwtacacs server fails to respond, the user will bypass authentication.
- D. The hwtacacs server will authorize the user.



Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:

QUESTION 6

Which of the following descriptions regarding eSight is not correct?

- A. eSight is used to monitor and manage enterprise networks.
- B. eSight supports only Huawei devices.
- C. eSight supports WLAN management and monitoring of hotspot coverage.
- D. eSight supports the backup of configuration flies and network traffic analysis

Correct Answer: B Section: (none) Explanation





QUESTION 7

what of the following statements is correct regarding access control list types and ranges?

- A. A basic ACL value ranges from 1000-2999
- B. An advanced ACL value ranges from 3000-4000
- C. A layer 2 ACL value ranges from 4000-4999
- D. An interface ACL value ranges 1000-2000

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 8



Which of the following parameters is not used by Advanced ACL?

- A. Source interface
- B. Destination port number
- C. Protocol number
- D. Time-range

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 9

[RTA]acl 2001 [RTA-acl-basic-2001]rule permit source 10.0.1.0.0.0.0.255 [RTA-acl-basic-2001]rule deny source 10.0.1.0.0.0.0.255

[Refer to the configuration output. Which of the following statements regarding ACL 2001 is correct?

- A. Packets from network 10.0.1.0/24 network will be denied VCE To PDF Free Practice Exam
- B. Packets from network 10.0.1.0/24 network will be permitted.
- C. Packets destined for network 10.0.1.0/24 will be denied.
- D. Packets destined for network 10.0.1.0/24 will be permitted.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 10

[RTA]acl 2002 [RTA-acl-basic-2002]rule permit source 20.1.1.1 0 [RTA-acl-basic-2002]rule permit source 30.1.1.1 0

Refer to the configuration output. A network administrator configured the ACL on router RTA, as shown. Which of the following statements regarding the rule order are correct? (Choose two).



- A. The rule-number of the first rule is 1
- B. The rule-number of the first rule is 5
- C. The rule-number of the second rule is 2
- D. The rule-number of the second rule is 10

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 11

Following a failure of services in the network, an administrator discovered that the configuration in one of the enterprise routers had been changed What actions can be taken by the administrator to prevent further changes? (Choose three)

- A. The administrator should limit access by setting the login privilege of users to 0.
- B. The administrator should configure AAA to manage user authorization on the router.
- C. The administrator should configure an ACL to allow only the administrator to manage the router.
- D. The administrator should configure port-security on the router CE To PDF Free Practice Exam

Correct Answer: ABC Section: (none) Explanation

Explanation/Reference:

QUESTION 12

[RTA]acl 2001 [RTA-acl-basic-2001]rule 20 permit source 20.1.1.0 0.0.0.255 [RTA-acl-basic-2001]rule 10 deny source 20.1.1.0 0.0.0.255

Refer to the configuration output. Which of the following statements is correct regarding the configuration of the ACL on RTA?

- A. Packets from network 20.1.1.0/24 network will be denied.
- B. Packets from network 20.1.1.0/24 network will be permitted.
- C. Packets destined for network 20-1.1.0/24 will be denied



D. Packets destined for network 20.1.1.0/24 will be permitted.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 13

[RTA]acl 2001 [RTA-acl-basic-2001]rule deny source 172.16.1.1 0.0.0.0 [RTA-acl-basic-2001]rule deny source 172.16.0.0 0.255.0.0

Refer to the configuration output. Which of the following statements are correct regarding the configuration of the ACL on RTA? (Choose two)

- A. Packets from network 172.16.1.1/32 will be denied.
- B. Packets from network 172.16.1.0/24 will be denied
- C. Packets from network 172.17.1.0/24 will be denied.
- D. Packets from network 172.18.0.0/16 will be denied.

Correct Answer: AD Section: (none) Explanation



Explanation/Reference:

QUESTION 14

The network administrator wants to improve the performance of network transmission, what steps can the administrator take? (Choose two)

- A. Change the work mode to full duplex of each end station.
- B. Link the end stations together using a switch
- C. Change the work mode to half duplex of each end station.
- D. ã—ink the end stations together using a hub

Correct Answer: AB Section: (none) Explanation



Explanation/Reference:

QUESTION 15

On Huawei switch, which of the following commands can be used to set port duplex mode as "auto negotiation"? (Choose two)

- A. duplex negotiation auto
- B. duplex auto-negotiation
- C. duplex auto
- D. undo duplex

Correct Answer: CD Section: (none) Explanation

Explanation/Reference:

QUESTION 16

The network administrator wishes to transmit data between two end stations. The network interface cards of both devices operates at 100Mbps however one supports half duplex while the other uses full duplex mode.

What will occur as a result?

VCE TO PDF - Free Practice Exam

- A. The end stations cannot communicate.
- B. The end stations can communicate, but data may be lost during transmission of large amounts of traffic.
- C. The end stations will operate normally
- D. The end stations can communicate, but speed is different during transmission of large amounts of traffic.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 17

An Ethernet port can work one of three duplex modes, whereas an Optical Ethernet port only supports one single mode Which of the following represents this mode?



- A. Full-duplex
- B. Half-duplex
- C. Auto-negotiation
- D. Simplex

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 18

While inspecting packets in the network, a network administrator discovers a frame with the destination MAC address of 01-00-5E-A0-B1-C3. What can the administrator determine from this?

- A. The MAC address is a unicast address.
- B. The MAC address is a broadcast address
- C. The MAC address is a multicast address.
- D. The MAC address is incorrect.



Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 19

According to OSI reference model which layer is responsible for end to end error checking and flow control?

- A. Physical layer
- B. Data link layer
- C. Network layer
- D. Transport layer

Correct Answer: D Section: (none)



Explanation

Explanation/Reference:

QUESTION 20

Which of the following mechanisms are used for flow control? (Choose three)

- A. Acknowledgement
- B. Buffering
- C. Source quench messages
- D. Windowing

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:

VCE To PDF - Free Practice Exam

QUESTION 21

Source Destination Protocol Info 10.0.12.1 10.0.12.2 TCP 50190 > telnet [SYN] Seq=0 Win=8192 Len=0 MSS=1460 10.0.12.2 10.0.12.1 TCP telnet> 50190 [SYN, ACK] Seq=0 Ack=1 Win=8192 Len=0 MSS=1460 10.0.12.1 10.0.12.2 TCP 50190 > telnet [ACK] Seq=1 Ack=1 Win=8192 Len=0

Refer to the capture output. The administrator has captured three packets in the network. Which statement regarding the captured packets is incorrect?

- A. This packets represent a TCP three-way handshake process.
- B. 10.0.12.1 is the telnet server, while 10.0.12.2 is the telnet client,
- C. The three packets contain no application data.
- D. 10.0.12.1 uses port 50190 to buid the telnet connection.

Correct Answer: B Section: (none) Explanation



QUESTION 22

An Ethernet frame is captured by network protocol analyzer tool and the value of Type/Length field is 0x0800. Which of the following statements about the frame are correct? (Choose two)

- A. The frame structure of the frame is Ethernet_II
- B. The frame structure of the frame is 802.3
- C. Its upper layer protocol is IP
- D. Its upper layer protocol is IPX

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 23

Which of the following descriptions regarding the TTL field of the IP packet is correct?

- A. The TTL defines how many packets the source can send
- B. The TTL defines the duration during which the source can send packets.
- C. The TTL value will decrement by 1 each time the packet is routed.
- D. The TTL value will increment by 1 each time the packet is routed

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 24

Which of the following statements are correct about TTL field in IP packet? (Choose two)

<choice ident="A">

<choice ident="B">

<choice ident="C">

<choice ident="D">



- A. The maximum value of TTL is 65535.
- B. Normally, it's impossible for a router to receive a packet whose TTL is zero.
- C. The main purpose of TTL is to prevent IP packets from circulating endlessly in a network which can consume a lot of bandwidth.
- D. TTL value will be decremented as a packet is passed through the network devices such as hub, LAN switch and router.

Correct Answer: BC Section: (none) **Explanation**

Explanation/Reference:

QUESTION 25

In the case of Huawei router, what is the "-i" parameter in a Ping command issued on a VRP operating system used to set?

- A. Interface for sending an Echo Request packet
- B. Source IP address for sending an Echo Request packet
- C. Interface for receiving an Echo Reply packet

D. Destination IP address for receiving an Echo Reply packet VCEPIUS VCE To PDF - Free Practice Exam

Correct Answer: A Section: (none) **Explanation**

Explanation/Reference:

QUESTION 26

To provide the information about the IP addresses that a user packet traverses along the path to the destination, which of the following does Tracert record in each expired ICMP TTL packet?

- A. Destination port
- B. Source port
- C. Destination address
- D. Source address

Correct Answer: D Section: (none)



Explanation

Explanation/Reference:

QUESTION 27

Which of the following statements regarding the verification of IP connectivity are false? (Choose three)

- A. The ping 127.0.0.1 command can be used to check whether the network cable is correctly inserted into the host's Ethernet port.
- B. The ping command with the host IP address as the destination can be used to verify that the TCP/IP protocol suite is functioning correctly.
- C. The ping command can be used to verify connectivity between the host and the local gateway.
- D. The command "ipconfig /release" can be used to check connectivity problems between the host and the local gateway.

Correct Answer: ABD Section: (none) Explanation

Explanation/Reference:



QUESTION 28

A network administrator uses the ping command to check for points of failure in the network ce Exam Which protocols will be used during this process? (Choose two)

<choice ident="A">

<choice ident="B">

<choice ident="C">

<choice ident="D">

- A. ICMP
- B. TCP
- C. ARP
- D. UDP

Correct Answer: AC Section: (none) Explanation



QUESTION 29

A network administrator recently used tracert to trace the path to the destination IP address of an external website, however the trace path displayed only a timeout result.

Which of the following statements correctly explains the reason for this? (Choose two)

- A. The source router had shutdown the ICMP function.
- B. This destination IP address does not exist.
- C. The gateway cannot find a route to the destination.
- D. This is a normal phenomenon.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 30

Ping 10.0.0.2: 56 data bytes, press CTRL_C to break
Reply from 10.0.0.2: bytes=800 Sequence=1 ttl=255 time=2 ms
Reply from 10.0.0.2: bytes=800 Sequence=2 ttl=255 time=10 ms
--- 10.0.0.2 ping statistics --2 packet(s) transmitted
2 packet(s) received
0.00% packet loss
round-trip min/avg/max = 2/6/10 ms



A network administrator uses the ping command to test connectivity to the destination 10.0.0.2 on a Huawei AR series router Which statement regarding the output is correct?

- A. The network administrator used the command ping -c 2 -s 800 10.0.0.2
- B. The network administrator used the command ping -a 2 -v 800 10 0.0 2
- C. The path between the source and destination is not OK.
- D. The network administrator changed the default TTL value.

Correct Answer: A Section: (none) Explanation



QUESTION 31

Which of the following statements explains the behavior of the ICMP redirect function? (Choose two)

- A. When a router receives data on the interface via which the same data needs to be forwarded, and the source is on the same segment as the next hop, an ICMP redirect message will be sent by the router to the source.
- B. When a router receives data on an interface, and the router's IP address matches the destination IP of the data, an ICMP redirect message will be sent by the router to the source.
- C. When a router receives data on the interface via which the same data needs to be forwarded, and the source is on the same segment as the next hop, an ICMP Redirect message will be sent by the source to the router.
- D. When a router receives data on the interface via which the same data needs to be forwarded, and the source is on a different segment from the next hop, an ICMP redirect message will be sent by the router to the source

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:



QUESTION 32

Host A wishes to send data to host c, and generates an ARP request to obtain the destination MAC address. Which statement is true?

- A. The destination IP address of the ARP request is Host c.
- B. The destination MAC address of this ARP request is Host c.
- C. The destination IP address for the ARP request is a broadcast IP address.
- D. The destination MAC address of this frame is the MAC address of G0/0/0 on RTA.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 33

An ARP request is sent by host A to obtain the destination MAC address of host D. Which statement is true about regarding the ARP reply?



- A. The destination MAC address of this frame is the MAC address of Switch A.
- B. The destination IP address of this packet is the VLANIF1 IP address of Switch A
- C. The destination MAC address of this frame is the MAC address of Host A.
- D. The destination IP address of this packet is a broadcast IP address.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 34

Which of the following applications can be used to detect the path along which the data packets are transmitted from the source to the destination?

<choice ident="A">

<choice ident="B">

<choice ident="C">

<choice ident="D">

- A. Route
- B. Netstat
- C. Tracert
- D. Send

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 35

How many probe packets are sent for each TTL value by default when "tracert" is used to detect the path along which packet is sent from source to destination?

- A. 3
- B. 4
- C. 6
- D. 8

	V	C	E	p	lι	1	S
VCE	To I	PDF -	Free	Pra	ctice	Exa	am



Correct Answer: A				
Section: (none)				
Explanation				

Explanation/Reference:

QUESTION 36

Which of the following types can ICMP packets be classified into? (Choose two)

- A. ICMP transport packet
- B. ICMP error reporting packet
- C. ICMP query packet
- D. ICMP application packet

Correct Answer: BC Section: (none) Explanation





QUESTION 37

On VRP platform, which of the following parameters can be used together with the "ping" command to specify the source address of an echo request message?

- A. A
- B. s
- C. D
- D. N

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 38



A router functioning as a Proxy receives an ARP request packet, but finds that the destination address in the packet is not intended for itself. In this case, what will the router do? (Choose two)

- A. Discard the packet.
- B. Check for a route that matches the destination address.
- C. Forward its MAC address to the ARP request sender after finding that a route to the destination address is available.
- D. Broadcast the ARP request packet.

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 39

Two end stations in a point-to-point network perform address resolution. Which of the following statements is correct?

- A. The destination address of an ARP request from each station will be a unicast MAC address.
- B. The destination address of an ARP request from each station will be a broadcast IP address.
- C. The destination address of an ARP reply from each station will be a unicast MAC address.
- D. The destination address of an ARP reply from each station will be a broadcast MAC address,

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 40

What will the destination MAC address be at the moment a frame is transmitted by the host, when the router is the IP destination?

- A. The MAC address of the switch.
- B. The MAC address of the router interface G0/0/0.
- C. The MAC address of the host.
- D. The destination MAC address will be a broadcast MAC address.



Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 41

Which of the following statements about gratuitous ARP packets are true? (Choose two)

- A. A system can determine whether conflicting IP addresses are used by sending a gratuitous ARP packet
- B. A gratuitous ARP packet uses the same format as an ARP request packet.
- C. A gratuitous ARP packet can help to update an IP address.
- D. A gratuitous ARP packet uses the same format as an ARP reply packet.

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:



QUESTION 42

UDP is connectionless oriented, which of the following must be used in order to ensure reliability?

- A. Internet Protocol
- B. Application Layer Protocol
- C. Network Layer Protocol
- D. Transmission Control Protocol

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 43

The administrator has configured an IP address for Host A and Host B, but had forgotten to configure a default gateway



What effect will this have on the hosts?

- A. Neither host will be affected, and therefore will be able to communicate with the peer.
- B. Host A will be unable to connect to the router's G0/0/0 interface.
- C. Hosts will be unable to communicate unless arp-proxy is enabled on the router.
- D. The host will be unable to reach neither the local nor remote network destinations.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 44

A host has established a telnet connection with the router attached to interface G0/0/0. Which of the following statements are correct? (Choose two)

- A. The destination address of a frame sent by the host will be the MAC address of the router interface.
- B. The destination address of a frame will be the MAC address of the switch interface,
- C. The destination port number in a segment header will have a value of 80F Free Practice Exam
- D. The destination IP address of a packet will be the IP address of the network interface of the router.

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 45

The administrator uses the ping command on the host to test connectivity to the website www.huawei.com The command line shows a request time out. The administrator displays the ARP entries for the host. Which entry will be found in the ARP cache table of the host?

- A. The MAC address of the destination www.huawei.com will exist in the ARP cache.
- B. The MAC address of the switch will exist in the ARP cache.
- C. The IP address of the destination WWW huawei.com will exist in the ARP cache.
- D. The MAC address of router interface G0/0/0, will exist in the ARP cache.



Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 46

When R2 forwards data to R3 from R1, which of the following items will change? (choose two)

- A. The source MAC address
- B. The destination MAC address
- C. The source IP address
- D. The destination IP address

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:



QUESTION 47

If Host B also configured the IP address as "192.168.1.1/241", an IP address config will occur. What will happen as a result?

- A. Host B will send an ICMP request to the destination with the configured IP address. If a reply is received, the host will notify of an address conflict.
- B. Host A will send a gratuitous ARP request to resolve the MAC address of the destination 192.168.1.1, for which Host B will reply.
- C. Host B will send a gratuitous ARP request to resolve the MAC address of the destination 192.168.1.1, for which Host A will reply.
- D. Host A will ignore any received ARP request intended for destination 192.168.1.1.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 48



Refer to the graphic. A switch attempts to forward a frame to the MAC destination 5489-98ec-f01. What operation will occur on the switch?

<quidway>display mac-address</quidway>	
MAC Address VLAN/VSI Learned-From Type	
5489-98ec-f018 1/- GE0/0/13 dynamic	
Total items displayed = 1	

- A. The switch will send a request to obtain the MAC address of 5489-98ec-f011.
- B. The switch will report that the destination is unreachable and report this to the source.
- C. The switch will flood the frame via all ports, with exception of the port on which the frame was received.
- D. The switch will drop the frame because it does not have an entry in its MAC address table.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:



QUESTION 49

Host A has been connected to switch A and configured with an IP address. When Host A initially forwards a frame, what action will be taken by Switch A?

- A. Switch A will drop this frame.
- B. Switch A will attempt to flood the frame to all ports except for the G0/0/1 interface.
- C. Switch A will forward the frame via ports G0/0/1, G0/0/2 and G0/0/3.
- D. Switch will receive this frame before returning the frame to G0/0/1.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 50

A server is linked to port interface G0/0/1 of a switch. The administrator wishes to allow only this server to be linked to this interface on the switch.



Which method can be used to achieve this?

- A. Configure a static ARP entry using the server's IP address and MAC address in the switch.
- B. Configure a static MAC address binding entry of the server's MAC address and the interface in the switch,
- C. Configure the default gateway of the switch to be the same as the server's IP address.
- D. It is not possible to enable a single device to be associated with an interface.

Correct Answer: B Section: (none) **Explanation**

Explanation/Reference:

QUESTION 51

An administrator connects two switches together in a local enterprise network. The ports of one switch support Fast Ethernet, while the ports of the other switch support Gigabit Ethernet. Hosts connected to one switch are able to communicate, however communication between the two switches fails. What is the possible reason for this?



- A. The ports have disabled auto-negotiation.B. One port is supporting auto-negotiation, while auto-negotiation is disabled on the port of the other switch.
- C. The port of one switch is operating using half duplex mode, while the port of the other switch is using full duplex mode.
- D. A Fast Ethernet port cannot communicate directly with a Gigabit Ethernet port.

Correct Answer: A Section: (none) **Explanation**

Explanation/Reference:

QUESTION 52

A layer 2 LAN switch generates CAM table entries according to the 0 of the received frame.

- A. Source MAC address
- B. Destination MAC address
- C. Source IP address
- D. Destination IP address



Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 53

Which of the following statements about collision domains and broadcast domains are correct? (Choose three)

- A. Devices connected to the same hub form a collision domain
- B. Devices connected to the same hub form a broadcast domain
- C. Devices connected to the same bridge form a collision domain
- D. Devices connected to the same bridge form a broadcast domain
- E. Devices connected to the same router form a broadcast domain

Correct Answer: ABD Section: (none) Explanation





QUESTION 54

Which of the following statements regarding layer-2 switch is incorrect?

- A. The switch learns MAC addresses automatically.
- B. The layer-3 header is modified before the received packet is transmitted.
- C. The layer-2 header is modified before the received packet is transmitted.
- D. The layer-2 LAN switch operates at data link layer.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 55



Refer to the display output what can be determined based on the output of the display command?

[R1]display interface GigabitEthernet0/0/0

GigabitEthernet0/0/0 current state: Administratively DOWN

Line protocol current state : DOWN

- A. Interface Gigabit Ethernet 0/0/0 is connected to a wrong cable
- B. Interface Gigabit Ethernet 0/0/0 is not associated with an IP address
- C. Interface Gigabit Ethernet 0/0/0 is not associated with a dynamically defined route.
- D. Interface Gigabit Ethernet 0/0/0 has been manually shut down by an administrator.

Correct Answer: D Section: (none) **Explanation**

Explanation/Reference:

QUESTION 56

Which of the following statements regarding static and dynamic routing is incorrect?

- A. The static route can be easily configured and managed on the enterprise network.
 B. The use of dynamic routing is more convenient for the administrator to manage the network following network convergence,
- C. The static route can automatically recover when a link failure is encountered.
- D. Dynamic routing will use more resources than static routes.

Correct Answer: C Section: (none) **Explanation**

Explanation/Reference:

QUESTION 57

Which of the following are routed protocols? (Choose two)

- A. IP
- B. OSPF
- C. BGP



D. IPX

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 58

Which of the following statements regarding the routing table are correct? (Choose two)

- A. The next hop in the routing table is redundant because the outgoing interface can be used for packet forwarding
- B. The routes from generated by different protocols have different preferences.
- C. The metrics of different routing protocols are comparable.
- D. The metrics of different routing protocols are not comparable

Correct Answer: BD Section: (none) Explanation



Explanation/Reference:

QUESTION 59

Which of the following commands can be used to display the routing table on a Quidway router?

- A. display ip path
- B. display Ip routing-table
- C. display interface
- D. display current-configuration

Correct Answer: B Section: (none) Explanation



QUESTION 60

Which of the following entries is not included in the routing table?

- A. source address
- B. next hop
- C. destination address
- D. cost

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 61

Which of the following problems are caused by routing loops? (Choose three)

- A. Slow convergence
- B. Packets circulate between routers
- C. Router restarting
- D. Inconsistency of routing information

Correct Answer: ABD

Section: (none) Explanation

Explanation/Reference:

QUESTION 62

An administrator wishes to manage the router in the remote branch office, which method can be used?

- A. Telnet
- B. FTP
- C. Console Connection
- D. DHCP





Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 63

The administrator cannot use telnet to manage the AR2200. The administrator is able to verify connectivity to the router and has been informed that other administrators have no difficulties using telnet.

Which statements describe the possible reasons for this problem? (Choose two)

- A. The user's status has been blocked
- B. The user's privilege level has been changed to 0.
- C. The user has been deleted.
- D. The telnet service in the AR2200 router has been disabled.

Correct Answer: AC Section: (none) Explanation



Explanation/Reference:

QUESTION 64

A user logged into a VRP supported device through telnet, but when attempting to configure the device, found that he is unable to use the system-view command to enter the system-view.

What are the possible reasons for this? (Choose two)

- A. The device's VTY interface only provides permission for some telnet users to run the system-view command.
- B. The user's telnet software restricts use of this command.
- C. The user's privilege level is lower than the level associated with the system-view command.
- D. The system-view command privilege level is lower than the level associated with the user.

Correct Answer: AC Section: (none) Explanation