

Parts List		
Item	Qty	Part Number
1	1	M12x1.5 Strain Relief
2	2	EBB36 Standoff
3	1	M3 2.6mm Plastic Washer
4	1	M3x40 SHCS
5	1	M3 0.4mm Plastic Washer

Please note the thickness. Failure to use the right spacer can damage your motor plate, necessetating a reprint and reassembly of your ClockWork 2.