#### **BOARD OF DIRECTORS**

Gary Phillips '18 President: 14800 N SR 167 N Albany, IN 47320 (260) 251-4670 behere@netdirect.net

#### Steve King '18

1155 S. Paoli Unionville Rd Paoli, IN 47454 (812) 797-0059 kingstephen228@gmail.com

#### Bill Convers '19 Vice Pres

50964 Lilac Rd, South Bend, IN (574) 277-8729 billconyerssr@yahoo.com

#### Bill Newman '19

4655 Williams Rd Martinsville, IN 46151 (317) 690-2455 ruralsmiths1@yahoo.com

#### James Johnston '21

Education Chairman: 806 Twyckingham Lane Kokomo, IN 46901-1885 (765) 452-8165 kokomoblacksmith@comcast.net

#### John Bennett '21

Secretary: 741 W Jessup Rd Rosedale, IN 47874 (812) 877-7274 JohnBennett1959@gamail.com

#### Jeff Reinhardt '20

2810 W. Riley Floyd's Knobs, IN (812) 949-7163 ptreeforge@aol.com

#### Dave Kunkler '20

20749 Lancaster Rd. Branchville, IN 47514 (270) 945-6222 dwkunkler@yahoo.com

Librarian: Larry Rosentrader 8715 E. 375 N Churubusco, IN 46723-9501 260-693-3267 Irosentrader@gmail.com

Editor: Bill Kendrick 1280 N 900 W Seymour, IN 47274 (812) 445-3009 bill.d.kendrick@cummins.com

Treasurer and membership secretary: Farrel Wells 8235 E 499 S Dunkirk, IN 47336-8807 (765) 768-6235 flwells@frontier.com

Awards Chairman: Charlie Helton 2703 South Water Plant Road Westport, IN 47283 (812) 591-3119 heltoncs@frontier.com

# THE FORGE FIRE

The Newsletter of the Indiana Blacksmithing Association, Inc.

An Affiliate Of The Artists-Blacksmiths' Association of North America, Inc.

IBA is a Not For Profit Indiana Corporation recognized by the IRS under section 501(c)(3)

9:30 AM is the regular meeting time for IBA Hammer-Ins with beginner training available at 9:00 AM.
PLEASE MAKE SURE TO ASK FOR HELP!

If you would like an IBA membership application form, please contact Farrel Wells, Membership Secretary (765) 768-6235.

BULK LOTS ARE AVAILABLE TO DEMONSTRATORS, SHOPS, SHOWS AND OTHERS WILLING TO MAKE THEM AVAILABLE. WE APPRECIATE YOUR HELP.

The Indiana Blacksmithing Association, Inc., its staff, officers, directors, members, and hosts and the *Forge Fire*, specifically disclaim any responsibility or liability for damages or injuries as a result of any construction, design, use, manufacture or other activity undertaken as a result of the use, or application of, information contained in any articles in the Forge Fire. The Indiana Blacksmithing Association, Inc. And the *Forge Fire* assumes no responsibility or liability for the accuracy, fitness, proper design, safety, or safe use of any information contained in the *Forge Fire*.

The Forge Fire is the newsletter of the Indiana Blacksmithing Association Inc. (IBA) IBA is an affiliate of the Artist-Blacksmiths Association of North America Inc. Permission is granted to other similar non-profit organizations to reproduce uncopyrighted articles originally appearing in The Forge Fire provided credit is given the original source.

# More nearby resources and organizations for blacksmiths:

#### **Rural Smiths of Mid-America:**

Meetings are on the first Saturday of each month
Call Ron Gill
317-374-8323 for details

#### **IBA MEETING SCHEDULE**

Check the latest *Forge Fire* for monthly **IBA** revisions.

Jan 20	LARRY WHITESELL'S SHOP
2018	TIPTON
Feb 17	KEN DETTMER'S SHOP
2018	COLUMBUS
Mar 17	KELLY FARMS
2018	BUSINESS MEETING
Apr 21 2018	TBD



#### **INDEX**

PGS 3-4 SATELLITE NEWS

> PG 4 BLACKSMITH WANTED

PG 5 DECEMBER HAM-MER IN PHOTOS

> PG6 ABANA

PGS7-9 MAKING A TAPERED RECTAN-GULAR DRIFT

PGS 10-11 BLINDED BY THE LIGHT

#### Dates to Remember

March 17 Annual Business Meeting at Kelley Farms

March 16 & 17 Little Giant Rebuild Class

June 1-3 IBA Conference

### **Editors Message**

If you are looking for an anvil, Chupp Auctions in Shipshewana, IN may have what you are looking for. They have a three day winter auction January 18-20. On January 19 they have a large number of anvils listed. There are large and small anvils, including two bridge anvils. The January 19 auction is open for on-line bidding. To see the complete listing go to <a href="https://www.auctionzip.com">www.auctionzip.com</a> and enter auctioneer ID 11841.

The December hammer in hosted by Don Reitzel was a big success. Kurt Fehrenbach demonstrated knife making techniques. Attendance was good despite the cold weather.

This month we will be meeting at Larry Whitesell's shop in Tipton. Ron Gill will be demonstrating. Larry (hopefully Glenda) will provide the main course for lunch. Please bring a side dish or desert.

As noted in last month's ForgeFire, we are looking for potential directors to serve on the IBA board. If you are interested, please contact Gary Phillips immediately. Next month's Forgefire will include the board of directors ballot in advance of the March business meeting.

It is time to start thinking about nominations for Rookie and Blacksmith of the Year awards. Charlie Helton has been working to get at least one nomination for each satellite group. We have continually fallen well short of that target. I know we have a large number of qualified individuals who are deserving of the recognition. Guidelines and nomination forms are posted on the IBA website (www.indianablacksmithing.org/) under the membership menu.

Spring Mill State Park is looking for a blacksmith to work in their shop this year. More details are listed on page 4. If you are interested contact Coletta Pruitt at (812) 849-3534.

On page 6, I have posted some information that came in from ABANA. Old Globe is a company that salvages material, including wrought iron, from old structures. They are offering a 20% discount to ABANA members. If you are in the market for wrought iron, this may be a good opportunity for you. Also listed on page 6 is a brief notice about this year's ABANA conference in Richmond, VA. I would encourage you to check the ABANA website for more details.

I have not made a plea for articles recently. If you have a project, tool or technique that would be of interest to others, please send me the information. Photographs can often reduce the need for detailed descriptions.

IBA website: www.indianablacksmithing.org IBA Facebook page: www.facebook.com/groups/IndianaBlacksmithingAssociation/

### IBA Satellite Groups and News

#### 1) Sutton-Terock Memorial Blacksmith Shop

Meet: 2nd Saturday at 9 AM Contacts: Fred Oden (574) 223-3508 Dennis Todd (574) 542-4886

#### 3) Wabash Valley Blacksmith Shop

Meet: 2nd Saturday at 9 AM Contacts: Doug Moreland (217) 284-3457 Max Hoopengarner (812) 249-8303

#### 5) Maumee Valley Blacksmiths

Meet: 2nd Saturday Contacts: Clint Casey (260) 627-6270 Mark Thomas (260) 758 2332

#### 7) Rocky Forge Blacksmith Guild

Meet: 2nd Saturday at 9 AM Contacts: Ted Stout (765) 572-2467

#### 9) Whitewater Valley Blacksmiths

Meet: 2nd Saturday

Contact: Keith Hicks (765) 914-6584

#### 11) Bunkum Valley Metalsmiths

Meet: 1st Saturday Contacts: Jim Malone (812) 725-3311 Terry Byers (812) 275-7150

#### 13) Satellite 13

Meet: 4th Saturday

Contact: Bill Newman (317) 690-2455

Carol Baker (317) 809-0314

#### 2) Jennings County Historical Society Blacksmith Shop

Meet: 2nd Saturday at 9 AM Contact: Ray Sease (812) 522-7722

#### 4) Fall Creek Blacksmith Shop

Meet: 4th Saturday at 9 AM Contacts: Gary Phillips (260) 251-4670 Dave Kline (765) 620-9351

#### 6) St. Joe Valley Forgers

Meet: 4th Saturday at 9 AM Contacts: Bill Convers (574) 277-8729 John Latowski (574) 344-1730

#### 8) Meteorite Mashers

Contacts: Mike Mills (812) 633-4273 Steve King (812) 797-0059 Jeff Reinhardt 812-949-7163

#### 10) One-Armed Blacksmith Shop

Meet: 1st Saturday

Contact: Tim Metz (812) 447-2606

#### 12) "Doc" Ramseyer Blacksmith Shop

Location: 6032W 550N, Sharpsville, IN 46060


Meet: 3rd Sunday at 2 PM

Contact: Charles Gruell (765) 513-5390

#### 14) Covered Bridge Blacksmith Guild

Meet: 1st Saturday

Contact: John Bennett (812) 877-7274



#### **Meteorite Mashers**

The December meeting was held at Dave Kunkler's Nice and warm shop on a very cold almost last day of the year. Inside we had a slightly smaller group than usual due to many having family holiday commitments. Steve King demonstrated and helped with tong making Aaron Baker showed tips on knife making. Joseph Gehl brought a show and tell item, a ladder damascus billet made with tooling he made from gear rack he got from Jeff Reinhardt last month. Dave and Donna Kunkler were the usual gracious hosts and provided a big crock pot of chili and Mike Mills brought fried chicken so we had a good hot lunch on a cold day. A good time was had by all. The next meeting will tentatively be again at Dave Kunkler's. If the weather is inclement then it may move to the shop of Jeff Reinhardt since Jeff has a more level driveway. If the meeting is moved it will be announced on the IBA Facebook page

### IBA Satellite Groups and News (continued)

#### Jennings County Historical Society Blacksmith shop

The Vernon blacksmiths met at the newly expanded shop of John Cummins. I could almost live in this . Kevin Welsh warmed up the forge by demonstrating the making of a leaf. Jackie Schmidt then tried her hand at the anvil, with the guidance of Kevin. Garry Johnson crafted a thistle motif hook , which was unique for some of us. Xander Good worked on a drawing out exercise. John Cummins then showed us how to form a billet by layering metals together and forge welding them together. After carefully drawing it out on his power hammer, he laid this one aside to cool while he used his prestacked billet to show us how to make a Damascus knife blank. We had a great Steel-in-the-Stetson , followed by an "all you can eat" food bar. The first door prize was a Damascus knife made by John Cummins and won by Fred Vinup. The second door prize was a set of tongs won by Garry Johnson. Third prize was a walking stick made by Jackie Schmidt and won by Ray Sease. There was enough left for another meal, I'm sure. The January meeting will be at Paul Bray, 139 South Park Drive, Seymour In 47274. Breakfast will be furnished. Bring iron in the hat and money. February meeting is at Kenny Dettmer's, and March is at Kevin Welsh's, 25619 Gill Rd. , Nabb IN 47147 . Merry Christmas and Happy New Year!- Paul Bray

#### **Rural Smith of Mid-America**

The RSMA have been very busy with the blacksmith shop in Johnson County park. We got the concrete floor poured and now we need to put the shop back together, we will be starting on building the brick forge. We have a lot to do in a short time. We will be having some work weekends coming soon.

With the January meeting we start a new year with lots to do. We will continue to work with the new smiths in the group, and when the shop is back in order we will start to work with the Veteran and also make garden tools for the Veterans shop. We will also be doing more projects and work shops, and blacksmith classes. So stay tune for some fun time this year.

Ron Gill President RSMA

### **Blacksmith Wanted: Spring Mill State Park**

Spring Mill is looking for a for blacksmith to work in pioneer village during the 2018 recreation season. If you have experience blacksmithing or basic knowledge and want to learn more, we are looking for you. We can offer housing with rooms and shared living areas. Position begins mid-March weekends only until mid-April when the position switches to 5 days a week with days off through the week. The position ends the last full weekend in October. No benefits are available with the job. The pay rate is commensurate with experience and we can provide additional training if previous experience is limited. Duties include but are not limited to: demonstrate blacksmithing in the 1800's; while demonstrating produce a line of products that will be sold by the park in the village mercantile; offer programs to small groups, assist in operations of the grist mill, offer special programs during special events. Work day is 9 am to 5 pm with some evenings scheduled for special events.

Contact: Coletta Pruitt Spring Mill State Park 3333 State Road 60 E. Mitchell, IN 47446 (812) 849-3534

### **December Hammer In**

# Kurt Fehrenbach demonstrating

Photos courtesy of Dave Wells













Old Globe is offering a Discount of 20% to all members of ABANA!

We are happy to extend a 20% discount to all members of ABANA through July 31,18.

With one of the largest supplies of wrought iron available in the USA over 900 tons to harvest.

Visit **Oldglobewood.com** and select from numerous diameter of rods.

Click **HERE** to visit Old Globe.

Use "ABANA" to receive your 20% discount on orders over \$250. Feel free to share with membership.

# The ABANA 2018 Conference

The ABANA 2018 Conference will held in Richmond, Virginia at the **Meadow Event Park** Wed Jun 27 – Sat 30 Jun, 2018 **Save the Date** 



# Making a Rectangular Tapered Drift with Terry Sheridan

By Joe Cebek

One of the most basic processes in blacksmithing is to punch a hole and then use a drift, or a series of drifts, to render the final shape and dimensions of the hole. An example is making the eye of an adze. The eye needs to be tapered so a wooden handle can be attached to the adze and stay on while the adze is in use. The tapered eye is largest at the bottom of the adze; the handle slides in from the bottom and its end is tapered to match the taper of the adze eye. An elegant feature of this design is that the handle can be easily knocked out whenever the adze needs sharpening.

An adze eye is generally tapered on two dimensions and a drift is the perfect tool to establish the correct tapers. Terry Sheridan regularly forges adzes, and this article shows how he goes about making a tapered drift that can be used to make an adze eye (Fig.1). For this drift, Terry begins with a piece of 1 x 2 x 6<sup>3</sup>/<sub>4</sub> inch mild steel bar stock. The finished drift is 13 inches long overall, with an 8 inch octagonal handle, and measures 3/4 x 11/4 inches at the tip. Tapers are generally expressed as a change in thickness or width over 12 inches, e.g. a ½ inch increase over twelve inches. Terry has measured numerous adze eye tapers, and has found the tapers to be fairly consistent at 3/4 inch over 12 inches on the narrow side and  $1\frac{1}{4}$ inches over 12 inches on the wide side. This makes it easy to interchange handles if necessary. Once you know the tapers that are needed for each side, you can easily make a template for a tapered drift (Fig. 2).

A good-sized handle greatly improves the usefulness of a drift. Not only does it make it easier to hold as you pound the drift into a hot piece of steel, a handle makes it possible to use the drift for holding an adze head as you shape the outside of the eye. Terry forges




Figure 1. A finished drift and a piece of flat bar stock for making another. Note that the bar stock has a short piece of 1 inch round stock welded on to make it easier to handle the flat bar during forging. The extension can be cut off when no longer needed.



Figure 2. Terry uses chalk to sketch the tapers for the wide and narrow sides of the drift on a scrap sheet of steel.

the handle first, using a spring fuller with his power hammer to begin necking down the bar (Figs. 3 & 4). The power hammer can quickly reduce the cross-section of the bar first to a square (Figs. 5 & 6) and then to an octagon (Fig. 7).

Terry also uses the power hammer to forge the tapers (Fig. 8) and frequently checks the developing drift against the chalk templates (Fig. 9). With auxiliary dies, he can smooth




Figure 3. Using a spring fuller with a power hammer to mark off where the handle begins, at roughly mid-way on the bar.



Figure 4. The spring fuller is also used to indent the steel near the end of the developing handle. Indent-ing at this point prevents a "bird's mouth" from forming on the handle's end as the bar is reduced in thickness.

The surfaces very close to finished dimensions (Figs. 10 & 11). A few minutes is all it takes on the belt grinder (Fig. 12), and he's done.



Figure 5. Terry uses the power hammer to quickly thin the bar for the handle.



Figure 6. The handle is first forged to a square cross-section.

Reprinted from the Spring 2017 Iron Trillium www.ontarioblacksmiths.ca



Figure 7. The handle is next forged to an octagon cross-section.



Figure 10. Using a hand-held auxiliary die with the power hammer.



Figure 8. With the handle finished, Terry begins to forge the tapers.



Figure 11. The auxiliary die allows Terry to refine the drift's surface.



Figure 9. During forging, the developing taper is regularly compared to the template.



Figure 12. Terry does a final touch-up of the drift on a belt grinder.

# Blinded By the Light

### Be Careful How You Look

#### Bob Dixon Gumm


Shortly before the holidays, I was working on a welding project. The object that I was MIG welding had many prongs sticking out from it. While welding another prong, I noticed what appeared to be a weak weld. Lifting up my helmet, I poked my head in for a closer examination. What I failed to do was to move the MIG gun away from the project and rest it in the table holder. The outcome is easy to imagine. The gun was near my face, and as I got even closer to the weak spot, I accidently pushed the trigger against one of the prongs. This was followed by a bright flash, a very warm feeling against my eyes, and a wait of about five minutes before I could resume welding. Once the bright spot in my eyes had gone away, I thought everything was fine. I worked for another hour, ate a meal, and sat in front of the television to see, 'How the Grinch Stole Christmas'.

It was soon after when I felt that I had a small grain of sand in my left eye. I lifted my eyelid back, hoping that tearing would remove the grain. My eyes cried a river, but the irritant only seemed to grow larger and the pain more intense. It wasn't long before my right eye began to express its outrage over my failure to secure the MIG gun. Convinced that I had a flash burn, I went to the urgent care clinic. They confirmed this, and provided antibiotic ointment and an ophthalmologist appointment. After about a week, my eye felt as good as new. I was lucky.

Most of us have heard of flash burn. But what exactly is it? Flash burn can be thought of as sunburn in the eye. If you imagine yourself lying on a beach, you know that there are greater things to worry about than being chomped on by a shark. Sunglasses, sunblock, that bird doo looking stuff that lifeguards wear on their nose, and an umbrella all point to the greatest danger: sunlight. Sunlight is ultraviolet (UV) light, and UV risk comes to us in many different ways: sunlamps; nearby lightning flash; halogen lamps;
reflection of sunlight off water and snow; and most important for us – any type of welding light, be it gas, SMAW, MIG, TIG, and
forge. The latter causes are reason why the condition is known as 'welder's flash' or 'are eye'.

A flash burn is a (painful) inflammation of the cornea. It produces a sensation similar to that of a corneal abrasion. But flash burn generally affects both eyes, though one eye usually is more irritated, whereas corneal abrasion takes usually occurs in one eye. The cornea is the clear tissue that covers the front of the eye. For our purposes, think of the cornea as the glass lens on the front of a camera. The cornea covers the iris (the colored part of the eye), focuses light on the retina, and protects deeper structures of the eye by acting like a windshield. Although the cornea is clear, it is consists of cells that are similar to those in the skin. If you've ever had sunburn that resulted in blistered or peeling skin, then imagine the damage that UV light can do to your eyes.

#### CROSS SECTION OF THE EYE



Jeepers, Creepers, where'd you get that peeper? Online, where else?



Bad news. It hurts worse than it looks.

What do you do when you receive a flash burn? The first step is to make arrangements to get to a doctor or care center. You should never attempt to drive yourself there. In the interim, flushing your eyes with water provides some pain relief. Once your eyes have been attended to by a doctor, you must be vigilant about applying prescribed antibiotic drops or ointment to your eyes. You may also with to use OTC artificial tears, anti-inflammatory, and pain medications. Do not wear contacts lenses and do not apply topical anesthetics. They will only prolong the condition. It is important to wear sunglasses whenever you're outside, and if the doctor determines that you need to wear a patch, ask for one of the black, pirate looking ones. They're rather dashing.

If you've followed doctor's orders carefully and have refrained from the activity that caused your flash burn, you can expect the cornea to repair itself within a few days, and all irritation or discomfort to end within a week. Typically, flash burn usually heals without leaving a scar. More severe cases may take longer. Like the time in my Navy days when our ship was is in the shipyard. A young seaman who was having second thoughts about his enlistment was assigned as fire watch to a welding crew. While maintaining vigilance, it occurred to him that flash burn might just be his ticket out of the Navy. And so he stared at welding arcs. Instead of getting a pirate looking patch, as one expect for a sailor, the corpsmen taped big wads of cotton and gauze on top of his eyes. So rather than Blackbeard or Barnacle Bill, the poor guy looked like a human fly. Whenever he was led past shipmates who were standing around with nothing much to do, they would yell, "Help me!," and then bust out laughing. Far be it from the Navy to provide no opportunity for fun. Several of his bunkmates waited through the night, and when they were certain he was asleep, took magic markers and drew owl eyes on his bandages. The crew thought it was a hoot!

For blacksmiths and welders, we know that working with hot metal is fraught with danger. We all fear the black hot burn that leaves an impression on our fingers of the thing we just picked up. Skin, like eyes, is an organ, but an organ with the capacity to replenish itself and go on working as if nothing happened. What's a little scar among blacksmiths, right? It may get you bragging rights or a! cup of coffee. The eye, unfortunately, is not so capable. A severe flash burn can produce scarring, and this can obstruct vision to some degree. If the flash burn is not treated, an infection may start. This is as serious a matter as getting a shard or miniscule piece of metal stuck in your eye. If infection sets in and goes untreated, the result may be partial vision loss or a blind eye.

# Remember!

- Arc rays can injure eyes and burn skin
- The welding arc is brighter than the sun
- Precaution must be taken to protect your eyes and skin from UV radiation
- Wear correct eye and body protection



Tommy Ward used to say, "You can walk on a wooden leg but you can't see out of a glass eye."

"CAUTION AND GOOD COMMON SENSE"



Address Correction Requested If Undeliverable return to sender

### January 20 Hammer In

# Larry Whitesell's Shop, 4314 S County Road 300W, Tipton, IN 46072

Directions: From US-31 turn east on CR 500S. Go east about 3 miles and turn north on CR 300W. The shop is about 3/4 of a mile up on the left (west). From SR28 turn south on CR 300W. The shop is about 2 miles south on the right (west) side of the road.

Please bring a dish to share.

## February 17 Hammer In Kenny Dettmer's Shop

15721 S 250W Columbus, IN

**From the North:** take I 65 S to Ogilville / Walesboro (exit 64) turn. right. Go to the 1st crossroads (300 W). Turn left. Approx 1 mile to the "T' . Turn left (600s). Go to 250W. Approx. 4 miles to a brick house on your left.

**From the South:** I 65N to Jonesville exit 55 turn. right, go to road 950 (in Jonesville). Turn left. Go to 250W turn. right. Kenny's house is approx 1/2 mile on your right.

Please bring a dish to share.

First Class Mail