

Home Appliance Repair Receipt

This document contains fictional test data created for LifeLens ingestion and retrieval testing.

Customer

Maya Sharma

Service Date

July 22, 2025

Vendor

Northside Appliance Repair

Appliance

Whirlpool refrigerator, model WRX735SDHZ.

Problem Reported

Refrigerator compartment was warmer than normal, while the freezer continued to operate.

Diagnosis

Technician found a failed evaporator fan motor. No refrigerant leak was detected.

Repair Performed

Replaced evaporator fan motor and cleaned condenser coils. Unit was tested for 30 minutes after repair.

Cost

Parts: \$168. Labor: \$145. Service fee: \$69. Total paid: \$382.

Warranty

Replacement fan motor and labor are covered for 90 days from July 22, 2025.