# $\begin{array}{c} R \text{Pi--R} \\ \text{Raspberry Pi Rheometer Reference} \end{array}$

### Contents

1		erview			
		Hardware			
		Electronics			
		Software			
	1.4	Summary			
2	Usage				
	2.1	Using the rheometer script			
	2.2	Custom usage scripts			
3					
4	Wh	y?			

### Overview

#### 1.1 Hardware

This section describes the main hardware that comprises the rheometer; the Taylor-couette cell, the bench, the scissor lift, etc. Most (i.e. all) of this was not of my design or choosing, it was set up by the department for a previous set of students, therefore I don't know the exact reasoning behind the choices, but I'll give it a go.

The Taylor-Couette cell is composed of a hollow glass cylinder and a perspex inner cylinder. The inner cylinder is attached to the rotor of a DC motor. The outer cylinder is attached to a scissor lift. Fluid can be placed into the gap between the cylinders and sheared - this is roughly the whole rheometer. In addition, there are sensors and other electronics which allow the hardware to be controlled by a Raspberry Pi computer, discussed in the next section.

The cell is based upon a heavy metal base, of unsure exact function. It is a nice way to organise the rheometer, it provides a stable base, and it protects the worktop, but a bare worktop would have been fine too. On this bench sits the scissor lift holding the fixed outer cylinder, as well as a clamp stand which holds the motor (and the inner cylinder).

The motor is a 15V DC electric motor with a 1/16th reduction gear system attached. This motor can operate nominally with a voltage supply between 4.5V and 15V.

There are some important geometries used in the rheometry calculation; the diameters of the inner and outer cylinders. These are summarised in Table 1.1.

#### Known Issues

Assumption: Couette flow in between the cylinders. Strengths: the cylinders have a small gap, and can be easily adjusted to minimise errors in centring. Weaknesses: both the inner and outer cylinders have small imperfections which could affect the flow in the cell. The glass outer cylinder is non uniform — to be expected with glass objects. Also, the inner cylinder is slightly off centre — slightly.

**Assumption:** motor gear system will not greatly affect the system, or it will but in a way that can be accounted for in calibrations. **Strengths:** this should be true for any well maintained gear system. Gears only transfer movement and should not present any resistance that is not easily accounted for. **Weaknesses:** 

Table 1.1: Summary of Hardware Geometries

Dimension	Symbol	Value
Inner cylinder diameter	$\mathrm{D}_{\mathrm{IC}}$	0.035  m
Outer cylinder diameter (outer)	$\mathrm{D}_{\mathrm{OCo}}$	0.044 m
Outer cylinder diameter (inner)	$\mathrm{D}_{\mathrm{OCi}}$	0.039  m

the gear system/motor sometimes acts oddle — making strange sounds and appearing to slow despite no changes to load or to power supply. This was remedied (hopefully) by applying WD40 to the gear system.

#### 1.2 Electronics

The electronics of the RPi-R consist of two sections: motor supply voltage control, and sensor readings. Both based on breadboard (at the moment — the prototype is subject to change, so nothing too permanent). The former consists of a digital potentiometer (a digitally programmable variable resistor) which alters the voltage going into an operational amplifier (very useful IC) which in this case is used to boost the voltage 2.1 times. The current is then boosted by a transistor roughly 200 times to around 2A. The sensors are all fed into an Analogue to Digital Converter (ADC).

The electronic system is connected to the Raspberry Pi using serial data transfer. Serial, as opposed to parallel, sends data as bits one after the other down one or more lines to as regulated by a clock signal. The SPI (Serial Peripheral Interface) protocol is the main serial interface used. One wire (1-Wire) is also used, but only for the temperature sensor.

The voltage regulation consists of a digital potentiometer which is controlled by the RPi via SPI. A signal (10-bit number, 0-127) is sent from the Pi, and represents the position of the wiper of the potentiometer and thus the resistance and the voltage on the wiper. This wiper voltage is amplified by an operational amplifier (in non-inverting operational mode) such that the voltage is able to be swept between around 2.4 volts up to 10.8 volts. This amplified voltage is passed through the base of a transistor which is used to boost its current up to a reasonably large 2A available. This transistor is therefore having to pass a high current and high voltage - it understandably therefore heats up a great deal<sup>1</sup>. This was dealt with by adding a heatsink<sup>2</sup> to the transistor. The heatsink may not be sufficient, a fan or larger heatsink may be necessary.

#### 1.3 Software

#### 1.4 Summary

Presented here are lists of every component used to construct the RPi-R, along with links to datasheets if possible, as well as the circuit diagrams and photographs of the actual layout.

<sup>&</sup>lt;sup>1</sup>Before the heatsink was attached, the transistor melted a section out of the breadboard. Then, after I attached wires to remove it from other components, it melted the wires. The transistor can get **very** hot.

<sup>&</sup>lt;sup>2</sup>Which can get very hot. I managed to burn a lovely pattern onto my thumb.

# Usage

- 2.1 Using the rheometer script
- 2.2 Custom usage scripts

Why?