Moraine Fire Department ALARM REPORT

DATE03/15/95	-	RUN #	3
METHOD OF ALARM FROM PUBLIC			
1 ☐ Telephone direct 2 ☐ Municipal alarm system 3 ☐ Private alarm system 4 ☐ Radio 5 ☐ Verbal	7 Q 8 Q 9 Q	 6 □ No alarm recd 7 □ Tie-line (911) 8 □ Voice signal municipal alarm signal 9 □ Not classified above 0 □ Undetermined or not reported 	
TIME RECEIVED 06:56	TIME	DISPATCHED	06:57
LOCATION 20 Loess Lane			
REPORTED AS fire in boiler room, possible hazardous materials			
BOX No. TRANSMITTED	0247		······································
	TIME OUT	IN-SERVICE	IN-QUARTERS
RESCUE 1	06:57	07:00	***************************************
ENGINE 1	06:57	06:59	***************************************
ENGINE 2	***************************************	***************************************	***************************************
ENGINE 3	***************************************	***************************************	***************************************
ENGINE 4		***************************************	***************************************
ENGINE 5		07.02	•••••
TOWER LADDER 1	06:58	07:02	***************************************
LADDER 2	07.00	07:04	***************************************
HAZMAT 1	07:00		***************************************
HAZMAT2			
FIRST UNIT AT SCENE Engine 1 TIME 06:59			
INITIAL REPORTfireir	n boiler room	r; contained as worse the	nan it actually was
PROBABLE CAUSE boxes and trash too close to exposed, old wiring Inspector Burnham Name of Operator			
** Chief has requested thorough investigation to rule out arson.			