


63



00
00
00
00
00
00
00
00
00
00
00
00

INSPECTION LIST REVISION #2 (SNAG LIST @ PC)

STELLENBOSCH UNIVERSITY



COETZENBURG STADIUM ADDITIONS & ALTERATIONS
ELECTRICAL SERVICES

3360 308 SS 01

E5186

15 June 2023

Changeroom



642.Row of fittings to be the same height between both store rooms.

PHOTO TIMESTAMP: 2023.06.13 14:07:51
GPS LAT: -33.9407 / GPS LONG: 18.8712



031.All socket outlets and lightswitches to be labelled.

PHOTO TIMESTAMP: 2023.06.13 14:08:35
GPS LAT: -33.9407 / GPS LONG: 18.8712



218.DB legend to be completed.

PHOTO TIMESTAMP: 2023.06.13 14:08:49
GPS LAT: -33.9405 / GPS LONG: 18.8713



143.Please consider replacing these bent covers with modern PVC cover plates.

PHOTO TIMESTAMP: 2023.06.13 14:09:13
GPS LAT: -33.9408 / GPS LONG: 18.8712




424.Please remove wall fittings above mirrors in change room. Not required and classhing with plumbing.

PHOTO TIMESTAMP: 2023.06.13 15:23:25
GPS LAT: -33.9407 / GPS LONG: 18.8712



865.Data cable required for LAN point.


PHOTO TIMESTAMP: 2023.06.13 16:09:39
GPS LAT: -33.9407 / GPS LONG: 18.8712





865.LAN point route to be completed.

PHOTO TIMESTAMP: 2023/06/13 16:09:39
GPS LAT: -33.9407 / GPS LONG: 18.8712



430.Socket outlet to be replaced with new in room 01.

PHOTO TIMESTAMP: 2023/06/13 16:09:48
GPS LAT: -33.9407 / GPS LONG: 18.8712



895.Please raise three phase outlet in room one to 300mm or up to 700m (from top edge).

PHOTO TIMESTAMP: 2023/06/13 16:10:01
GPS LAT: -33.9407 / GPS LONG: 18.8712



448.Missing LAN wall cabinet and fibre splicing.

PHOTO TIMESTAMP: 2023/06/13 16:10:10
GPS LAT: -33.9407 / GPS LONG: 18.8712



428.RED].Please remove redundant wiring if not needed.

PHOTO TIMESTAMP: 2023/06/13 16:10:32
GPS LAT: -33.9407 / GPS LONG: 18.8712



095.Please seal gap around socket outlet.

PHOTO TIMESTAMP: 2023/06/13 16:12:35
GPS LAT: -33.9407 / GPS LONG: 18.8712




920.MDB Lighting section Legend to be typed.

PHOTO TIMESTAMP: 2023/06/14 15:12:57
GPS LAT: -33.9407 / GPS LONG: 18.8712



908.Two fans not working SUN property services to address. Fan 5 and 7 to be disconnected in the meantime for safety.

PHOTO TIMESTAMP: 2023/06/14 15:14:12
GPS LAT: -33.941 / GPS LONG: 18.8711



580.Please correct label. needs to be general lighting.

PHOTO TIMESTAMP: 2023/06/14 15:29:23
GPS LAT: -33.9407 / GPS LONG: 18.8712

ELECTRICAL: LIGHTING, POWER, WIREWAYS (EMG)

BUILDING WORKS AND ACCESS CONTROL (BAMBAWA)

N/A

N/A

ELECTRICAL ENGINEER, FACILITIES MANAGEMENT, PROPERTY SERVICES, QS

FACILITIES MANAGEMENT



554.[RED] Circled circuits to go to general section.

PHOTO TIMESTAMP: 2023/06/14 15:32:22
GPS LAT: -33.9407 / GPS LONG: 18.8712



Various keyswitches to be reinstated (HVAC, FANS).

PHOTO TIMESTAMP: Date
GPS LAT: coords_lat / GPS LONG:
2023/06/14 15:32:22




Lightfittings to align.

PHOTO TIMESTAMP: 2023/04/19 16:09:34
GPS LAT: -33.9404 / GPS LONG: 18.8713




Redundant isolators to be disconnected and removed.

PHOTO TIMESTAMP: 2023/04/19 16:09:45
GPS LAT: -33.9403 / GPS LONG: 18.8712



Room 1 - Please cut and remove redundant cabling and surface trunking up to wall penetration.

PHOTO TIMESTAMP: 2023/05/22 12:54:49
GPS LAT: -33.94 / GPS LONG: 18.8717



Please disconnect and remove doorbell.

PHOTO TIMESTAMP: 2023/05/22 12:55:44
GPS LAT: -33.941 / GPS LONG: 18.8713



Please remove doorbell and plaque.

PHOTO TIMESTAMP: 2023/05/22 12:55:45
GPS LAT: -33.941 / GPS LONG: 18.8713



Exit light at incorrect location.

PHOTO TIMESTAMP: 2023/05/22 12:58:49
GPS LAT: -33.9402 / GPS LONG: 18.8714



Exit light is fitted off perpendicular. Please refit.

PHOTO TIMESTAMP: 2023/05/22 13:04:35
GPS LAT: -33.9402 / GPS LONG: 18.8711

ELECTRICAL: LIGHTING, POWER, WIREWAYS (EMG)	N/A
BUILDING WORKS AND ACCESS CONTROL (BAMBANA)	ELECTRICAL ENGINEER, FACILITIES MANAGEMENT, PROPERTY SERVICES, QS
N/A	FACILITIES MANAGEMENT



Paintwork to be fixed behind lightfitting (East escape).

PHOTO TIMESTAMP: 2023/05/22 13:04:59
GPS LAT: -33.9406 / GPS LONG: 18.8714



Please raise lightfitting line to structural beam soffit.

PHOTO TIMESTAMP: 2023/05/22 13:05:24
GPS LAT: -33.9404 / GPS LONG: 18.8713




Missing labels at socket outlets and switches etc.

PHOTO TIMESTAMP: 2023/05/22 13:06:25
GPS LAT: -33.94 / GPS LONG: 18.8713



West toilets in changeroom. Missing screw.

PHOTO TIMESTAMP: 2023/05/22 13:06:33
GPS LAT: -33.94 / GPS LONG: 18.8713



West toilets. Missing wall lightfitting.

PHOTO TIMESTAMP: 2023/05/22 13:07:14
GPS LAT: -33.94 / GPS LONG: 18.8707



This trunking and wiring is redundant. Please however fix a cover plate.

PHOTO TIMESTAMP: 2023/05/22 13:10:12
GPS LAT: coords_lat / GPS LONG:
coords_long



Please install a new lid to the existing powerskirting.

PHOTO TIMESTAMP: 2023/05/22 13:10:51
GPS LAT: coords_lat / GPS LONG:
coords_long



Room 1 - Please remove redundant phone point and conductor.

PHOTO TIMESTAMP: 2023/05/22 13:13:35
GPS LAT: coords_lat / GPS LONG:
coords_long



Please reinstate plug point and conductor to the NO-SMOKING sign.

PHOTO TIMESTAMP: 2023/05/22 13:13:41
GPS LAT: coords_lat / GPS LONG:
coords_long

ELECTRICAL: LIGHTING, POWER, WIREWAYS (EMG)	N/A
BUILDING WORKS AND ACCESS CONTROL (BAMBANA)	ELECTRICAL ENGINEER, FACILITIES MANAGEMENT, PROPERTY SERVICES, QS
N/A	FACILITIES MANAGEMENT

ENG-CI



Earth leakage required for Heat Pump.

PHOTO TIMESTAMP: 2023/06/14 15:13:42
GPS LAT: -33.9407 / GPS LONG: 18.8712



MDB internals to be dust free.

PHOTO TIMESTAMP: 2023/06/14 15:36:50
GPS LAT: -33.9407 / GPS LONG: 18.8712







Please tuck redundant circuits in MDB out of way and end with heat shrink.

PHOTO TIMESTAMP: 2023/06/14 15:37:36
GPS LAT: -33.9407 / GPS LONG: 18.8712






MDB room to be cleaned and painted.

PHOTO TIMESTAMP: 2023/06/14 15:41:48
GPS LAT: -33.9405 / GPS LONG: 18.8713



Ground floor



ENG-CI



172.Local control of gallery lights required.

DONE







Cover all exposed conduit boxes. This one is in the gallery seating area.


PHOTO TIMESTAMP: 2023.06.13 16:08:38
GPS LAT: -33.9407 / GPS LONG: 18.8712

PHOTO TIMESTAMP: 2023.05.22 12:56:45
GPS LAT: -33.9403 / GPS LONG: 18.8713

Playing Area



ENG-CI



945.Cover plate missing. Engineer to check if this was issued.

PHOTO TIMESTAMP: 2023.06.13 14:09:25
GPS LAT: -33.9408 / GPS LONG: 18.8712



945.Please align, clean and paint wall penetrations.

PHOTO TIMESTAMP: 2023.06.13 14:09:25
GPS LAT: -33.9408 / GPS LONG: 18.8712



260.ITERRA press siwtch to be seated correctly inside housing.

PHOTO TIMESTAMP: 2023.06.13 15:19:11
GPS LAT: -33.9405 / GPS LONG: 18.8713




971.Please permanently plug penetration.

PHOTO TIMESTAMP: 2023.06.13 16:15:49
GPS LAT: -33.9408 / GPS LONG: 18.8714



Method to connect vertical conduit to manhole to be discussed on site.

PHOTO TIMESTAMP: 2023.04.19 16:14:48
GPS LAT: -33.9408 / GPS LONG: 18.8712



Lightfitting rotation not aligning.

PHOTO TIMESTAMP: 2023.04.19 16:18:16
GPS LAT: -33.9407 / GPS LONG: 18.8713

ELECTRICAL: LIGHTING, POWER, WIREWAYS (EMG)

N/A

BUILDING WORKS AND ACCESS CONTROL (BAMBANA)

ELECTRICAL ENGINEER, FACILITIES MANAGEMENT, PROPERTY SERVICES, QS

N/A


FACILITIES MANAGEMENT




Please dust top of fittings while performing the alignment rectification activity.




SUN IT to reactivate.



Please reconnect LAN cabinet to electrical supply (please take from DB-TV).



Please remove electronic cable entirely (runs along playing area perimeter).



Missing conduit over plate (over the firepanel).



Please seat cover plate to box.



Missing cover plate. Please advise of CI required.



Missing cover plate. Please advise if CI required.




PHOTO TIMESTAMP: 2023:05:11 14:38:34
GPS LAT: -33.9408 / GPS LONG: 18.8712

PHOTO TIMESTAMP: 2023:05:19 14:20:24
GPS LAT: coords_lat / GPS LONG:
coords_long

PHOTO TIMESTAMP: 2023:05:19 14:20:24
GPS LAT: coords_lat / GPS LONG:
coords_long

PHOTO TIMESTAMP: 2023:05:22 13:01:04
GPS LAT: -33.9405 / GPS LONG: 18.8715



PHOTO TIMESTAMP: 2023:05:22 13:08:51
GPS LAT: coords_lat / GPS LONG:
coords_long

PHOTO TIMESTAMP: 2023:06:14 15:04:50
GPS LAT: -33.9403 / GPS LONG: 18.871

PHOTO TIMESTAMP: 2023:06:14 15:05:51
GPS LAT: -33.9406 / GPS LONG: 18.8707

PHOTO TIMESTAMP: 2023:06:14 15:08:12
GPS LAT: -33.9406 / GPS LONG: 18.8715

Ramp & Site




739.ATS interface to be completed and generator interface to MDB to be commissioned.

PHOTO TIMESTAMP: 2022:10:21 11:08:09
GPS LAT: -33.9403 / GPS LONG: 18.8713



818.Fibre splice missing.

PHOTO TIMESTAMP: 2023:06:13 16:16:53
GPS LAT: -33.941 / GPS LONG: 18.8714



437.Please cut hole in cover plate to let cable to pass through.

PHOTO TIMESTAMP: 2023:06:13 16:17:32
GPS LAT: -33.9407 / GPS LONG: 18.8712



Missing Data Point. Please liaise with engineer for position.

PHOTO TIMESTAMP: 2023:05:22 12:31:35
GPS LAT: coords. lat / GPS LONG:
200000S 1000E




LAN cabine power to be restored from a temporary supply.

PHOTO TIMESTAMP: 2023:04:19 16:08:12
GPS LAT: -33.9407 / GPS LONG: 18.8712



Missing sleeve penetration to power manhole.

PHOTO TIMESTAMP: 2023:04:19 16:20:49
GPS LAT: -33.9408 / GPS LONG: 18.8712





Please shift the sump pump panel to the left to align edge with socket outlet.

PHOTO TIMESTAMP: 2023/05/17 12:58:33
GPS LAT: -33.9409 / GPS LONG: 18.8716




Perimeter lights to be removed.

PHOTO TIMESTAMP: 2023/05/17 12:59:08
GPS LAT: -33.9407 / GPS LONG: 18.8714



Missing ramp lighting. Points must be at or below grade.

PHOTO TIMESTAMP: 2023/05/22 12:38:49
GPS LAT: coords_lat / GPS LONG:
2000000.0000




Redundant lighting points to be filled with plaster (no cover plates).

PHOTO TIMESTAMP: 2023/05/22 12:41:10
GPS LAT: coords_lat / GPS LONG:
2000000.0000



Please fix conduit to wall. Please advise if CI required.

PHOTO TIMESTAMP: 2023/06/14 14:59:05
GPS LAT: -33.9407 / GPS LONG: 18.8713



Legend card to be completed in DB-TV.

PHOTO TIMESTAMP: 2023/06/14 15:01:19
GPS LAT: -33.9408 / GPS LONG: 18.8715

