

锌空电池 Zin-Air Battery

产品概述 PRODUCT INTRODUCTION

锌空电池

Zin-Air Battery

锌空电池属于一次电池,正极为空气极,负极为锌浆,其优势为比容量和比能量高、放电电压平稳、生产成本低、使用安全、环保无污染。主要应用于**助听器**、蓝牙耳机(小功率)等。有潜力用于电子台历、计算器等氧化银电池可以用到的场合,电流较小但容量比氧化银电池要高。



锌空电池

Zin-Air Battery






产品参数

PRODUCTPARAMETERS

	A10	A312	A13	A675(P)	
相同型号(IEC)	PR536	PR41	PR48	PR44(P)	
直径mm	5.8	7.9	7.9	11.6	
高度mm	3.6	3.6	5.4	5.4	
重量g	0.3	0.5	0.8	1.6	
电压V	1.45	1.45	1.45	1.45	
电阻Ω	≤12	≤6.0	≤9.0	≤2.7	
容量mAh	80	158	235	560	
使用天数	2-5	7-15	10-20	15-30	
适用机型	深耳道式	耳内式、耳道式	耳背式、耳内式	大功率耳背式	
贴纸颜色	黄色	棕色	橙色	蓝色	

规格书(Spec





DATASHEET	A10 (Mercury free)	W Great Power	DATASHEET	A13 (Mercury free)	W Great Power
Greatpower Stock Number	10MF	A	Greatpower Stock Number	13MF	
Name	10 Mercury Free	Appearance:	Name	13Mercury Free	Appearance:
Cell Chemistry	Zinc Air	10+	Cell Chemistry	Zinc Air	13+
Recommended Use	Hearing Aid Instruments		Recommended Use	Hearing Aid Instruments	
Nominal Volatge	1.45 V	(Top View) (Bottom View)	Nominal Volatge	1.45 V	(Top View) (Bottom View)
Impedance	≤12Ω		Impedance	≤9Ω	
Typical Weight	0.3g	Dimensions: Unit:mm	Typical Weight	0.8g	Dimensions: Unit:mm
Typical Volume	0.08cm ⁸	ricia.	Typical Volume	0.25cm ^a	#75Eps
Environmental	These cells have no added mercury.	9	Environmental	These cells have no added mercury.	
Operating Temp	0°C to 50°C	nose.	Operating Temp	0°C to 50°C	
Capacity(IEC 60086-2:2000):	$84mAh$ - Rated at 3000Ω to 0.90V at $20^{\circ}C$ and 60% RH.	98	Capacity(IEC 60086-2:2000):	$255 mAh$ - Rated at 1500Ω to 0.90V at $20^{\circ}C$ and 60% RH.	11 (E)
Capacity(IEC 60086-2:2011):	80mAh - Rated at 1mA background, 5mA 100ms pulse, once every 2 hours, 12 hours/day to 1.05V at 20°C and 60% RH.	Configuration:	Capacity(IEC 60086-2:2011):	235mAh - Rated at 3mA background ,12mA 100ms pulse, once every 2 hours, 12 hours/day to 1.05V at 20°C and 60% RH.	Configuration:
Storage Loss at 70°F(21°C)	Less than 5% in one year with tab applied.	snock (-)	Storage Loss at 70°F(21°C)	Less than 5% in one year with tab applied.	ange (-)
Activation and use	Remove and discard the plastic tab covering air holes. Allow the battery to stand for one minute to insure proper activation. The battery compartment must allow for an adequate oxygen supply to reach air holes.	20% gal country can call ode call ode can call ode call ode can call ode call ode can call ode call ode can call ode can call ode call o	Activation and use	Remove and discard the plastic tab covering air holes. Allow the battery to stand for one minute to insure proper activation. The battery compartment must allow for an adequate oxygen supply to reach air holes.	and get — Gasket Separate — Chicket — Chicket Separate — Chicket Separ





更多型号请登录公司网站查询

www.greatpower.net



应用场景





完整的电池解决方案供应商



◇ 联系我们

广州鹏辉能源科技股份有限公司

地址:广州市番禺区沙湾镇市良路西村段912号

电话: 020-39196888 传真: 020-39196767

邮箱: info@greatpower.net

http://www.greatpower.net