


零件1,数量2



- 1. 图中尺寸 $248_{-1}^{0} \times 155_{-1}^{0}$ 为配合尺寸,需按图纸控制公差;
- 2. 为了不影响安装,四个板的焊接位置必须在板内侧;
- 3. 零件1,2各2件,焊接到零件3面板上;
- 4. 零件1,2为装卡扣的板。

零件2,数量2

