TV Intelligence Scanner — Operating System Report

Project #1 SAMPLE — Bench TV (synthetic data) | Acme TESTTV55 | 2026-11-08 22:07 UTC

Sources: firmware_analysis (analysed firmware files), fingerprint (OS indicator rules), system_menu_ocr (photos of the System Information screen), operator (entered with reference), upnp / adb (authorised read-only device queries). No access method was assumed to exist.

1. Summary

Item	Value	Confidence	Sources
Operating system	Android	97%	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 5 sources: extracted file 0x00030000_gzip/cpio_contents/system/build.prop; extracted file 0x00050000_zip/system/build.prop; extracted file 0x00040000_tar/system/build.prop; …; firmware_analysis: firmware #1 orig_dump.bin, run #1: 5 sources: extracted file 0x00030000_gzip/cpio_contents/system/build.prop; extracted file 0x00050000_zip/system/
Operating system	Linux	97%	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 3 sources: extracted file 0x00030000_gzip/cpio_contents/etc/os-release; extracted file 0x00050000_zip/etc/os-release; extracted file 0x00040000_tar/etc/os-release; firmware_analysis: firmware #1 orig_dump.bin, run #1: 3 sources: extracted file 0x00030000_gzip/cpio_contents/etc/os-release; extracted file 0x00050000_zip/etc/os-release; extrac
Operating system	Linux (generic)	60%	fingerprint: firmware #2 upgrade_tv_v2.bin, run #2: OS fingerprint rules; fingerprint: firmware #1 orig_dump.bin, run #1: OS fingerprint rules
OS version	Android 9	97%	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 4 sources: extracted file 0x00030000_gzip/cpio_contents/system/build.prop; extracted file 0x00050000_zip/system/build.prop; extracted file 0x00040000_tar/system/build.prop; …; firmware_analysis: firmware #1 orig_dump.bin, run #1: 4 sources: extracted file 0x00030000_gzip/cpio_contents/system/build.prop; extracted file 0x00050000_zip/system/
OS version	os-release VERSION_ID 4.9	97%	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 3 sources: extracted file 0x00030000_gzip/cpio_contents/etc/os-release; extracted file 0x00050000_zip/etc/os-release; extracted file 0x00040000_tar/etc/os-release; firmware_analysis: firmware #1 orig_dump.bin, run #1: 3 sources: extracted file 0x00030000_gzip/cpio_contents/etc/os-release; extracted file 0x00050000_zip/etc/os-release; extrac
Kernel	4.9.200	96%	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 2 sources: string @0x14e75: Linux version 4.9.200 (builder@tv) (gcc version 6.3.1 (Linar; uImage name 'Linux-4.9.200' @0x10000
Kernel	4.9.118	96%	firmware_analysis: firmware #1 orig_dump.bin, run #1: 2 sources: string @0x14e75: Linux version 4.9.118 (builder@tv) (gcc version 6.3.1 (Linar; uImage name 'Linux-4.9.118' @0x10000
Build	built Mon Mar 2 10:11:12 CST 2020	60%	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: string @0x14ec4; firmware_analysis: firmware #1 orig_dump.bin, run #1: string @0x14ec4
Firmware version	V1.0	80%	operator: Settings > Support > About this TV
Bootloader	U-Boot 2015.04-tv	85%	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: string @0x14ee0; firmware_analysis: firmware #1 orig_dump.bin, run #1: string @0x14ee0

Item	Value	Confidence	Sources
Device information	platform m7642	97%	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 4 sources: property string @0x40635; extracted file 0x00030000_gzip/cpio_contents/system/build.prop; extracted file 0x00050000_zip/system/build.prop; …; firmware_analysis: firmware #1 orig_dump.bin, run #1: 4 sources: property string @0x40635; extracted file 0x00030000_gzip/cpio_contents/system/build.prop; extracted file 0x00050000_zip/syst
Device information	model TESTTV55	97%	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 4 sources: property string @0x4061b; extracted file 0x00030000_gzip/cpio_contents/system/build.prop; extracted file 0x00050000_zip/system/build.prop; …; firmware_analysis: firmware #1 orig_dump.bin, run #1: 4 sources: property string @0x4061b; extracted file 0x00030000_gzip/cpio_contents/system/build.prop; extracted file 0x00050000_zip/syst

Counts: application 0, library 0, driver 0, network_interface 0, display 2, audio 0

2. Installed applications

No evidence found.

3. System libraries

No evidence found.

4. Hardware drivers / kernel modules

No evidence found.

5. Network interfaces

No evidence found.

6. Display configuration

Name	Detail	Source
PanelName	LC550EGE	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 0x00030000_gzip/cpio_contents/vendor/config/panel/panel_lc550ege.ini
m_wPanelWidth	3840	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 0x00030000_gzip/cpio_contents/vendor/config/panel/panel_lc550ege.ini
PanelName	LC550EGE	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 0x00040000_tar/vendor/config/panel/panel_lc550ege.ini
m_wPanelWidth	3840	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 0x00040000_tar/vendor/config/panel/panel_lc550ege.ini
PanelName	LC550EGE	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 0x00050000_zip/vendor/config/panel/panel_lc550ege.ini
m_wPanelWidth	3840	firmware_analysis: firmware #2 upgrade_tv_v2.bin, run #2: 0x00050000_zip/vendor/config/panel/panel_lc550ege.ini
PanelName	LC550EGE	firmware_analysis: firmware #1 orig_dump.bin, run #1: 0x00030000_gzip/cpio_contents/vendor/config/panel/panel_lc550ege.ini
m_wPanelWidth	3840	firmware_analysis: firmware #1 orig_dump.bin, run #1: 0x00030000_gzip/cpio_contents/vendor/config/panel/panel_lc550ege.ini
PanelName	LC550EGE	firmware_analysis: firmware #1 orig_dump.bin, run #1: 0x00040000_tar/vendor/config/panel/panel_lc550ege.ini

Name	Detail	Source
m_wPanelWidth	3840	firmware_analysis: firmware #1 orig_dump.bin, run #1: 0x00040000_tar/vendor/config/panel/panel_lc550ege.ini
PanelName	LC550EGE	firmware_analysis: firmware #1 orig_dump.bin, run #1: 0x00050000_zip/vendor/config/panel/panel_lc550ege.ini
m_wPanelWidth	3840	firmware_analysis: firmware #1 orig_dump.bin, run #1: 0x00050000_zip/vendor/config/panel/panel_lc550ege.ini

7. Audio configuration

No evidence found.