


1 Issue


A reflected Cross Site Scripting issue was identified on several Zyxel devices, on pages that use the **mp_idx** parameter. The affected pages, included in this report, do not require authentication.

² Description

The issue was identified during a Network Penetration Test for a SecurityMetrics, Inc. customer using several Zyxel devices. While investigating devices that appeared on the Port Scan, the analyst noted there were several login pages, similar to the following:




The analyst referenced Zyxel documentation, such as the web_portal_html_guide.pdf:



To identify what parameters are used and what pages use the parameter. Several pages use the **mp_idx** parameter and include it in the page without validation. A request such as \$HOST/ weblogin.cgi?mobile=1&mp_idx=";alert(1);// injects the **mp_idx** parameter in the source of the page:

The alert is interpreted and triggered when the page is visited:



3 Affected Pages and Devices

The analyst has verified the following pages are vulnerable:

- weblogin.cgi
- webauth_relogin.cgi

Additional devices and pages may also be vulnerable, however, this was a black box test. Credentials were not provided, pages requiring authentication were not tested, and additional devices were not available for testing. The following devices are known to be vulnerable:

- ZyWALL 310
- ZyWALL 110
- ATP 500
- USG1900
- USG40