d) Feature Importance for Changes in Req. & Qual. Unc. 1000 Months in service Num. activities 800 Num. projects Qual. Features (Origin) Valle del Cauca Frequency in 1000 bootstraps (Origin) Huila -(Origin) Nariño -600 (Origin) Cauca in Req. & (S) Design changes (S) Unnecessary client interferences -400 Changes (S) Technical spec. changes (S) Equipment changes (S) Unclear client requirements - 200 (S) Design misalig. with client expect. (S) Design error 0 0.2 0.0 0.1 0.3 0.4 0.5 Avg. Importance