01

58khz

Connect the device to
a power source

02

58khz

Bring the label closer to
the demagnetizer

03

58khz

Beep

When the beep sounds,
demagnetization is successful