	Parameters: Illumination	WEM Results						GPI Result	s			
GPI Plant Location		Minimum	Maximum	Actual	OSH Standard	Result	Verification			Correction (as advised by Admin/FEM during verification in each area)	Responsible	Remarks
				<u> </u>	Ctandard		Minimum	Maximum	Evaluation	verification in each drea		
GPI 8	(Richard Mojica's Table) [office works]	<40	<40	<40	300	Failed	71	72	Failed	Provision of LED Lights (2pcs)	Admin/EEM	Overall sequence of Corrective Action:
GPI 8	Inspection Table) [secc metal plate bending inspection]	462	463	463	500	Failed	447	448	Failed	Additional LED lights (2pcs) with reflector	Admin/FEM	1. May 06-08, 2024 - filing of
GPI 8	[secc metal plate measuring and hole measuring]	328	329	329	500	Failed	306	306	Failed	Additional LED lights (1pc) or reflector	Admin/FEM	J.O 2. May 13-17, 2024 - request of
GPI 8	Fabrication Office [office]	100	101	101	300	Failed	118	118	Failed	Provision of LED Lights (2pcs) - movable type	Admin/FEM	materials 3. May 20-27, 2024 - activity for
GPI 8	Molding Office [office works]	51	52	52	300	Failed	28	39	Failed	Provision of LED Lights (2pcs) - movable type	Autilit/TEPT	correction 4. May 28, 2024 - submission of result to PEZA