Branch-Smith Restoration

32699 Bobby Drive Apt. 740, Mariafurt, CA 10237 | License # CRC697356

ESTIMATE EST-9262

Date Received	02/19/2026
Date Inspected	02/21/2026
Estimate Date	03/11/2026
Insured	Larry Smith
Property	23100 Robles Fall Apt. 783, South Dawn, DE 52255
Claim Number	CLM-3769526
Policy Number	HO911-116166
Date of Loss	02/19/2026
Type of Loss	Hail damage to roof and gutters

Garage

	DESCRIPTION	QTY	REPLACE	TAX	O&P	TOTAL
1.	Remove drywall - 1/2"	92.3 SF	0.53	1.50	9.78	60.20
2.	Air mover (per 24 hour period)	4 DA	30.22	4.10	24.18	149.16
	Totals: Garage			**5.60**	**33.96**	**209.36**

Master Bedroom

	DESCRIPTION	QTY	REPLACE	TAX	O&P	TOTAL
3.	Clean ceiling - heavy smoke	503.38 SF	0.87	8.84	87.59	534.37
4.	Water extraction from carpeted floor	475.26 SF	0.58	8.26	55.13	339.04
5.	Apply antimicrobial agent	315.37 SF	0.22	2.29	13.88	85.55
6.	Baseboard - 3 1/4" MDF	34.79 LF	3.06	2.09	21.29	129.84
7.	Water extraction from carpeted floor	428.25 SF	0.55	8.52	47.11	291.17
	Totals: Master Bedroom			**30.00**	**225.00**	**1,379.97**

Bathroom

	DESCRIPTION	QTY	REPLACE	TAX	O&P	TOTAL
8.	Interior door - slab only	2 EA	248.10	10.79	99.24	606.23
9.	Install drywall - 1/2" hung, taped, floated	166.23 SF	3.03	13.90	100.74	618.32
10.	Apply antimicrobial agent	232.82 SF	0.34	1.74	15.83	96.73
11.	Water extraction from carpeted floor	461.79 SF	0.85	11.01	78.50	482.03
	Totals: Bathroom			**37.44**	**294.31**	**1,803.31**

Line Item Total	$2,766.33
Material Sales Tax	$73.04
Subtotal	$2,839.37
Overhead & Profit	$553.27
Replacement Cost Value	**$3,392.64**