

```
R1_ohm = 2; R2_ohm = 3; Rs_ohm = 1;  
V1_V = 5; V2_V = 2;  
A_ohm = [R1_ohm+Rs_ohm, -Rs_ohm; ...  
          -Rs_ohm, R2_ohm+Rs_ohm];  
b_V = [V1_V; V2_V];  
x_A = A_ohm\b_V;  
I1_A = x_A(1);  
I2_A = x_A(2);
```