

ADD Instruction

X1	X2	X3	
Output Instruction Register 2 to the Bus	Output ScratchPad Addressed to the Bus	Output Adder Sum to the Bus	Increment Program Counter
Load ScratchPad Index Reg from the Bus	Load Temporary Register from the Bus	Load Acc Register from the Bus	Reset Micro Instruction Step Counter
	Address ScratchPad Individually using low order bit		Load Second Stage of Carry