



UNIT 6/7 BUCKINGHAM SQUARE, HURRICANE WAY, WICKFORD, ESSEX SS11 8YQ  
Telephone: 01268 562102

Email: sales@plantexpand.com / admin@plantexpand.com

Registered No. 2194749 VAT REG No. 466001473



## Job Summary Report

### Asset Details

Asset No:	WX24UFM	Make/Model:	Mercedes-Benz Sprinter
Customer:	Cadent	Site Address / Contact:	Plantexpand Workshop
Miles/Hours:	10275	Serial No:	wx24ufm

### Completion Details

Date:	10/11/2025	Compliance Type:	Service - Other - Specify in Repairs
Next Service Date:	09/11/2026	Compliance Title:	Axtec On Board
Service Completed?	No	Additional Tasks Complete?	No
All Works Completed?	No	Return Visit Needed?	Yes
Consumables Used?	No	Asset Safe To Use?	Yes

Job Duration: 0.5 Overtime: No Travel : 0.0 Job ID : 28

## Compliance Checklist

### Axtec On Board Weighing

Task Description	Result
------------------	--------

Chassis number	W1V3KBFZXRP653277
System serial number	n/a
Is the system powering up ok?	No
Check condition & security of cab mounted display screen	N/A
Carry out visual examination of front & rear system installation	N/A
Were any repairs required to the system prior to ZERO adjust process?	Yes
Is the system displaying "data logger full"?	No
If data logger is full, please complete clear down of data.	No
Check RAW Weights are within tolerance (10,000 - 30,000)	N/A
Ensure RAW Weights are not displayed in red, fluctuating excessively or at zero.	N/A
Check CAL Factors are within the expected range (0.06 - 2.00)	N/A
If RAW & CAL are as expected, park first axle onto weigh pads.	N/A
Follow ZERO ADJUST procedure for both axles.	N/A
System firmware version	N/A
Weight Limits (Using VIN plate)	3500
RAW Weight	N/A
CAL Factor	N/A
Include pictures of system data.	Yes
Using the weigh pads, is this vehicle exceeding the GVW?	No
Weighing System Operational?	No

## Repairs Required

### Engineer Comments

FAULT 62 CALL SERVICE on screen not reading weights checked springs not broken. loose connection between cable and screen. book in for diagnostics and possible screen replacement

### Fault Reason Repair Duration

Reason 1.0

## Parts Used

## Parts Still Required

Technician Name:

joe.butler

Signature:

## Images

