FIELD EXECUTION SCHEDULE: RISER TAPE MEASURES & PIPE CUT-LIS
Exact field dimensions from reference origins for excavation, plumbing, and ris

Station C	Referenc	Tape Mea	Global C	Zone / Su	Trench / F	Covered I	Pipe Cut I
Tee A	Plot A Ce	0	(500, 100	Plot A Ce	Mainline F	Y = 100	215 ft We
Riser A1	Tee A (50	30	(500, 130	Plot A Arr	5 ft Trenc	Y = 115 t	1x 4ft 2" F
Riser A2	Tee A (50	60	(500, 160	Plot A Arr	5 ft Trenc	Y = 145 t	1x 4ft 2" F
Riser A3	Tee A (50	90	(500, 190	Plot A Arr	5 ft Trenc	Y = 175 t	1x 4ft 2" F
Riser A4	Tee A (50	120	(500, 220	Plot A Arr	5 ft Trenc	Y = 205 t	1x 4ft 2" F
End Cap	Tee A (50	145	(500, 245	Plot A Ma	Terminal	Y = 245	1x 2" End
Tee B	Plot B En	0	(285, 100	Plot B Ea	Mainline F	Y = 100	Connecte
Riser B1	Tee B (28	24	(285, 124	Plot B Arr	8 ft Row S	Y = 92 to	1x 4ft 2" F
Riser B2	Tee B (28	88	(285, 188	Plot B Arr	8 ft Row S	Y = 156 t	1x 4ft 2" F
Riser B3	Tee B (28	152	(285, 252	Plot B Arr	8 ft Row S	Y = 220 t	1x 4ft 2" F
Riser B4	Tee B (28	216	(285, 316	Plot B Arr	8 ft Row S	Y = 284 t	1x 4ft 2" F
End Cap	Tee B (28	240	(285, 340	Plot B Ma	Terminal	Y = 340	1x 2" End