












USBSS

POWER






SPI FLASH






NC

DEBUG




MCU




USBSS

POWER






SPI FLASH







NC




DEBUG




MCU



POWER&USB




POWER-1.2V




If use CH2003K, all NC in POWER-1.2V need to be welded;
if use CH2003V, R6 and C4 not be welded and R4 need to be welded 0Ω.





XTAL





KEY




PIN




MCU




LED





ETH




POWER&USBPD





POWER&USB




POWER-1.2V




MCU




XTAL




KEY




PIN




LED



POWER&USBPD




POWER&USB




MCU


POWER-1.2V




XTAL



KEY



LED



PIN

