

ARROW AUTO BODY, INC

Workfile ID: e98ec842 Federal ID: 35-2128232

Power Trunk/Liftgate

ARROWAUTOBODY@FRONTIER.COM 808 W COLISEUM BLVD, FORT WAYNE, IN 46808

> Phone: (260) 482-6822 FAX: (260) 482-4632

Preliminary Supplement 4 with Summary

Customer: MUTUURA, HELEN Job Number:

Written By: Donna Oswalt Adjuster: RZO1

Insured: MUTUURA, HELEN Policy #: PT5010A6146391712031 Claim #: I9K7016001

Type of Loss: Collision Date of Loss: 1/31/2024 1:00 PM Days to Repair: 4

Point of Impact: 01 Right Front

Owner: Inspection Location: Insurance Company:

MUTUURA, HELEN FORT WAYNE, IN 46805-0000 TRAVELERS - THE STANDARD FIRE INSURANCE

COMPANY

1622 HOBSON RD Virtual AUTO EXPRESS - NATIONAL

FORT WAYNE, IN 46805-4876 ORLANDO

(973) 234-4320 Cell

Overhead Console

VEHICLE

2014 TOYO RAV4 LE AWD 4D UTV 4-2.5L Gasoline Sequential MPI Red

VIN: JTMBFREVXEJ007006 Interior Color: Ash Mileage In: 69,429 Vehicle Out:

License: WJX985 Exterior Color: Red Mileage Out:

State: IN Production Date: 5/2014 Condition: Job #:

 TRANSMISSION
 Air Conditioning
 Search/Seek
 SEATS

 Automatic Transmission
 Intermittent Wipers
 CD Player
 Cloth Seats

4 Wheel Drive Tilt Wheel Auxiliary Audio Connection Bucket Seats

POWER Cruise Control SAFETY Reclining/Lounge Seats

Power SteeringRear DefoggerDrivers Side Air BagWHEELSPower BrakesKeyless EntryPassenger Air BagWheel CoversPower WindowsMessage CenterAnti-Lock Brakes (4)PAINT

Power Locks Steering Wheel Touch Controls 4 Wheel Disc Brakes Clear Coat Paint
Power Mirrors Rear Window Wiper Traction Control Metallic Paint

DECORTelescopic WheelStability ControlOTHERDual MirrorsBackup CameraFront Side Impact Air BagsRear SpoilerPrivacy GlassRADIOHead/Curtain Air BagsCalifornia Emissions

Console/Storage AM Radio Hands Free Device **TRUCK**

CONVENIENCE Stereo Luggage/Roof Rack

FM Radio

Get live updates at www.carwise.com/e/55W4Tu

ROOF

5/20/2025 2:05:23 PM 437602 Page 1

Customer: MUTUURA, HELEN

Job Number:

2014 TOYO RAV4 LE AWD 4D UTV 4-2.5L Gasoline Sequential MPI Red

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	SPECIAL PREC	AUTIC	DN			•		
2	# S03		D&R BATTERY		1		0.2	
3	FRONT BUMPE	R & G	RILLE					
4		R&I	R&I bumper cover				1.2	
5	FRONT LAMPS							
6		R&I	RT R&I headlamp assy				0.2	
			Note: LABOR: Time is after bumper co	ver is removed.				
7	FENDER		DT 5 1 2 1 10				2.0	4.0
8	* S02	Rpr	RT Fender Japan built				<u>2.0</u>	1.8
			Note: Scratches & dents see photos					
9	S01		Add for Clear Coat					0.7
10		R&I	RT Wheel opng mldg Japan Built				0.3	
11		R&I	RT Corner molding Japan built				0.1	
12	S04	R&I	RT Fender liner Canada built				0.4	
13	RESTRAINT SY	STEM	S					
14	S01	R&I	RT Side impact sens front door Japan built			m	0.2 M	
			Note: Replacing door must be installed	in new used door				
15	S02	Repl	Air bag system diagnosis		1	m	0.5 M	
16	PILLARS							
17	# S03		BLEND UPPER OUTER INCL W/S PILLAR & CC		1			1.0
18	FRONT DOOR							
19	S02	Repl	RT Door shell Japan built (HSS)	6700142140	1	908.01	4.8	3.0
20	S02		Overlap Major Adj. Panel					-0.4
21	S02		Add for Clear Coat					0.5
22	S03	Refn	RT Handle, outside w/o smart entry, Japan built black					0.5
			Note: See photo					
23	S03		Overlap Minor Panel					-0.2
24	S03		Add for Clear Coat					0.1
25	S02	Repl	RT Water shield	678310R041	1	26.06	Incl.	
			Note: PARTS: Part cannot be reused/re					
			Must be removed to replace door one to					
26	S02	Repl	RT Black out tape	759210R030	1	33.50	0.3	
27	S02	Repl	RT Applique	757550R010	1	41.06	Incl.	
28	S02	Repl	RT Lower molding Japan built	7507342011	1	251.65	0.3	
29	S04	Repl	RT Corner trim Japan built Note: SEE PART INVOICE \$37.29 LIST.	674910R030	1	37.29	0.1	
30	S04	Repl	LT Door shell cushion Note: STOCK 2 of these are required.	9054109137	2	7.06		

Customer: MUTUURA, HELEN

Job Number:

2014 TOYO RAV4 LE AWD 4D UTV 4-2.5L Gasoline Sequential MPI Red

31	REAR	DOOR								
32	*	S04	Rpr	RT Door shell Japan built (HSS)				4.0	2.0	
				Note: Damage goes past the outer panel Damage on edge of door (near the RF door and RT QTR as well a the center of the door) see photo. Blending within a panel takes more time and materials than full refinish. documention attached.						
33		S01		Overlap Major Adj. Panel	erlap Major Adj. Panel					
34		S01		Add for Clear Coat	for Clear Coat					
35		S04		Add for Edging					0.5	
				Note: see photo						
36	#	S04		Unable to do partial basecoat refinish d/t entire door		1				
				Note: needed refinished. See picture. R Paint Labor. Line # 32.	efinished the Front door	r and Qtr a	also. Please remo	ve 0.3 deduction fro	m	
37			R&I	RT Belt molding				0.2		
38		S01	R&I	RT Lower molding Japan built				0.3		
				Note: PARTS: Part has related compone pad rear.	ents that cannot be reus	sed/ reinst	alled; seal, pad u	pper, pad lower and		
39		S04	Refn	RT Handle, outside Japan built red					0.5	
				Note: See photo. Refinished for color m	natch.					
40		S04		Overlap Minor Panel					-0.2	
41		S04		Add for Clear Coat					0.:	
42			R&I	RT Handle, outside Japan built red				0.3		
43			R&I	RT R&I trim panel				0.4		
44	*	S04	Repl	RT Lower molding pad upper	7579742030	1	<u>12.30</u>			
				Note: PARTS: Part cannot be reused/re PART PRICE INCREASE	installed.					
45		S01	Repl	RT Lower molding pad lower	757670R010	1	11.18			
				Note: PARTS: Part cannot be reused/re	installed.					
46		S01	Repl	RT Lower molding pad rear	757980R030	1	11.18			
				Note: PARTS: Part cannot be reused/re	installed.					
47	•	TER PAN	IEL							
48	*	S04	Rpr	RT Quarter panel				<u>1.5</u>	2.6	
				Note: see photo of damage						
49		S01		Overlap Major Adj. Panel					-0.4	
50		S01		Add for Clear Coat					0.4	
51		S02	Repl	RT Wheel opng mldg Japan Built	756050R030	1	131.42	0.4		
52		S01	Repl	RT Quarter glass Toyota Japan built	627100R060	1	106.10	2.2		
				Note: PARTS: Part cannot be reused/re removed.	installed. LABOR: Time	is after up	per and lower qu	arter trim panels are	9	
53		S01	R&I	RT Lower qtr trim Japan built				0.7		
54		S01	R&I	RT Upper qtr trim Japan built				0.3		
55		S04	Repl	LT Wheelhouse liner fastener Note: STOCK	9046706121	2	12.36			
56	DEAD	LAMPS								

56 **REAR LAMPS**

ust	omer: I	MUTUL	JRA, I	HELEN				Job Nu	umber:
)14 T	OYO RAV	4 LE AWI	4D U	TV 4-2.5L Gasoline Sequential MPI Rec	d				
57	**	S04	Repl	A/M CAPA RT Tail lamp	8155142161	1	96.02	0.3	
58		S04	Repl	RT Tail lamp	8155142161	1	117.00	Incl.	
59	REAR	BUMPER							
60		S01	R&I	R&I bumper cover				1.0	
				Note: To refinish QTR					
61	VEHIC	LE DIAG	NOST	ICS					
62	#	S02		Pre - Scan		1	60.00 X	0.5 M	
				Note: see invoice attached					
63	#	S01		Post - Scan		1	60.00 X	0.5 M	
64	MISCE	LLANEC	US OF	PERATIONS					
65	#	S04	Refn	Test Spray Out					1
				Note: see photo.					
				item to achieve a blendable match. It painting is necessary to restore the Nalso, please see photo regarding pain CONTAINS A RARE LIMITED USE PIGE.	vehicle to pre-loss condition nt formula cost for Barcelo	n. na Red fro	om the paint manu		
66	#	S03	Subl	Hazardous waste removal	ONEITH COOT ENGLESS IN	1	3.00 X		
67	#	S03	oub.	Car Cover		1	7.00	0.2	
•				Note: For primer \$5.00 is below our cost		-	7.00	V.=	
68	#	S03		2nd Car Cover		1	7.00	0.2	
				Note: For paint					
				\$ 5.00 is below our cost					
69	#	S01		Urethane kit		1	25.00		
70	#	S02	Repl	Corrosion protection		1	7.00 T	0.2	
71	#	S01		Mask Jamb(s)		1	4.00	0.2	
72	#	S01	Repl	Remove adhesive		1	3.00 T	0.3	
			·	Note: W/O MLDG on QTR panel remo	ove adhesive from body to	refinish			
73	#	S04		LABOR RATES ADJUSTED TO LOWEST CONTRACTED RATES		1			
				Note: CUSTOMER TO PAY DIFFEREN TRAVELERS HAS ON THEIR ESTIMA OUR AREA ARE MORE THAN \$60/40,	TE \$60/40/95. CAN PROVII				
74	#	S04		Color sand and buff		1		2.0	
75	#	S04		Material Invoice attached		1	97.71		
76	#	S04		Seat Weight Sensor calibration		1	119.95 X		
				Note: Meline on wester selling?					
				Note: Waiting on parts; calibration to	o be done after vehicle is a	ssembled.			

Customer: MUTUURA, HELEN

Job Number:

2014 TOYO RAV4 LE AWD 4D UTV 4-2.5L Gasoline Sequential MPI Red

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				1,942.90
Body Labor	24.6 hrs	@	\$ 62.00 /hr	1,525.20
Paint Labor	13.9 hrs	@	\$ 62.00 /hr	861.80
Mechanical Labor	1.7 hrs	@	\$ 100.00 /hr	170.00
Paint Supplies	13.9 hrs	@	\$ 42.00 /hr	583.80
Miscellaneous				252.95
Subtotal				5,336.65
Sales Tax	\$ 2,536.70	@	7.0000 %	177.57
Grand Total				5,514.22
Deductible				1,000.00
CUSTOMER PAY				1,000.00
INSURANCE PAY				4,514.22

Customer: MUTUURA, HELEN

Job Number:

2014 TOYO RAV4 LE AWD 4D UTV 4-2.5L Gasoline Sequential MPI Red

SUPPLEMENT SUMMARY

Line			Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Chang	ed Items								
28		S02	Repl	RT Corner trim Japan built	674910R030	1	-37.29	-0.1	
29		S04	Repl	RT Corner trim Japan built	674910R030	1	37.29	0.1	
				NOTE: SEE PART INVOICE \$37.29 LIS	ST.				
30	*	S02	Rpr	RT Door shell Japan built (HSS)				<u>-3.5</u>	-2.0
				NOTE: Damage goes past the outer p the center of the door) see photo	anel Damage on edge of	f door (ne	ear the RF door ar	nd RT QTR as well	as in
32	*	S04	Rpr	RT Door shell Japan built (HSS)				<u>4.0</u>	2.0
				NOTE: Damage goes past the outer p the center of the door) see photo. Ble documention attached.					
33	*	S03		Add for Edging					<u>-0.2</u>
				NOTE: see photo					
35		S04		Add for Edging					0.5
				NOTE: see photo					
38		S01	Repl	RT Lower molding pad upper	7579742030	1	-11.18		
				NOTE: PARTS: Part cannot be reused	/reinstalled.				
44	*	S04	Repl	RT Lower molding pad upper	7579742030	1	<u>12.30</u>		
				NOTE: PARTS: Part cannot be reused PART PRICE INCREASE	/reinstalled.				
42	*	S02	Rpr	RT Quarter panel				<u>-1.0</u>	-2.6
				NOTE: see photo of damage					
48	*	S04	Rpr	RT Quarter panel				<u>1.5</u>	2.6
				NOTE: see photo of damage					
59	#	S03	Refn	Test Spray Out					-0.5
				NOTE: see photo					
65	#	S04	Refn	Test Spray Out					1.5
				NOTE: see photo. 3 Spray outs were completed by our pitem to achieve a blendable match. Hipainting is necessary to restore the vealso, please see photo regarding pain CONTAINS A RARE LIMITED USE PIG	owever, they are not inc chicle to pre-loss condition t formula cost for Barcel	lluded in t on. ona Red	the base refinish t from the paint ma	ime allocated whe	n
68	#	S03		LABOR RATES ADJUSTED TO LOWEST CONTRACTED RATES		1			
73	#	S04		LABOR RATES ADJUSTED TO LOWEST CONTRACTED RATES		1			
				NOTE: CUSTOMER TO PAY DIFFERENT TRAVELERS HAS ON THEIR ESTIMAT OUR AREA ARE MORE THAN \$60/40/9	E \$60/40/95. CAN PROV				
Delete	d Items								
49	REAR LA	MPS							
50		S01	R&I	RT Tail lamp				-0.3	

Custo	Customer: MUTUURA, HELEN Job Numb								umber:
2014 TO	2014 TOYO RAV4 LE AWD 4D UTV 4-2.5L Gasoline Sequential MPI Red								
57	#	S01	Refn	Test Spray Out					-0.5
58	#	S03	Refn	Tint Color	• •				
67	#	S03		Feather edge prime and block					-0.5 -1.0
07	"	303	rtein	NOTE: See photo and CCC P- pages					1.0
Added	Items			Note: See photo and eee 1 pages					
12	2001110	S04	R&I	RT Fender liner Canada built				0.4	
30		S04	Repl	LT Door shell cushion	9054109137	2	7.06		
				NOTE: STOCK		_			
				2 of these are required.					
36	#	S04		Unable to do partial basecoat		1			
				refinish d/t entire door					
				NOTE: needed refinished. See picture. R Paint Labor. Line # 32.	efinished the Front doc	or and Qtr	also. Please re	move 0.3 deduction	n from
39		S04	Refn	RT Handle, outside Japan built red					0.5
				NOTE: See photo. Refinished for color m	atch.				
40		S04		Overlap Minor Panel					-0.2
41		S04		Add for Clear Coat					0.1
55		S04	Repl	LT Wheelhouse liner fastener	9046706121	2	12.36		
				NOTE: STOCK					
56	REAR	LAMPS							
57	**	S04	Repl	A/M CAPA RT Tail lamp	8155142161	1	96.02	0.3	
58		S04	Repl	RT Tail lamp	8155142161	1	117.00	Incl.	
74	#	S04		Color sand and buff		1		2.0	
75	#	S04		Material Invoice attached		1	97.71		
76	#	S04		Seat Weight Sensor calibration		1	119.95 X		
				NOTE: Waiting on parts; calibration to be	e done after vehicle is a	assembled	d		
				SUE	BTOTALS		451.22	3.4	-0.3

TOTALS SUMMARY

Category	Basis		Rate	Cost \$
Parts				331.27
Body Labor	3.4 hrs	@	\$ 62.00 /hr	210.80
Paint Labor	-0.3 hrs	@	\$ 62.00 /hr	-18.60
Paint Supplies	-0.3 hrs	@	\$ 42.00 /hr	-12.60
Miscellaneous				119.95
Subtotal				630.82
Sales Tax	\$ 318.67	@	7.0000 %	22.31
Total Supplement Amount				653.13
NET COST OF SUPPLEMENT				653.13

Customer: MUTUURA, HELEN Job Number:

2014 TOYO RAV4 LE AWD 4D UTV 4-2.5L Gasoline Sequential MPI Red

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate	1,833.02	ERIC SCHATVET
Supplement S01	2,973.36	Maggie Sands
Supplement S02	97.92	Donna Oswalt
Supplement S03	-43.21	Donna Oswalt
Supplement S04	653.13	Donna Oswalt

Job Total: \$ 5,514.22 CUSTOMER PAY: \$ 1,000.00 INSURANCE PAY: \$ 4,514.22

All supplements must be pre-approved by Travelers.

Supplement repair charges may be subject to rejection unless approved by Travelers prior to repairs.

This instrument is a damage estimate only and not an acceptance of liability or authorization to repair.

Repair must be pre-authorized by the vehicle owner.

Vehicle owner maintains the right to repair vehicle at a repair facility of their choice.

Please present this estimate to the repair facility prior to repairs.

Necessary Information for Photograph and Video Estimates (READ CAREFULLY):

This estimate may have been completed based wholly or in part using photographs and/or video. Because of the use of photographs and video, this estimate may not be complete, as there could be hidden damage. You should provide this estimate to the shop of your choice prior to commencement of work. If your shop finds additional damages or undiscovered damages, Travelers will work with your repairer to assess the appropriate scope of work. Your shop is instructed in this estimate to contact Travelers through its supplement process and the damages they discover must be reviewed and approved prior to repairing the vehicle In the event that you are not repairing your vehicle and believe that our estimate does not account for all of your damages, please contact your Claim professional to discuss and address your concerns and options.

A PERSON WHO KNOWINGLY AND WITH INTENT TO DEFRAUD AN INSURER FILES A STATEMENT OF CLAIM CONTAINING ANY FALSE, INCOMPLETE, OR MISLEADING INFORMATION COMMITS A FELONY.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Customer: MUTUURA, HELEN

Job Number:

2014 TOYO RAV4 LE AWD 4D UTV 4-2.5L Gasoline Seguential MPI Red

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARM8451, CCC Data Date 05/08/2025, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Customer: MUTUURA, HELEN

Job Number:

2014 TOYO RAV4 LE AWD 4D UTV 4-2.5L Gasoline Sequential MPI Red

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
30	Bill Estes Toyota	#9054109137	\$ 3.53
	3232 Harper Road	LT Door shell cushion	
	Indianapolis IN 46240	Quote: 2354356774	
		Expires: 07/05/24	
	HeadlightsDepot	#312-19B6R-UC	\$ 96.02
	8701 W 47th Street Ste E	A/M CAPA RT Tail lamp	
	McCook IL 60525	Quote: 2400281441	
	(855) 544-4875	Expires: 06/25/24	