




B10_10_T90X_W2_KA_LMG





KITE(35.01.24341.44)

SpecReference :







Higher resolution images are resized by 70% | Sat Feb 14 09:21:05 IST 2026

Detailed Test Report














Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
Set Device to ROBOT MG400 and External Camera Basler [SUCCESS]	SET_DEVICE	Set ROBOT device [MGROBOT] to perform operation	Robot device with deviceId [MGROBOT] is set successfully to perform operation	[Pass]
	SET_DEVICE	Set camera device [camera1] as DUT to perform operations	Camera device is set to perform operation	[Pass]
Go to Homescreen Page1 [SUCCESS]	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	CLICK_BY_IMAGE			[Pass] 1. Image found [with confidence 99.0%]. 2. Position identified in image [147.0]:[262.0]. 3. Robot click performed .
	WAIT	Wait for [500] milliseconds	Wait for [500] milliseconds completed successfully	[Pass]
	CLICK_BY_IMAGE			[Pass] 1. Image found [with confidence 99.0%]. 2. Position identified in image [147.0]:[262.0]. 3. Robot click performed .
	WAIT	Wait for [500] milliseconds	Wait for [500] milliseconds completed successfully	[Pass]
Switch Control to Phone1 [SUCCESS]	SET_DEVICE	Set AppiumAndroid device with device Id [AndroidPhone1] as DUT to perform operation	AppiumAndroid device with device ID [AndroidPhone1] set successfully	[Pass]
	WAIT	Wait for [200] milliseconds	Wait for [200] milliseconds completed successfully	[Pass]
	SET_HOME	Go to Android home screen	Android Device set to Home screen	[Pass]
	SET_HOME	Go to Android home screen	Android Device set to Home screen	[Pass]
Launch Link Manager Application on Phone [SUCCESS]	ADB_KEY_EVENT	Send Key events [KEYCODE_APP_SWITCH] on android device	KEYCODE_APP_SWITCH Key events send on android device	[Pass]
	ADB_KEY_EVENT	Send Key events [20] on android device	20 Key events send on android device	[Pass]
	WAIT	Wait for [10000] milliseconds	Wait for [10000] milliseconds completed successfully	[Pass]
	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]
	IF	VERIFY_TEXT_BY_TEXT shall PASS	IF [Pass], VERIFY_TEXT_BY_TEXT Result-[SUCCESS : Element with text [Close all] found]	[Pass]
	CLICK_BY_TEXT	Click on text [Close all]	Clicked on element with text [Close all]	[Pass]
	ENDIF	NA	NA	[Pass]
	SET_HOME	Go to Android home screen	Android Device set to Home screen	[Pass]
	WAIT	Wait for [500] milliseconds	Wait for [500] milliseconds completed successfully	[Pass]
	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]
	CLICK_BY_TEXT	Click on text [MicroServer]	Clicked on element with text [MicroServer]	[Pass]
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]
	CLICK_BY_TEXT	Click on text [STOP]	Clicked on element with text [STOP]	[Pass]
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]
	CLICK_BY_TEXT	Click on text [START]	Clicked on element with text [START]	[Pass]
Wait till Link Manager Status is Connected on Phone [SUCCESS]	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]
	WHILENOT			[ROI1] [74.0%] [Fail] Section not found on Screen
	CLICK_BY_TEXT	Click on text [STOP]	Clicked on element with text [STOP]	[Pass]
	WAIT	Wait for [500] milliseconds	Wait for [500] milliseconds completed successfully	[Pass]

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	CLICK_BY_TEXT	Click on text [START]	Clicked on element with text [START]	[Pass]
	WAIT	Wait for [500] milliseconds	Wait for [500] milliseconds completed successfully	[Pass]
	CLICK_BY_TEXT	Click on text [Enable]	Clicked on element with text [Enable]	[Pass]
	WAIT	Wait for [500] milliseconds	Wait for [500] milliseconds completed successfully	[Pass]
	CLICK_BY_TEXT	Click on text [Enable]	Clicked on element with text [Enable]	[Pass]
	WAIT	Wait for [20000] milliseconds	Wait for [20000] milliseconds completed successfully	[Pass]
	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [100%] [Pass] Section Found on Screen
	END_WHILE			[ROI1] [100%] [Pass] Section Found on Screen
	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]













Result : ■ Pass ■ Statement is not considered for result evaluation(loop and conditional statements)
■ Fail ■ Statement is executed asynchronously
■ Verify Manually

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	WHILENOT			[ROI1] [100%] [Pass] Section Found on Screen
	END_WHILE			[ROI1] [100%] [Pass] Section Found on Screen
Validate Link Manager Status is Connected on Phone [SUCCESS]	WAIT	Wait for [1500] milliseconds	Wait for [1500] milliseconds completed successfully	[Pass]
	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]
	IS_SECTION_PRESENT			[ROI1] [100%] [Pass] Section Found on Screen
Set Device to ROBOT MG400 and External Camera Basler [SUCCESS]	SET_DEVICE	Set ROBOT device [MGROBOT] to perform operation	Robot device with deviceId [MGROBOT] is set successfully to perform operation	[Pass]
	SET_DEVICE	Set camera device [camera1] as DUT to perform operations	Camera device is set to perform operation	[Pass]
Go to Homescreen Page1 [SUCCESS]	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]











Result : ■ Pass ■ Statement is not considered for result evaluation(loop and conditional statements)
■ Fail ■ Statement is executed asynchronously
■ Verify Manually

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	CLICK_BY_IMAGE			[Pass] 1. Image found [with confidence 99.0%], 2. Position identified in image [147.0]:[262.0], 3. Robot click performed .
	WAIT	Wait for [500] milliseconds	Wait for [500] milliseconds completed successfully	[Pass]
	CLICK_BY_IMAGE			[Pass] 1. Image found [with confidence 99.0%], 2. Position identified in image [147.0]:[262.0], 3. Robot click performed .
Go to General Settings from Home Screen [SUCCESS]	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	WHILENOT			[ROI1] [73.0%] [Fail] Section not found on Screen
	SWIPE	Swipe operation performed from co-ordinates [715.0]:[543.0] to [418.0]:[540.0]	Swipe operation performed from co-ordinates [715.0]:[543.0] to [418.0]:[540.0] successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	WAIT	Wait for [500] milliseconds	Wait for [500] milliseconds completed successfully	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [95%] [Pass] Section Found on Screen
	END_WHILE			[ROI1] [95%] [Pass] Section Found on Screen
	CLICK_BY_IMAGE			[Pass] 1. Image found [with confidence 98.0%], 2. Position identified in image [665.0]:[398.0], 3. Robot click performed .
Select Connections on General Settings Screen [SUCCESS]	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	CLICK_BY_IMAGE			[Pass] 1. Image found [with confidence 96.0%], 2. Position identified in image [798.0]:[469.0], 3. Robot click performed .
Select Manage Device Connections on Connections Screen [SUCCESS]	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	CLICK_BY_IMAGE			[Pass] 1. Image found [with confidence 95.0%], 2. Position identified in image [673.0]:[386.0], 3. Robot click performed .









Result : ■ Pass ■ Statement is not considered for result evaluation(loop and conditional statements)
■ Fail ■ Statement is executed asynchronously
■ Verify Manually

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
Validate Phone1 Bluetooth Icon Highlighted on Registered Device List Screen [SUCCESS]	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen



Result : ■ Pass ■ Statement is not considered for result evaluation(loop and conditional statements)
■ Fail ■ Statement is executed asynchronously
■ Verify Manually





Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen

Result : ■ Pass ■ Statement is not considered for result evaluation(loop and conditional statements)
■ Fail ■ Statement is executed asynchronously
■ Verify Manually





Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
WHILENOT				[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
				[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
IF				[ROI1] [0.0%] [Fail] Section not found on Screen
				[ROI1] [98%] [Pass] Section Found on Screen
	RETURN_FUNCTION_BLOCK_PASS	Breaks currently executing function block and marks function block as pass. Remaining function block commands does not execute	Return function block pass completed successfully	[Pass]
Switch Control to Phone1 [SUCCESS]	SET_DEVICE	Set AppiumAndroid device with device Id [AndroidPhone1] as DUT to perform operation	AppiumAndroid device with device ID [AndroidPhone1] set successfully	[Pass]
	WAIT	Wait for [200] milliseconds	Wait for [200] milliseconds completed successfully	[Pass]
	SET_HOME	Go to Android home screen	Android Device set to Home screen	[Pass]
	SET_HOME	Go to Android home screen	Android Device set to Home screen	[Pass]
Launch KITE App on Android Phone [SUCCESS]	SET_HOME	Go to Android home screen	Android Device set to Home screen	[Pass]
	WAIT	Wait for [500] milliseconds	Wait for [500] milliseconds completed successfully	[Pass]
	CLICK_BY_TEXT	Click on text [KITE App]	Clicked on element with text [KITE App]	[Pass]
	WAIT	Wait for [200] milliseconds	Wait for [200] milliseconds completed successfully	[Pass]
IF		VERIFY_TEXT_BY_ID shall PASS		[Fail]
			CHANGE PROFILE CHANGE DEVICE NAME III ○ < IF [Failed], VERIFY_TEXT_BY_ID Result-[Element at id (android.id/alertTitle) not found, Refer Screenshot: D:/KITE/KITE/ReportData/Failed Test steps screenshots/screenshot_26_02_14_09_18_24_523.png]	

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	ELSE_IF	VERIFY_TEXT_BY_ID shall PASS	09:18 BTWIFI MEDIA PHONE FILE Bluetooth Settings DISABLESCAN BT Name : BT DeviceBT Status : ON Device Status: Not Connected CHANGE PROFILE CHANGE DEVICE NAME III□< ELSE_IF [Failed], VERIFY_TEXT_BY_ID Result-[Element at id (android:id/alertTitle) not found, Refer Screenshot: D:/KITE/KITE/ReportData/Failed Test steps screenshots/screenshot_26_02_14_09_18_29_968.png]	[Fail]
	ENDIF	NA	09:18 BTWIFI MEDIA PHONE FILE Bluetooth Settings DISABLESCAN BT Name : BT DeviceBT Status : ON Device Status: Not Connected CHANGE PROFILE CHANGE DEVICE NAME III□< NA	[Fail]

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
Select BT Tab in KITE App [SUCCESS]	IF	VERIFY_WIDGET shall PASS	 IF [Failed], VERIFY_WIDGET Result-[Element with id [android:id/message] not found , Refer Screenshot: D:/KITE/KITE/ReportData/Failed Test steps screenshots/screenshot_26_02_14_09_18_35_408.png]	[Fail]
	ENDIF	NA	 NA	[Fail]
	CLICK_BY_TEXT	Click on text [BT]	Clicked on element with text [BT]	[Pass]

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
Disable Bluetooth of Phone [SUCCESS]	WHILE	VERIFY_TEXT_BY_TEXT shall PASS	 WHILE [Failed], VERIFY_TEXT_BY_TEXT Result- [Element with text [Deny] not visible, Refer Screenshot: D:/KITE/KITE/ReportData/Failed Test steps screenshots/screenshot_26_02_14_09_18_41_090.png]	[Fail]
	END_WHILE	NA	 NA	[Fail]
	IF	VERIFY_TEXT_BY_ID shall PASS	IF [Pass], VERIFY_TEXT_BY_ID Result-[SUCCESS : Actual text matches expected text]	[Pass]
	CLICK_BY_ID	Click on element at id as [com.kpit.testensemble.kiteapp:id/btn_enable]	Clicked on element at id [com.kpit.testensemble.kiteapp:id/btn_enable]	[Pass]
	WAIT	Wait for [200] milliseconds	Wait for [200] milliseconds completed successfully	[Pass]
Set Device to ROBOT MG400 and External Camera Basler [SUCCESS]	SET_DEVICE	Set ROBOT device [MGROBOT] to perform operation	Robot device with deviceId [MGROBOT] is set successfully to perform operation	[Pass]
	SET_DEVICE	Set camera device [camera1] as DUT to perform operations	Camera device is set to perform operation	[Pass]
Validate Phone1 Bluetooth Icon is Not Highlighted on Registered Device List Screen [SUCCESS]	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	IF			[ROI1] [ColorCheck[true] 97%] [Pass] Section Found on Screen
	RETURN_FUNCTION_BLOCK_PASS	Breaks currently executing function block and marks function block as pass. Remaining function block commands does not execute	Return function block pass completed successfully	[Pass]
Switch Control to Phone1 [SUCCESS]	SET_DEVICE	Set AppiumAndroid device with device Id [AndroidPhone1] as DUT to perform operation	AppiumAndroid device with device ID [AndroidPhone1] set successfully	[Pass]
	WAIT	Wait for [200] milliseconds	Wait for [200] milliseconds completed successfully	[Pass]
	SET_HOME	Go to Android home screen	Android Device set to Home screen	[Pass]
	SET_HOME	Go to Android home screen	Android Device set to Home screen	[Pass]
Launch Link Manager Application on Phone [SUCCESS]	ADB_KEY_EVENT	Send Key events [KEYCODE_APP_SWITCH] on android device	KEYCODE_APP_SWITCH Key events send on android device	[Pass]




Result : ■ Pass ■ Statement is not considered for result evaluation(loop and conditional statements)
■ Fail ■ Statement is executed asynchronously
■ Verify Manually

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	ADB_KEY_EVENT	Send Key events [20] on android device	20 Key events send on android device	[Pass]
	WAIT	Wait for [10000] milliseconds	Wait for [10000] milliseconds completed successfully	[Pass]
	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]
	IF	VERIFY_TEXT_BY_TEXT shall PASS	IF [Pass], VERIFY_TEXT_BY_TEXT Result-[SUCCESS : Element with text [Close all] found]	[Pass]
	CLICK_BY_TEXT	Click on text [Close all]	Clicked on element with text [Close all]	[Pass]
	ENDIF	NA	NA	[Pass]
	SET_HOME	Go to Android home screen	Android Device set to Home screen	[Pass]
	WAIT	Wait for [500] milliseconds	Wait for [500] milliseconds completed successfully	[Pass]
	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]
	CLICK_BY_TEXT	Click on text [MicroServer]	Clicked on element with text [MicroServer]	[Pass]
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]
	CLICK_BY_TEXT	Click on text [STOP]	Clicked on element with text [STOP]	[Pass]
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]
	CLICK_BY_TEXT	Click on text [START]	Clicked on element with text [START]	[Pass]
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
Validate Link Manager Status is Disconnected on Phone [SUCCESS]	CAPTURE_SCREEN	Capture screenshot from DUT	Screenshot captured successfully with image name as [GrabbedImage.png]	[Pass]
	IF			[ROI1] [100%] [Pass] Section Found on Screen
	RETURN_FUNCTION_BLOCK_PASS	Breaks currently executing function block and marks function block as pass. Remaining function block commands does not execute	Return function block pass completed successfully	[Pass]
Set Device to ROBOT MG400 and External Camera Basler [SUCCESS]	SET_DEVICE	Set ROBOT device [MGROBOT] to perform operation	Robot device with deviceid [MGROBOT] is set successfully to perform operation	[Pass]
	SET_DEVICE	Set camera device [camera1] as DUT to perform operations	Camera device is set to perform operation	[Pass]
Validate Phone1 Bluetooth Icon is Not Highlighted on Registered Device List Screen [SUCCESS]	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	IF			[ROI1] [ColorCheck[true] 97%] [Pass] Section Found on Screen
	RETURN_FUNCTION_BLOCK_PASS	Breaks currently executing function block and marks function block as pass. Remaining function block commands does not execute	Return function block pass completed successfully	[Pass]
Switch Control to Phone1 [SUCCESS]	SET_DEVICE	Set AppiumAndroid device with device Id [AndroidPhone1] as DUT to perform operation	AppiumAndroid device with device ID [AndroidPhone1] set successfully	[Pass]
	WAIT	Wait for [200] milliseconds	Wait for [200] milliseconds completed successfully	[Pass]
	SET_HOME	Go to Android home screen	Android Device set to Home screen	[Pass]
	SET_HOME	Go to Android home screen	Android Device set to Home screen	[Pass]
Launch KITE App on Android Phone [SUCCESS]	SET_HOME	Go to Android home screen	Android Device set to Home screen	[Pass]
	WAIT	Wait for [500] milliseconds	Wait for [500] milliseconds completed successfully	[Pass]
	CLICK_BY_TEXT	Click on text [KITE App]	Clicked on element with text [KITE App]	[Pass]
	WAIT	Wait for [200] milliseconds	Wait for [200] milliseconds completed successfully	[Pass]



Result : ■ Pass ■ Statement is not considered for result evaluation(loop and conditional statements)
■ Fail ■ Statement is executed asynchronously
■ Verify Manually



Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	IF	VERIFY_TEXT_BY_ID shall PASS	09:19 100% BTWIFIMEDIAPHONEFILE Bluetooth Settings ENABLESCAN BT Name : BT Status : OFF Device Status: Not Connected CHANGE PROFILE CHANGE DEVICE NAME □< IF [Failed], VERIFY_TEXT_BY_ID Result-[Element at id (android:id/alertTitle) not found, Refer Screenshot: D:/KITE/KITE/ReportData/Failed Test steps screenshots/screenshot_26_02_14_09_19_28_226.png]	[Fail]
	ELSE_IF	VERIFY_TEXT_BY_ID shall PASS	09:19 100% BTWIFIMEDIAPHONEFILE Bluetooth Settings ENABLESCAN BT Name : BT Status : OFF Device Status: Not Connected CHANGE PROFILE CHANGE DEVICE NAME □< ELSE_IF [Failed], VERIFY_TEXT_BY_ID Result-[Element at id (android:id/alertTitle) not found, Refer Screenshot: D:/KITE/KITE/ReportData/Failed Test steps screenshots/screenshot_26_02_14_09_19_34_184.png]	[Fail]

Result : ■ Pass ■ Statement is not considered for result evaluation(loop and conditional statements)
■ Fail ■ Statement is executed asynchronously
■ Verify Manually




Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	ENDIF	NA	 NA	[Fail]
Select BT Tab in KITE App [SUCCESS]	IF	VERIFY_WIDGET shall PASS	 IF [Failed], VERIFY_WIDGET Result[Element with id [android:id/message] not found , Refer Screenshot: D:/KITE/KITE/ReportData/Failed Test steps screenshots/screenshot_26_02_14_09_19_39_680.png]	[Fail]
	ENDIF	NA	 NA	[Fail]
	CLICK_BY_TEXT	Click on text [BT]	Clicked on element with text [BT]	[Pass]

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
Disable Bluetooth of Phone [SUCCESS]	WHILE	VERIFY_TEXT_BY_TEXT shall PASS	09:19 100% BTWIFIMEDIAPHONEFILE Bluetooth Settings ENABLESCAN BT Name :BT Status : OFF Device Status: Not Connected CHANGE PROFILE CHANGE DEVICE NAME III□< WHILE [Failed], VERIFY_TEXT_BY_TEXT Result- [Element with text [Deny] not visible, Refer Screenshot: D:/KITE/KITE/ReportData/Failed Test steps screenshots/screenshot_26_02_14_09_19_45_364.png]	[Fail]
	END_WHILE	NA	09:19 100% BTWIFIMEDIAPHONEFILE Bluetooth Settings ENABLESCAN BT Name :BT Status : OFF Device Status: Not Connected CHANGE PROFILE CHANGE DEVICE NAME III□< NA	[Fail]















Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	IF	VERIFY_TEXT_BY_ID shall PASS	 Bluetooth Settings BT Name : BT Status : OFF Device Status: Not Connected CHANGE PROFILE CHANGE DEVICE NAME III □ < IF [Failed], VERIFY_TEXT_BY_ID Result-{Actual text [DISABLE] does not match expected text, Refer Screenshot: D:\KITE\KITE\ReportData\Failed Test steps screenshots/screenshot_26_02_14_09_19_45_779.png}	[Fail]
	ENDIF	NA	 Bluetooth Settings BT Name : BT Status : OFF Device Status: Not Connected CHANGE PROFILE CHANGE DEVICE NAME III □ < NA	[Fail]
Enable Bluetooth of Phone [SUCCESS]	IF	VERIFY_TEXT_BY_ID shall PASS	IF [Pass], VERIFY_TEXT_BY_ID Result-[SUCCESS : Actual text matches expected text]	[Pass]
	CLICK_BY_ID	Click on element at id as [com.kpit.testensemble.kiteapp:id/btn_enable]	Clicked on element at id [com.kpit.testensemble.kiteapp:id/btn_enable]	[Pass]
	WAIT	Wait for [200] milliseconds	Wait for [200] milliseconds completed successfully	[Pass]
	WHILENOT	VERIFY_TEXT_BY_TEXT shall FAIL	WHILENOT-[Failed], VERIFY_TEXT_BY_TEXT Result-[SUCCESS : Element with text [Allow] found]	[Fail]
	END_WHILE	NA	NA	[Fail]
	WHILE	VERIFY_TEXT_BY_TEXT shall PASS	WHILE [Pass], VERIFY_TEXT_BY_TEXT Result-[SUCCESS : Element with text [Allow] found]	[Pass]
	CLICK_BY_ID	Click on element at id as [android:id/button1]	Clicked on element at id [android:id/button1]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILE	VERIFY_TEXT_BY_TEXT shall PASS	WHILE [Pass], VERIFY_TEXT_BY_TEXT Result-[SUCCESS : Element with text [Allow] found]	[Pass]
	CLICK_BY_ID	Click on element at id as [android:id/button1]	Clicked on element at id [android:id/button1]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILE	VERIFY_TEXT_BY_TEXT shall PASS	WHILE [Pass], VERIFY_TEXT_BY_TEXT Result-[SUCCESS : Element with text [Allow] found]	[Pass]
	CLICK_BY_ID	Click on element at id as [android:id/button1]	Clicked on element at id [android:id/button1]	[Pass]
	END_WHILE	NA	NA	[Pass]
	ENDIF	NA	NA	[Pass]

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	IF	VERIFY_WIDGET shall PASS	 IF [Failed], VERIFY_WIDGET Result-[Element with id [com.google.android.projection.gearhead.id/dialog_title] not found , Refer Screenshot: D:/KITE/KITE/ReportData/Failed Test steps screenshots/screenshot_26_02_14_09_19_56_933.png]	[Fail]
	ENDIF	NA	 NA	[Fail]













Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
Select Scan for Bluetooth Devices [SUCCESS]	IF	VERIFY_WIDGET shall PASS	09:20 100% BTWIFIMEDIAPHONEFILE Bluetooth Settings DISABLESCAN BT Name : BT DeviceBT Status : On Device Status: Connected CHANGE PROFILE CHANGE DEVICE NAME III□< IF [Failed], VERIFY_WIDGET Result-[Element with id [android:id/message] not found , Refer Screenshot: D:/KITE/KITE/ReportData/Failed Test steps screenshots/screenshot_26_02_14_09_20_02_423.png]	[Fail]
	ENDIF	NA	09:20 100% BTWIFIMEDIAPHONEFILE Bluetooth Settings DISABLESCAN BT Name : BT DeviceBT Status : On Device Status: Connected CHANGE PROFILE CHANGE DEVICE NAME III□< NA	[Fail]

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	IF	VERIFY_TEXT_BY_TEXT shall PASS	 IF [Failed], VERIFY_TEXT_BY_TEXT Result-[Element with text [Auto on your car screen] not visible, Refer Screenshot: D:\KITE\KITE\ReportData\Failed Test steps screenshots/screenshot_26_02_14_09_20_08_089.png]	[Fail]
	ENDIF	NA	 NA	[Fail]
	CLICK_BY_ID	Click on element at id as [com.kpit.testensemble.kiteapp:id/btn_scan]	Clicked on element at id [com.kpit.testensemble.kiteapp:id/btn_scan]	[Pass]
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	IFNOT	VERIFY_TEXT_BY_TEXT shall FAIL	IFNOT-[Failed], VERIFY_TEXT_BY_TEXT Result-[SUCCESS : Element with text [DELETE] found]	[Fail]
	ENDIF	NA	NA	[Fail]
Set Device to ROBOT MG400 and External Camera Basler [SUCCESS]	SET_DEVICE	Set ROBOT device [MGROBOT] to perform operation	Robot device with deviceid [MGROBOT] is set successfully to perform operation	[Pass]
	SET_DEVICE	Set camera device [camera1] as DUT to perform operations	Camera device is set to perform operation	[Pass]
Select Bluetooth Icon of First Disconnected Registered Device on Manage Device Connection Screen [SUCCESS]	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	CLICK_BY_IMAGE			[Pass] 1. Image found [with confidence 98.0%]. 2. Position identified in image [908.0;1559.0]. 3. Robot click performed .
Validate Phone1 Bluetooth Icon Highlighted on Registered Device List Screen [SUCCESS]	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]







Result : ■ Pass ■ Statement is not considered for result evaluation(loop and conditional statements)
■ Fail ■ Statement is executed asynchronously
■ Verify Manually

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
WHILENOT				[ROI1] [0.0%] [Fail] Section not found on Screen
WAIT		Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
RESETARM		Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
IMAGE_GRAB		Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
END_WHILE		NA	NA	[Pass]
WHILENOT				[ROI1] [0.0%] [Fail] Section not found on Screen
WAIT		Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
RESETARM		Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
IMAGE_GRAB		Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
END_WHILE		NA	NA	[Pass]
WHILENOT				[ROI1] [0.0%] [Fail] Section not found on Screen
WAIT		Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
RESETARM		Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
IMAGE_GRAB		Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
END_WHILE		NA	NA	[Pass]
WHILENOT				[ROI1] [0.0%] [Fail] Section not found on Screen
WAIT		Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
RESETARM		Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
IMAGE_GRAB		Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
END_WHILE		NA	NA	[Pass]
WHILENOT				[ROI1] [0.0%] [Fail] Section not found on Screen
WAIT		Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
RESETARM		Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
IMAGE_GRAB		Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
END_WHILE		NA	NA	[Pass]
WHILENOT				[ROI1] [0.0%] [Fail] Section not found on Screen
WAIT		Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
RESETARM		Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
IMAGE_GRAB		Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
END_WHILE		NA	NA	[Pass]
WHILENOT				[ROI1] [0.0%] [Fail] Section not found on Screen
WAIT		Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
RESETARM		Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]

Result : ■ Pass ■ Statement is not considered for result evaluation(loop and conditional statements)
■ Fail ■ Statement is executed asynchronously
■ Verify Manually

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [12.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen

Result : ■ Pass ■ Statement is not considered for result evaluation(loop and conditional statements)
■ Fail ■ Statement is executed asynchronously
■ Verify Manually

Test Script Id	Test Script Objective			Result
KPIT_TC_DRT_LMG_011	KPIT_TC_DRT_LMG_011 : To verify Link manager connection is disconnected when Bluetooth is disabled on Phone1 while Phone1 is connected as Bluetooth device and link manager connection is established			Pass
Function Block [Result]	Command	Expected Result	Actual Result	Status
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WHILENOT			[ROI1] [0.0%] [Fail] Section not found on Screen
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	END_WHILE	NA	NA	[Pass]
	WAIT	Wait for [1000] milliseconds	Wait for [1000] milliseconds completed successfully	[Pass]
	RESETARM	Reset Arm successfully executed.	Reset Arm successfully executed.	[Pass]
	IMAGE_GRAB	Grab the image from connected DUT with image name as [GrabbedImage.png]	Successfully grabbed image from connected DUT with image name as [GrabbedImage.png]	[Pass]
	IF			[ROI1] [0.0%] [Fail] Section not found on Screen
	ELSE_IF			[ROI1] [97%] [Pass] Section Found on Screen
	RETURN_FUNCTION_BLOCK_PASS	Breaks currently executing function block and marks function block as pass. Remaining function block commands does not execute	Return function block pass completed successfully	[Pass]