



3D modeling



匯入檔案

Drag the file
into mesher



輕量化模型
(reduce the surface)

select all :

{ command + A }
 control + A


edit

↓

reduce

↓

percentage



滑順表面(smoothen)


sculpt



brushes



bubble smooth
and
shrink smooth



移動位置


edit

↓

transform

↓

move



切割

edit





plane cut



move the plane



no fill



縮放

select all

↓

edit

↓

offset

↓

distance

Offset 

Distance 2.5 mm

Accuracy 50

Regularity 25


Soft Transition 0 mm

☐ Connected

☒ Preserve Boundary

☒ Preserve Groups

Accept Cancel



刪除多餘圖層


edit



separate shells



delete useless shells



使用畫筆刪除部分區域

select



size



draw





edit



plane cut



no fill



建立pattern

edit




make patterns



pattern type (edges)




set gradient
(line gradient)





空腔檢測

Analysis
↓
inspector



加厚

select all
↓
edit
↓
extrusion







重要！如何補破圖：

用select的畫筆把破掉部分標記起來

edit→plane cut

edit→make solid

(記得配合空腔檢測)



儲存檔案的格式：**stl**

save file as .stl

