




Battery and Power Converters




Motors, Motor Driver and Encoders





Robot Arm (Servo Motors and Color Sensor)



IR Sensor Panel

Sensor Panel Input Ground IR Sensor 0 Output IR Sensor 1 Output IR Sensor 2 Output IR Sensor 3 Output IR Sensor 4 Output IR Sensor 7 Output Output **IR Sensor Panel TCRT 5000**

Sharp IR sensors (Front, Right and Left)

