

Air Services, Inc.

FAA CRS # Z4AR547Y
400 Regional Airport Rd
Carrollton, GA 30117

Estimate

Date	Estimate #
3/5/2026	1527

Name / Address
9H Aviation Charles Hergott

Description	Qty	Cost	Sales Tax	Total ICA USD
TWIN OTTER SN 938 - INSPECTION				
LABOR - Jet/Turbo Repairs/Maintenance - Reassemble aircraft from recovery	300.00	150.00		45,000.00
Parts - Various bolts, screws, nuts, washers to reassemble	1.00	1,000.00		1,000.00
LABOR - Jet/Turbo Repairs/Maintenance - EMMA 1 - 48	100.00	150.00		15,000.00
Parts - Various necessary items to comply with EMMA Inspection	1.00	2,000.00		2,000.00
LABOR - Jet/Turbo Repairs/Maintenance - Calendar Card included in EMMA Inspections	0.00	150.00		0.00
LABOR - Jet/Turbo Repairs/Maintenance - Corrosion check YR 1 - 5	300.00	150.00		45,000.00
Parts - Various necessary items to comply with Corrosion check	1.00	2,000.00		2,000.00
LABOR - Jet/Turbo Repairs/Maintenance - SB 6/486	144.00	150.00		21,600.00
Wing inspection holes (must be done to complete corrosion inspection)				
Parts - Various items to complete Service bulletin 6/486	1.00	5,000.00		5,000.00
LABOR - Jet/Turbo Repairs/Maintenance - SB V6/0067 Torque tube	1.00	150.00		150.00
LABOR - Jet/Turbo Repairs/Maintenance - SP2D10 Wing bolts	2.00	150.00		300.00
LABOR - Jet/Turbo Repairs/Maintenance - SP2D9 Strut bolts	2.00	150.00		300.00
LABOR - Jet/Turbo Repairs/Maintenance - SB6/521 239 Frame inspection	2.00	150.00		300.00
LABOR - Jet/Turbo Repairs/Maintenance - SP2L1 Compass swing	4.00	150.00		600.00
LABOR - Jet/Turbo Repairs/Maintenance - IFR	1.00	975.00		975.00
LABOR Outside vendor repairs & overhauls - SP2N1 and ESIS battery cap check	1.00	750.00		750.00

Total ICA USD

Phone #	Fax #	E-mail	Web Site
770-836-9002		sherrie.stringer@airservicesinc.aero	www.airservicesinc.aero

Air Services, Inc.

FAA CRS # Z4AR547Y
400 Regional Airport Rd
Carrollton, GA 30117

Estimate

Date	Estimate #
3/5/2026	1527

Name / Address
9H Aviation Charles Hergott

Description	Qty	Cost	Sales Tax	Total ICA USD
LABOR - Jet/Turbo Repairs/Maintenance - R & R Battery for SP2N1 and testing	2.00	150.00		300.00
LABOR - Jet/Turbo Repairs/Maintenance - SP2N3 and N6 ULB testing	2.00	150.00		300.00
LABOR - Jet/Turbo Repairs/Maintenance - SP2N8 and N6 FDR correlation test and CVR test	16.00	150.00		2,400.00
LABOR Outside vendor repairs & overhauls - SP2N8 and N6 FDR - interpretation of CVR and FDR data	1.00	5,000.00		5,000.00
LABOR - Jet/Turbo Repairs/Maintenance - Main battery replacement	1.00	150.00		150.00
Parts - Battery RG-380E	1.00	5,474.79		5,474.79
LABOR - Jet/Turbo Repairs/Maintenance - Replace tires	10.00	150.00		1,500.00
Parts - Tires - Main 112T06-3 Goodyear 11.00X12 10ply	2.00	1,495.49		2,990.98
Parts - Tires - Nose 892C616B1 Goodyear 8.9X12.5 6 ply	1.00	1,869.45		1,869.45
LABOR - Jet/Turbo Repairs/Maintenance - SP2J6 R & R Engine fire extinguishers	4.00	150.00		600.00
LABOR Outside vendor repairs & overhauls - Engine fire extinguishers and squibs OH	1.00	1,517.15		1,517.15
LABOR - Jet/Turbo Repairs/Maintenance - SP2J3 Engine fire X continuity check	2.00	150.00		300.00
LABOR - Jet/Turbo Repairs/Maintenance - SP2J7 R & R Hand held fire extinguishers	1.00	150.00		150.00
Parts - Hand held fire extinguisher	2.00	800.00		1,600.00
LABOR - Jet/Turbo Repairs/Maintenance - SP2G4 R & R overspeed governors	2.00	150.00		300.00
LABOR Outside vendor repairs & overhauls - OH Overspeed governors (oil contamination due to non-preservation)	2.00	3,000.00		6,000.00
LABOR - Jet/Turbo Repairs/Maintenance - SP2G6 R & R propellers	6.00	150.00		900.00

Total ICA USD

Phone #	Fax #	E-mail	Web Site
770-836-9002		sherrie.stringer@airservicesinc.aero	www.airservicesinc.aero

Air Services, Inc.

FAA CRS # Z4AR547Y
400 Regional Airport Rd
Carrollton, GA 30117

Estimate

Date	Estimate #
3/5/2026	1527

Name / Address
9H Aviation Charles Hergott

Description	Qty	Cost	Sales Tax	Total ICA USD
LABOR Outside vendor repairs & overhauls - OH both propellers (AVERAGE)	2.00	17,300.00		34,600.00
Parts - SP2G1 Engine mount bolts - replace with new	1.00	1,005.00		1,005.00
LABOR - Jet/Turbo Repairs/Maintenance - SP2F4 - SB6/454 PART A	8.00	150.00		1,200.00
LABOR - Jet/Turbo Repairs/Maintenance - SP2D12 Wing strut inspection	4.00	150.00		600.00
LABOR - Jet/Turbo Repairs/Maintenance - SP2C8 Flight control cables	40.00	150.00		6,000.00
Parts - SP2C8 Flight control cables (Kit) SP2C8 - NEW	1.00	5,350.00		5,350.00
Parts - SP2C9 STN 270.3 Pulleys	4.00	267.00		1,068.00
LABOR - Jet/Turbo Repairs/Maintenance - Engine strip, build-up, install and rig X 2 (50 each)	100.00	150.00		15,000.00
Parts - Miscellaneous parts for engine change	1.00	350.00		350.00
Parts - Turbine oil	24.00	26.75		642.00
LABOR - Jet/Turbo Repairs/Maintenance - Oil cooler flush	4.00	150.00		600.00
Parts - First aid kit	1.00	400.00		400.00
LABOR Outside vendor repairs & overhauls - ELT re-programming, battery replacement and recertification	1.00	1,800.00		1,800.00
LABOR - Jet/Turbo Repairs/Maintenance - Main landing gear replacement	35.00	150.00		5,250.00
LABOR Outside vendor repairs & overhauls - Main landing gear (AVERAGE)	2.00	9,000.00		18,000.00
LABOR - Jet/Turbo Repairs/Maintenance - Replace de-ice boots (AIRFRAME)	120.00	150.00		18,000.00
Parts - De-ice boots - IF NEEDED	4.00	0.00		0.00
AS OF 03/09/2026 WAITING ON QUOTE FROM OEM - UNKNOWN WILL INSPECT AT RECOVERY AND REVISE THIS ESTIMATE IF NECESSARY!!				

Total ICA USD

Phone #	Fax #	E-mail	Web Site
770-836-9002		sherrie.stringer@airservicesinc.aero	www.airservicesinc.aero

Air Services, Inc.

FAA CRS # Z4AR547Y
400 Regional Airport Rd
Carrollton, GA 30117

Estimate

Date	Estimate #
3/5/2026	1527

Name / Address
9H Aviation Charles Hergott

Description	Qty	Cost	Sales Tax	Total ICA USD
LABOR - Jet/Turbo Repairs/Maintenance - Service Bulletins and Airworthiness Directives compliance	30.00	150.00		4,500.00
LABOR - Jet/Turbo Repairs/Maintenance - Weight and Balance	6.00	150.00		900.00
* Aircraft painting - Aircraft painted one color (WHITE) and black nacelles	1.00	86,500.00		86,500.00
LABOR Outside vendor repairs & overhauls - Light overhaul PT6A-34 Engines	2.00	184,250.00		368,500.00
TIMEFRAME: May 01 - September 15, 2026 THIS IS DOES NOT INCLUDE ANY MAJOR AVIONICS CHANGES THE ENGINES ARE 3 - 4 MONTHS TURN FROM THE OH SHOP THE SOONER WE START WE MIGHT BE ABLE TO DELIVERY EARLIER				
* The paint shop is located here at the same airport we sublet paint to them <u>BUT</u> sign off the logbook entry as the repair station after inspected.				

Total ICA USD

Phone #	Fax #	E-mail	Web Site
770-836-9002		sherrie.stringer@airservicesinc.aero	www.airservicesinc.aero

Air Services, Inc.

FAA CRS # Z4AR547Y
400 Regional Airport Rd
Carrollton, GA 30117

Estimate

Date	Estimate #
3/5/2026	1527

Name / Address
9H Aviation Charles Hergott

Description	Qty	Cost	Sales Tax	Total ICA USD
NOTES: Avionics. Phase II (2) AND ADSB Out Not being quoted at this time, due to the possibility of Avionics Suite replacement. Should this offer be accepted and the work-scope performed outlined below are the deposit requirements: FROM ESTIMATE # 1526 RECOVERY \$102,748.75 Deposit # 1 Due 15 days at or near the departure for recovery \$36,000.00 Deposit # 2 Due within 45 days from departure for recovery \$36,000.00 Final balance due within 60 days from departure for recovery \$30,748.75 FROM ESTIMATE # 1527 WORK-SCOPE \$741,592.37 Deposit # 1 Due 15 days from completion of recovery \$185,000.00 Deposit # 2 Due 30 days from commence of work \$185,000.00 Deposit # 3 Due 60 days from commence of work \$185,000.00 Final balance due at time of completion prior to aircraft departing our facility.				

onsite Avionics Contractor

Total ICA USD \$741,592.37

Phone #	Fax #	E-mail	Web Site
770-836-9002		sherrie.stringer@airservicesinc.aero	www.airservicesinc.aero