

Inspection Types - TSSA Ontario Elevator Program

Rocket Elevators - Ontario Fleet Technical Reference

Overview

The Technical Standards and Safety Authority (TSSA) administers five categories of inspection for elevating devices in Ontario. Each type has distinct triggering conditions, documentation requirements, and pass/fail criteria.

Periodic Inspection

Trigger: Annual cycle for all licensed devices.

Scope: Full visual and operational inspection of all safety systems, doors, buffers, safeties, interlocks, and control systems.

Outcome codes: Passed, Follow up (minor deficiency), Follow up Major, Shutdown (immediate hazard).

Timeline: Device must be re-inspected within 60 days of a Follow up order and immediately upon correction of a Shutdown order.

Follow-Up Inspection

Trigger: Issued after a Periodic or Initial inspection results in a deficiency order.

Scope: Limited to the specific deficiency items noted in the order.

Documentation: Inspector must reference the original order number. Owner must certify in writing that all cited deficiencies have been corrected before the follow-up visit is booked.

Initial / Pre-Open Inspection

Trigger: New installation or reinstatement after more than 12 months out of service.

Scope: Complete inspection against current code - no grandfather provisions apply to newly installed equipment. Includes all tests specified in ASME A17.1 Section 8.10.

Outcome: Device receives its first operating licence upon passing.

Special Inspection

Trigger: Incident, complaint, or TSSA directive.

Scope: Directed by the issuing TSSA officer - may be limited to specific components or may constitute a full periodic inspection.

Authority: TSSA may issue a Shutdown order on-site if an imminent hazard is found. Owner has the right to appeal within 30 days.

Alteration Inspection

Trigger: Any work classified as an alteration under CAN/CSA B44 Appendix E.

Examples: Control system replacement, cab enlargement, drive conversion, rope replacement on gearless traction.

Process: Alteration must be registered with TSSA Design before work begins. Post-alteration inspection required before the device is returned to service. Status in the TSSA database will show 'Pending Follow Up' until inspection passes.

Documentation Requirements

The current operating licence must be posted in the elevator machine room or on the landing door (for winding drum or hydraulic units with no machine room). Maintenance logs must record: date, technician licence number, work performed,

and parts replaced. Logs must be available at the premises for three years.