STIMULAN®

POWER TO TRANSFORM™

CASE STUDY

Courtesy of Mr. Hemant K Sharma

Consultant Orthopaedic Surgeon, Hull, UK

Clinical particulars

35-year-old male involved in a road traffic accident suffered multiple injuries and subtrochanteric fracture of left femur. This was nailed, but subsequently, he developed infection and drainage from both proximal and distal locking screw areas. He went to theatre multiple times and developed wound approx. I5cm on the proximal lateral thigh, which was treated with VAC.

He presented a year later with discharging wound proximally and distally.

Treatment

The femoral nail was removed followed by reaming of the femoral canal and wash-out procedure. 40cc of STIMULAN beads were placed in the intramedullary canal. Cultures revealed infection to be *Staphylococcus aureus*.

Outcome

2.5 months' post-operatively x-rays showed almost complete absorption of the STIMULAN beads and at 7 months there was complete healing of the non-union.

At I year follow-up, the patient remains infection free, walking with no pain.



Pre-operative x-ray showing non-union



X-ray - 2 months



CT - 2 months



2.5 months



Lyear

For indications, contraindications, warnings and precautions see Instructions for Use. Concurrent use of locally administered antibiotics may affect setting time.

This brochure may include the use of STIMULAN or techniques that go beyond the current clearance/approval granted by the relevant regulatory authority. Please contact your local representative for further information.

©2018, Biocomposites, STIMULAN, Bringing Calcium to Life and Power to Transform are trademarks/registered trademarks of Biocomposites Ltd.

All rights reserved. No unauthorized copying, reproduction, distributing or republication is allowed unless prior written permission is granted by the owner, Biocomposites Ltd.

Patents granted: GB2367552, EP I204599 BI, US 678039I, EP 259423I BI, US 8883063, CN ZL20I2I0466II7.X, GB24967I0, EP 3058899 BI Patents pending: GBI502655.2, US I5/040075, CN 20I6I00897I0.5, US I5/288328, GBI704688.9
MA0I24R3

