

Sector 1

$$\begin{aligned}H_a &= 0 \\H_b &= 0 \\H_c &= 1\end{aligned}$$



Sector 2

$$\begin{aligned}H_a &= 1 \\H_b &= 0 \\H_c &= 1\end{aligned}$$



Sector 3

$$\begin{aligned}H_a &= 1 \\H_b &= 0 \\H_c &= 0\end{aligned}$$



Sector 4

$$\begin{aligned}H_a &= 1 \\H_b &= 1 \\H_c &= 0\end{aligned}$$



Sector 5

$$\begin{aligned}H_a &= 0 \\H_b &= 1 \\H_c &= 0\end{aligned}$$



Sector 6

$$\begin{aligned}H_a &= 0 \\H_b &= 1 \\H_c &= 1\end{aligned}$$

