

FIELD INSPECTION NOTE

Inspection date: 2026-04-15

Property: River Tower

Asset: RTU-C-04

Observation:

Abnormal compressor vibration was observed during startup. The unit remained operational, but vibration exceeded the technician's normal field expectation.

Recommendation:

Schedule vibration analysis within 5 business days.

Technician: M. Patel

Reference: INSPECT-RTU-C-04-2026