```
**************************
'* Name : IR home.BAS
   Author : Antor Ahmed
   Notice : Copyright (c) 2017 Antor Ahmed
         : All Rights Reserved
         : 28-Jun-17
'* Version : 1.0
  Notes
Device = 16F676
Config FOSC_INTRCIO, WDTE_OFF, PWRTE_OFF, MCLRE_ON, BOREN_OFF, CP_ON, CPD_ON
Xtal 20
ANSEL = 0
Declare Sonyin Pin = PORTC.0
Symbol FAN = PORTC.1
Symbol L_1 = PORTC.2
Symbol L 2 = PORTC.3
Symbol L 3 = PORTC.4
Symbol L_4 = PORTC.5
Symbol L_5 = PORTA.0
Symbol L_6 = PORTA.1
Symbol L_7 = PORTA.2
Output FAN: Output L_1
Output L_2 : Output L_3
Output L_4 : Output L_5
Output L_6 : Output L_7
PORTC = 0 : PORTA = 0
Dim speed As Byte
Dim flag As Bit
Dim sony As Word
Dim cmd As sony.LowByte
Clear
main:
 Repeat
   sony = SonyIn
   GoSub fan_speed
 Until cmd <> 255
 If cmd >= 0 And cmd <= 8 Then
   speed = cmd + 2
   flag = 1
 EndIf
 If cmd = 21 Then flag = 0
 If cmd = 16 Then L_1 = \sim L_1 : DelayMS 500
 If cmd = 17 Then L_2 = \sim L_2: DelayMS 500
 If cmd = 18 Then L_3 = \sim L_3: DelayMS 500
 If cmd = 19 Then L_4 = \sim L_4: DelayMS 500
GoTo main
fan_speed:
 If flag = 1 Then
   FAN = 0
   DelayMS 10 - speed
   FAN = 1
 Else
   FAN = 0
 EndIf
Return
```