



Notes:
Apply Loctite to threads of FN 4 prior to inserting into FN1
Loosen coupler and center on potentiometer and FN4




REVISIONS				
ZONE	REV.	DESCRIPTION	DATE	APPROVED
	A	Initial Release	5/17/2014	

ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	OM500002	Bottom of the foot, sits directly on the table	1
2	OM700001	Rotary Base Plate	1
3	6391K172	SAE 841 Bronze Sleeve Bearing for 3/8" Shaft Diameter, 1/2" OD, 3/8" Length	1
4	93558A101	Cap for Female Threaded Round Standoffs 18-8 Stainless Steel, 1/4" Cap Diameter 6-32	1

SolidWorks Student Edition.
For Academic Use Only.

PROPRIETARY AND CONFIDENTIAL
THE INFORMATION CONTAINED IN THIS
DRAWING IS THE SOLE PROPERTY OF
UNIVERSITY OF UTAH. ANY
REPRODUCTION IN PART OR AS A WHOLE
WITHOUT THE WRITTEN PERMISSION OF
UNIVERSITY OF UTAH IS
PROHIBITED.

UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN INCHES TOLERANCES: ANGULAR: $\pm 1^\circ$ X.X ± 0.100 X.XX ± 0.030 X.XXX ± 0.010 BREAK SHAPR EDGES .005 MAX. ALL SMALL FILLOTS .002 MAX. INTERPRET GEOMETRIC TOLERANCING PER: ASME Y14.5		NAME	DATE	UTAHTELEROBOTICS TITLE: Table Base Plate SIZE DWG. NO. REV B OM700002 A SCALE: 1:2 SHEET 1 OF 2	
MATERIAL		DRAWN	RN		05/2014
FINISH		CHECKED			
DO NOT SCALE DRAWING		ENG APPR.			
APPLICATION		COMMENTS:			
DASH	NEXT ASSY	USED ON			



SolidWorks Student Edition.
For Academic Use Only.

PROPRIETARY AND CONFIDENTIAL
THE INFORMATION CONTAINED IN THIS
DRAWING IS THE SOLE PROPERTY OF
UNIVERSITY OF UTAH. ANY
REPRODUCTION IN PART OR AS A WHOLE
WITHOUT THE WRITTEN PERMISSION OF
UNIVERSITY OF UTAH IS
PROHIBITED.