
Complete and assemble the hand and test

4. COLLECT & ASSEMBLE

Collect the printed parts & other working parts
Non-elastic Nylon cord
Flexible Elastic cord
Tensioner Screws
Velcro & attachment screws & nuts
Foam Padding



3. TIDY

Use Tools from the toolbench to help clear/clean and prepare components for assembly. Remove Support material. Sand and smooth sharp edges.


TOOL

Safety Glasses
Tweezers
Pliers
Scalpel
Hand Drill

2011111

1. MEASURING & MODELLING

Measure the Width of full hand across knuckles with calipers Enter into handomatic or use at our Measuring Workshops



2. PRINT

Generate files 5 x Fingertips Download Import in software Print a full set of Rapture-Reloaded Parts Right Palm 5 x Proximals Right Gauntlet Tensioner 2 x Knuckle Pins x Thumb Pin Retention_clip 5 x Finger Pins 2 x Wrist Pins

1220m