

3 methods to co-optimize HW & SW



* HW parameters as actions



* HW parameters in policy & actions.

yi of.

Vi ok

OK