
UST Wanderer

Master Board Documentation



Function	Device	Port and Pin	CubeMX Config
	Front Ultrasound	PA8	TIM1_CH1
Ultrasonic		PA4	GPIO_OutPut
Sensor	Back Ultrasound	PA11	TIM1_CH4
		PA5	GPIO_OutPut

^{*} For all Timers, the mode is set to Input Capture direct mode.

Function	Device	Port and Pin	CubeMX Config
PWM	Left Motor PWM	PC6	TIM3_CH1
	Right Motor PWM	PC7	TIM3_CH2
	Back Motor PWM	PC9	TIM3_CH4

^{*} For all Timers, the mode is set to PWM Generation.

Function	Device	Port and Pin	CubeMX Config
	Bluetooth	PA10	USART1_RX
UART		PA9	USART1_TX
	UART	PB11	USART3_RX
		PB10	USART3_TX

^{*} All UART's are configured with Baud Rate = 115200 Bits/s.

Function	Device	Port and Pin	CubeMX Config
	Left Motor	PB8	GPIO_Output
		PB9	GPIO_Output
Motor	Right Motor	PB12	GPIO_Output
		PB13	GPIO_Output
	Back Motor	PB14	GPIO_Output
		PB15	GPIO_Output

^{*} For all GPIO_Output without specification, the pin is configured with Output Push Pull and without pull-up and pull-down resistors.

^{*} For all Timers, Prescaler = 0x0047 and AutoReload Register = 0xFFFF-1.

^{*} For all Timers, Capture Compare Interrupt is enabled.

^{*} For all Input Capture Channels, it is all configured to Rising Edge.

^{*} For all GPIO_Output without specification, the pin is configured with Output Push Pull and without pull-up and pull-down resistors.

^{*} For all Timers, Prescaler = 0x0000 and AutoReload Register = 0x03E7.

Function	Device	Port and Pin	CubeMX Config
LED	LED Red	PB5	GPIO_Input
	LED Green	PB0	GPIO_Input
	LED Blue	PA1	GPIO_Input

^{*} For all GPIO_Input, the pin is configured with No pull-up and No pull-down resistors.

Function	Device	Port and Pin	CubeMX Config
Button	KEY1	PA0	GPIO_Input

^{*} For all GPIO_Input, the pin is configured with No pull-up and No pull-down resistors.