

REPAIR INVOICE

Invoice number	INV-CLM-UK-001	Invoice date	02/08/2026
Registration	CG01 UKX	Vehicle	HYUNDAI KONA HYBRID
Repairer	UK Demonstration Repair Centre 1	Mileage	12,875

Description	Qty	Unit price	Net subtotal
Front bumper remove and refit	1	£78.50	£78.50
Radiator grille remove and refit	0.3	£78.50	£23.55
Radar sensor calibrate	0.3	£78.50	£23.55
Front bumper repair paint plastic	1	£94.20	£94.20
Standard vehicle recovery	1	£150.00	£150.00

Parts net £150.00

Labour net £219.80

Subtotal net £369.80

VAT (20%) £73.96

Invoice Total £443.76