

REPAIR INVOICE

Invoice number	INV-CLM-UK-002	Invoice date	03/08/2026
Registration	CG02 UKX	Vehicle	HYUNDAI KONA HYBRID
Repairer	UK Demonstration Repair Centre 2	Mileage	13,750

Description	Qty	Unit price	Net subtotal
Front bumper remove and refit	1	£81.64	£81.64
Radiator grille remove and refit	0.3	£82.43	£24.73
Radar sensor calibrate	0.3	£78.50	£23.55
Front bumper repair paint plastic	1	£97.03	£97.03
Standard vehicle recovery	1	£150.00	£150.00

Parts net £150.00

Labour net £226.95

Subtotal net £376.95

VAT (20%) £75.39

Invoice Total £452.34