

# REPAIR INVOICE

|                |                                  |              |                     |
|----------------|----------------------------------|--------------|---------------------|
| Invoice number | INV-CLM-UK-003                   | Invoice date | 04/08/2026          |
| Registration   | CG03 UKX                         | Vehicle      | HYUNDAI KONA HYBRID |
| Repairer       | UK Demonstration Repair Centre 3 | Mileage      | 14,625              |

| Description                       | Qty | Unit price | Net subtotal |
|-----------------------------------|-----|------------|--------------|
| Front bumper remove and refit     | 1   | £95.77     | £95.77       |
| Radiator grille remove and refit  | 0.3 | £94.20     | £28.26       |
| Radar sensor calibrate            | 0.3 | £92.63     | £27.79       |
| Front bumper repair paint plastic | 1   | £94.20     | £94.20       |
| Standard vehicle recovery         | 1   | £150.00    | £150.00      |

Parts net £150.00

Labour net £246.02

Subtotal net £396.02

VAT (20%) £79.20

**Invoice Total £475.22**