

REPAIR INVOICE

Invoice number	INV-CLM-UK-005	Invoice date	06/08/2026
Registration	CG05 UKX	Vehicle	HYUNDAI KONA HYBRID
Repairer	UK Demonstration Repair Centre 5	Mileage	16,375

Description	Qty	Unit price	Net subtotal
Front bumper remove and refit	1	£102.05	£102.05
Radiator grille remove and refit	0.3	£98.13	£29.44
Radar sensor calibrate	0.3	£94.20	£28.26
Front bumper repair paint plastic	1	£130.00	£130.00
Standard vehicle recovery	1	£192.00	£192.00

Parts net £192.00

Labour net £289.75

Subtotal net £481.75

VAT (20%) £96.35

Invoice Total £578.10